



TOYOTA




report date: 2024-03-28

General information

Make	TOYOTA
Model	CELICA VVTi
Colour	Silver
Year of manufacture	2003
Top speed	127 mph
0 - 60 mph	8.7 seconds
Gearbox	6 speed Manual

Engine & fuel consumption

Power	140 BHP
Max. torque	172 Nm at 4.200 rpm
Engine capacity	1.794 cc
Cylinders	4
Fuel type	Petrol
Consumption city	27.4 mpg
Consumption extra urban	45.6 mpg
Consumption combined	36.7 mpg
CO2 emission	185 g/km
CO2 label	I





Internet history

Entry 1

Date	2021-09-25
Pictures	0
Listing price	View report

source: [autotrader.co.uk](#)

**MOT history**

MOT expiry date	2022-11-05
MOT pass rate	80 %
MOT passed	16
Failed MOT tests	4
Total advice items	48
Total items failed	10

MOT #20	2021-10-28 13:13
MOT test number	887813499133
Result	✓ Passed
Next expiry date	2022-11-05
Advice	Slight corrosion to underbody

MOT #19	2020-10-16 13:08
MOT test number	208502710173
Result	✓ Passed
Advice	Offside Rear Brake pipe corroded, covered in grease or other material (1.1.11 (c))
Advice	Front Registration plate deteriorated but not likely to be misread (0.1 (b))
Minor	Nearside Rear Brake pipe inadequately clipped or supported at floor mountings (1.1.11 (d) (i))
Advice	Nearside Rear Brake pipe corroded, covered in grease or other material (1.1.11 (c))
Advice	Rear Brakes imbalanced requirements only just met. It would appear that the braking system requires adjustment or repair. (1.2.1 (b) (i))
Minor	Offside Registration plate lamp inoperative in the case of multiple lamps or light sources (4.7.1 (b) (i))
Advice	Nearside Front Service brake binding but not excessively (1.2.1 (f))

**MOT #18**

2020-10-13 15:07

MOT test number

465940447146

Result**✗ Failed**

- Advice** Nearside Front Service brake binding but not excessively (1.2.1 (f))
- Advice** Offside Rear Brake pipe corroded, covered in grease or other material (1.1.11 (c))
- Advice** Rear Brakes imbalanced requirements only just met. It would appear that the braking system requires adjustment or repair. (1.2.1 (b) (i))
- Minor** Nearside Rear Brake pipe inadequately clipped or supported at floor mountings (1.1.11 (d) (i))
- Advice** Front Registration plate deteriorated but not likely to be misread (0.1 (b))
- Advice** Nearside Rear Brake pipe corroded, covered in grease or other material (1.1.11 (c))
- Fail** Nearside Rear Fuel pipe insecure at floor mountings (6.1.3 (a) (i))
- Minor** Offside Registration plate lamp inoperative in the case of multiple lamps or light sources (4.7.1 (b) (i))
- Fail** Nearside Front Coil spring fractured or broken (5.3.1 (b) (i))

MOT #17

2019-10-09 15:25

MOT test number

874935775049

Result**✓ Passed**

- Minor** Offside Registration plate lamp inoperative in the case of multiple lamps or light sources (4.7.1 (b) (i))
- Advice** Offside Rear Brake pipe corroded, covered in grease or other material (1.1.11 (c))
- Advice** Front Registration plate deteriorated but not likely to be misread (0.1 (b))
- Advice** Rear Registration plate deteriorated but not likely to be misread (0.1 (b))

**MOT #16** 2018-10-08 13:01**MOT test number** 218511069348**Result** ✓ Passed**Advice** Offside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))**Advice** Nearside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))**Advice** Offside Rear Tyre perishing/cracking on tread**MOT #15** 2017-10-20 12:30**MOT test number** 812001323459**Result** ✓ Passed**Advice** Offside Rear Tyre perishing/cracking on tread**MOT #14** 2017-10-11 14:52**MOT test number** 467203679080**Result** ✗ Failed**Fail** Exhaust emissions Lambda reading after 2nd fast idle outside specified limits (7.3.D.3)**Fail** Front position lamp(s) not working (1.1.A.3b)**Fail** Rear Exhaust has a major leak of exhaust gases (7.1.2)**Advice** Offside Rear Tyre perishing/cracking on tread**Fail** Nearside Registration plate lamp not working (1.1.C.1d)**MOT #13** 2016-10-07 13:58**MOT test number** 826482065407**Result** ✓ Passed**Advice** Offside rear tyre perishing/cracking on tread

**MOT #12** 2015-10-06 13:11**MOT test number** 349174871420**Result** ✓ Passed**MOT #11** 2014-10-21 11:23**MOT test number** 467184894212**Result** ✓ Passed**Advice** Front registration plate deteriorated but not likely to be misread (6.3.1d)**Notice** Front tyres perishing/cracking on tread**Notice** Under-trays fitted obscuring some underside components**Notice** Offside rear tyre perishing/cracking on tread**MOT #10** 2014-10-21 11:23**MOT test number** 635924494202**Result** ✗ Failed**Notice** Under-trays fitted obscuring some underside components**Notice** Offside rear tyre perishing/cracking on tread**Pass with rectification** Offside Front position lamp(s) not working (1.1.A.3b)**Advice** Front registration plate deteriorated but not likely to be misread (6.3.1d)**Notice** Front tyres perishing/cracking on tread**Pass with rectification** Offside Registration plate lamp not working (1.1.C.1d)**MOT #9** 2013-10-10 16:04**MOT test number** 239033383248**Result** ✓ Passed**Notice** Under-trays fitted obscuring some underside components

**MOT #8** 2012-10-16 14:13**MOT test number** 327360792470**Result** ✓ Passed**Notice** Under-trays fitted obscuring some underside components**MOT #7** 2011-10-14 15:27**MOT test number** 378297581244**Result** ✓ Passed**Notice** Protective covers fitted to underside of vehicle & over outer sills restricting inspections of testable items/areas**MOT #6** 2010-10-22 14:27**MOT test number** 210535390237**Result** ✓ Passed**Notice** Protective covers fitted to underside front of vehicle & over outer sills restricting inspections of testable items/areas**Advice** Offside Front Tyre worn close to the legal limit (4.1.E.1)**Advice** Nearside Front Tyre worn close to the legal limit (4.1.E.1)**MOT #5** 2009-10-27 14:24**MOT test number** 591960309321**Result** ✓ Passed**Notice** Protective covers fitted to underside front of vehicle & over outer sills restricting inspections of testable items/areas**MOT #4** 2008-10-22 17:02**MOT test number** 263836798288**Result** ✓ Passed**Notice** Engine and underside covers fitted restricting full inspection



MOT #3 2007-10-26 13:31

MOT test number 720999297219

Result ✓ Passed

Notice Nail in nearside rear tyre

Notice Protective cover fitted to underside front of vehicle restricting inspections of testable items.

Notice Nail in offside rear tyre

MOT #2 2007-10-23 14:42

MOT test number 841116097229

Result ✗ Failed

Notice Nail in nearside rear tyre

Fail Offside Front Brake pad(s) less than 1.5 mm thick (3.5.1g)

Notice Protective cover fitted to underside front of vehicle restricting inspections of testable items.

Notice Nail in offside rear tyre

Fail Offside Front brake disc excessively pitted (3.5.1h)

Advice Nearside Front brake disc slightly pitted (3.5.1h)

MOT #1 2006-10-23 16:44

MOT test number 934706696242

Result ✓ Passed



Tax & MOT check

✕
Untaxed

Tax expired:
31 January 2022

✕
MOT

Expired:
5 November 2022

Tax status	Expired at 31 January 2022
Days left	818 days too late
MOT expiry date	5 November 2022
Full MOT history	See MOT history

Tax calculation

Vehicle class	48
Band	I
Single payment (12 months)	£ 320,00,-
Single six month payment	£ 176,00,-
Total payable by 12 monthly instalments	£ 336,00,-




Damage history

Check the damage history for this TOYOTA. See if, where and when this TOYOTA had damage and the car repair costs. We also check if this TOYOTA was scrapped. Download the premium report [here](#) for the results.


Damage 1

Date	
Category	
Type	



Damage 2

Date	
Category	
Type	



Extra TOYOTA salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this TOYOTA in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,999
Auction value	£ 19,999
Average private trade value	£ 19,999

More info >



Owner history

For how long did the current and previous owner(s) have this TOYOTA? How many owners did this TOYOTA have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration

More info >

Plate changes

See in this check if this TOYOTA had different number plates.

Number of plates	1
Current registration	BD53JZJ
Plate since	2019-03-28
Current registration	BD53JZJ
Plate since	2019-03-28

More info >



Finance check

Check if this TOYOTA is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this TOYOTA has been settled. If not, and you buy this TOYOTA then you could lose the money and the car you paid for. Download the premium report [here](#) and check if this TOYOTA is financed.


Finance company	XXXXXXXXXX	XXXX
Date of agreement	XXXXXXXXXX	XXXX
Agreement type	XXXXXXXXXX	XXXX
Agreement term	XXXXXXXXXX	XXXX
Agreement number	XXXXXXXXXX	XXXX
Contact info	XXXXXXXXXX	XXXX

More info >



Mileage check

Odometer	In miles
Mileage registrations	21
First mileage registration	2003-11-05
Last registration	2021-10-28
Complete history	See info



Registration #1	2003-11-05	28 mi
Registration #2	2006-10-23	18.320 mi
Registration #3	2007-10-23	24.973 mi
Registration #4	2007-10-26	25.225 mi
Registration #5	2008-10-22	29.580 mi
Registration #6	2009-10-27	34.079 mi
Registration #7	2010-10-22	38.724 mi
Registration #8	2011-10-14	42.602 mi
Registration #9	2012-10-16	47.314 mi
Registration #10	2013-10-10	51.282 mi
Registration #11	2014-10-21	56.799 mi
Registration #12	2015-10-20	61.317 mi
Registration #13	2016-10-20	65.835 mi
Registration #14	2017-10-20	70.353 mi
Registration #15	2018-10-20	74.871 mi
Registration #16	2019-10-20	79.389 mi
Registration #17	2020-10-20	83.907 mi
Registration #18	2021-10-20	88.425 mi
Registration #19	2022-10-20	92.943 mi
Registration #20	2023-10-20	97.461 mi
Registration #21	2024-03-28	101.979 mi

More info >



Car features

The TOYOTA factory car options list is only available in the premium report.

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

View the complete TOYOTA factory list for this vehicle [here](#).

More info >

Dimensions & weight

Width	1735 mm
Height	1315 mm
Length	4350 mm
Wheel base	2600 mm
Kerb weight	1145 kg

Additional information

Fuel tank capacity	60 l
Fuel delivery	Multi-Point Injection
Number of doors	3
Engine number	1ZZ1324678