





report date: 2024-03-28

General information

Make	KIA
Model	CEED CRDI 3 SW
Colour	Blue
Year of manufacture	2011
Top speed	111 mph
0 - 60 mph	12.3 seconds
Gearbox	4 speed automatic

Engine & fuel consumption

Power	114 BHP
Max. torque	255 Nm at 2.750 rpm
Engine capacity	1.582 cc
Cylinders	4
Fuel type	Diesel
Consumption city	39.8 mpg
Consumption extra urban	55.4 mpg
Consumption combined	48.7 mpg
CO2 emission	154 g/km
CO2 label	G



CarCheck.co.uk page 1/12



report date: 2024-03-28

Internet history

Entry 1

Date 2021-02-01

Pictures 10

Listing price <u>View report</u>









source: autoonline.co.uk

CarCheck.co.uk page 2/12



report date: 2024-03-28

MOT history

MOT expiry date	2025-03-23
MOT pass rate	92 %
MOT passed	11
Failed MOT tests	1
Total advice items	16
Total items failed	3

MOT #12		2024-03-20 09:27
MOT test	number	139023045254
Result		✓ Passed
Next expi	ry date	2025-03-23
Advice	Nearside Rear Direction indicator slightly discoloured (4.4.3 (a))	
Advice	Offside Front Direction indicator slightly discoloured (4.4.3 (a))	
Advice	Nearside Front Side repeater slightly discoloured (4.4.3 (a))	
Advice	Nearside Front Direction indicator slightly discoloured (4.4.3 (a))	

MOT #11	2023-03-16 14:52
MOT test number	236318377334
Result	✓ Passed

CarCheck.co.uk page 3/12



report date: 2024-03-28

MOT #10 2023-03-16 11:18

MOT test number 857850989151

Result X Failed

Fail Nearside Front Anti-roll bar linkage ball joint dust cover no longer prevents the ingress of dirt (5.3.4 (b) (ii))

Advice Offside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))

Fail Offside Stop lamp(s) not working (4.3.1 (a) (ii))

Advice Nearside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))

Minor Offside Registration plate lamp inoperative in the case of multiple lamps or light sources (4.7.1 (b) (i))

Fail Nearside Stop lamp(s) not working (4.3.1 (a) (ii))

MOT #9 2022-03-24 12:15

MOT test number 828314951564

Result \rightarrow Passed

Advice Offside Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))

Advice Nearside Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))

MOT #8 2021-03-16 13:42

MOT test number 614969988312

Result ✓ Passed

MOT #7 2020-02-19 13:18

MOT test number 904137716688

Result ✓ Passed

MOT #6 2019-02-20 13:14

MOT test number 355314709441

Result

Passed

CarCheck.co.uk page 4/12



report date: 2024-03-28

MOT #5		2018-03-13 08:28
MOT test	number	610569849794
Result		✓ Passed
Advice	Offside Front Inner Tyre worn close to the legal limit edge (4.1.E.1)	
Advice	Offside Front Anti-roll bar linkage has slight play in a ball joint (2.4.G.2)	
Advice	Nearside Front Inner Tyre worn close to the legal limit edge (4.1.E.1)	
Advice	Rear Brake pad(s) wearing thin (3.5.1g)	

Advice Rear Brake pag(s) wearing thin (3.5.1g)	
MOT #4	2017-03-09 11:36
MOT test number	247238181071
Result	✓ Passed
MOT #3	2016-03-14 17:09
MOT test number	850102628725
Result	√ Passed
MOT #2	2015-09-23 10:02
MOT test number	184791703008
Result	√ Passed
MOT #1	2014-08-29 14:33
MOT test number	869881944249

1.101 #1		2014 00 23 14.33
MOT test	number	869881944249
Result		✓ Passed
Notice	N/s front tyre slight sidewall damage	
Advice Windscreen has damage to an area less than a 40mm circle outside zone 'A' (8.3.1d)		3.1d)
Notice	Under-trays fitted obscuring some underside components	

CarCheck.co.uk page 5/12



report date: 2024-03-28

Tax & MOT check



Tax status	Valid until 1 March
Days left	305
MOT expiry date	23 March 2025
Full MOT history	See MOT history

Tax calculation

Vehicle class	49
Band	G
Single payment (12 months)	£ 240,00,-
Single six month payment	£ 132,00,-
Total payable by 12 monthly instalments	£ 252,00,-

CarCheck.co.uk page 6/12



report date: 2024-03-28

Damage history

Check the damage history for this KIA. See if, where and when this KIA had damage and the car repair costs. We also check if this KIA was scrapped. Download the premium report <u>here</u> for the results.

Damage 1
Date
Category
Type
Damage 2
Date
Category
Type



Extra KIA salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report <u>here</u> for more information.

More info >

CarCheck.co.uk page 7/12



KU61XWP report date: 2024-03-28

Vehicle valuation

What is this car worth? See the vehicle value of this KIA in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value

Auction value

Average private trade value

More info >

CarCheck.co.uk page 8/12



report date: 2024-03-28

Owner history	
For how long did the current and previous owner(s) have this KIA? How many owners did Check it in the premium report and see all owner registrations. Download the full report J	

	More info >
Plate changes See in this check if this KIA had different number plates.	
Number of plates	
Current registration	NK NK
Plate since	
Current registration	NK NE
Plate since	
	More info >

CarCheck.co.uk page 9/12



report date: 2024-03-28

Finance check

Check if this KIA is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this KIA has been settled.

If not, and you buy this KIA then you could lose the money and the car you paid for.

Download the premium report <u>here</u> and check if this KIA is financed.

Finance company	
Date of agreement	
Agreement type	
Agreement term	
Agreement number	
Contact info	

More info >

CarCheck.co.uk page 10/12



report date: 2024-03-28

Mileage check

Registration #14

Odometer	In miles
Mileage registrations	14
First mileage registration	2011-09-27
Last registration	2024-03-20
Complete history	See info



Registration #1	2011-09-27	20 mi
Registration #2	2014-08-29	10.826 mi
Registration #3	2015-09-23	20.613 mi
Registration #4	2016-03-14	25.100 mi
Registration #5	2017-03-09	44.596 mi
Registration #6	2018-03-13	51.926 mi
Registration #7	2019-02-20	59.646 mi
Registration #8		11.777 es
Registration #9		11.777 es
Registration #10		11.777 es
Registration #11		11.777 es
Registration #12		11.777 es
Registration #13		11.777 es

mn.n.n

More info >

77.777 au

CarCheck.co.uk page 11/12



report date: 2024-03-28

Car features

50225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

Safety ratings

NCAP rating	****
Video	see crash video



Dimensions & weight

Width	1790 mm
Height	1525 mm
Length	4490 mm
Wheel base	2650 mm
Kerb weight	1509 kg
Max. allowed weight	1940 kg

Additional information

Fuel delivery	Direct Injection
Number of doors	5
Number of seats	5
Number of axles Carcheck.co.uk	2 page 12/12