





report date: 2024-03-29

General information

Make	VOLKSWAGEN
Model	FOX
Colour	Red
Year of manufacture	2008
Top speed	92 mph
0 - 60 mph	17.5 seconds
Gearbox	5 speed Manual

Engine & fuel consumption

Power	55 BHP
Max. torque	108 Nm at 3.000 rpm
Engine capacity	1.198 cc
Cylinders	3
Fuel type	Petrol
Consumption city	36.2 mpg
Consumption extra urban	55.4 mpg
Consumption combined	46.3 mpg
CO2 emission	139 g/km
CO2 label	E



CarCheck.co.uk page 1/12



report date: 2024-03-29

Internet history

Entry 1

Date 2021-07-28

Pictures 16

Listing price <u>View report</u>









source: autotrader.co.uk

CarCheck.co.uk page 2/12



report date: 2024-03-29

MOT history

MOT expiry date	2024-07-25
MOT pass rate	93 %
MOT passed	13
Failed MOT tests	1
Total advice items	13
Total items failed	1

MOT #14		2023-07-25 16:06
MOT test	number	318115266096
Result		✓ Passed
Next exp	ry date	2024-07-25
Minor	Offside Front Upper Anti-roll bar linkage ball joint dust cover severely dete	eriorated (5.3.4 (b) (i))
Advice	Advice Tyre slightly damaged/cracking or perishing all 4 are slightly cracking (5.2.3 (d) (ii))	
Minor	Offside Front Suspension arm ball joint dust cover severely deteriorated (5.3.4 (b) (i))
Minor	Nearside Front Upper Anti-roll bar linkage ball joint dust cover severely de	eteriorated (5.3.4 (b) (i))
Minor	Nearside Front Suspension arm ball joint dust cover severely deteriorated	d (5.3.4 (b) (i))

MOT #13		2023-07-24 09:20
MOT test	number	997851637823
Result		≍ Failed
Minor	Nearside Front Upper Anti-roll bar linkage ball joint dust cover severely	y deteriorated (5.3.4 (b) (i))
Minor	Nearside Front Suspension arm ball joint dust cover severely deteriora	ated (5.3.4 (b) (i))
Advice	Tyre slightly damaged/cracking or perishing all 4 are slightly cracking	g (5.2.3 (d) (ii))
Fail Nearside Front Outer Drive shaft joint constant velocity boot split or insecure, no longer prevents the ingress of dirt split (6.1.7 (g) (ii))		
Minor	Offside Front Upper Anti-roll bar linkage ball joint dust cover severely	deteriorated (5.3.4 (b) (i))
Minor	Offside Front Suspension arm ball joint dust cover severely deteriorate	ed (5.3.4 (b) (i))

CarCheck.co.uk page 3/12



MOT #12

Result

FM08WVC

report date: 2024-03-29

2022-07-26 10:10

✓ Passed

MOT test r	number	289037758478
Result		✓ Passed
Advice	Nearside Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))	
Advice	Offside Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))	
MOT #11		2021-07-16 12:10
MOT test r	number	671205103696
Result		✓ Passed
MOT #10		2020-08-21 10:16
MOT test r	number	345232854439
Result		✓ Passed
MOT #9		2019-08-27 13:27
MOT test r	number	207559354981

MOI #8	2018-08-28 10:32
MOT test number	490460815782
Result	✓ Passed

MOT #7	2017-08-16 09:36
MOT test number	498233697119
Result	√ Passed

MOT #6	2016-08-16 09:43
MOT test number	201155816179
Result	✓ Passed

CarCheck.co.uk page 4/12



report date: 2024-03-29

MOT #5	2015-08-12 10:59
MOT test number	213988117543
Result	✓ Passed
MOT #4	2014-08-11 11:05
MOT test number	566593624226
Result	✓ Passed
MOT #3	2013-08-13 10:11
MOT test number	306875623408
Result	✓ Passed
MOT #2	2012-08-13 11:50
MOT test number	435046422242
Result	✓ Passed
MOT #1	2011-08-15 10:54
MOT test number	297527621209
Result	✓ Passed
Advice Brake hydraulic reservoir fluid close to minimum level (3.6.G.1b)	

CarCheck.co.uk page 5/12



report date: 2024-03-29

Tax & MOT check



Tax status	Valid until 1 April
Days left	337
MOT expiry date	25 July 2024
Full MOT history	See MOT history

Tax calculation

Vehicle class	48
Band	Е
Single payment (12 months)	£ 180,00,-
Single six month payment	£ 99,00,-
Total payable by 12 monthly instalments	£ 189,00,-

CarCheck.co.uk page 6/12



report date: 2024-03-29

Damage history

Check the damage history for this VOLKSWAGEN. See if, where and when this VOLKSWAGEN had damage and the car repair costs. We also check if this VOLKSWAGEN was scrapped. Download the premium report here for the results.


Damage 1

Date
Category
Type
Damage 2

Date

Category

Type



Extra VOLKSWAGEN salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report <u>here</u> for more information.

More info >

CarCheck.co.uk page 7/12



report date: 2024-03-29

Vehicle valuation

What is this car worth? See the vehicle value of this VOLKSWAGEN in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value

Auction value

Average private trade value

More info >

CarCheck.co.uk page 8/12



report date: 2024-03-29

Owner history

For how long did the current and previous owner(s) have this VOLKSWAGEN? How many VOLKSWAGEN have? Check it in the premium report and see all owner registrations. Downere.	

	More info >
Plate changes	
See in this check if this VOLKSWAGEN had different number plates.	
Number of plates	,
Current registration	OK SIE
Plate since	
Current registration	IR SIE
Plate since	
	More info

CarCheck.co.uk page 9/12



report date: 2024-03-29

Finance check

Check if this VOLKSWAGEN is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this VOLKSWAGEN has been settled.

If not, and you buy this VOLKSWAGEN then you could lose the money and the car you paid for.

Download the premium report <u>here</u> and check if this VOLKSWAGEN is financed.

Finance company	
Date of agreement	
Agreement type	
Agreement term	
Agreement number	
Contact info	

Contact info

 $\quad \text{More info} \quad > \quad$

CarCheck.co.uk page 10/12



report date: 2024-03-29

Mileage check

Registration #16

Odometer	In miles
Mileage registrations	16
First mileage registration	2008-08-29
Last registration	2023-07-25
Complete history	See info



Registration #1	2008-08-29	19 mi
Registration #2	2011-08-15	4.619 mi
Registration #3	2012-08-13	6.014 mi
Registration #4	2013-08-13	6.868 mi
Registration #5	2014-08-11	8.379 mi
Registration #6	2015-08-12	9.519 mi
Registration #7	2016-08-16	10.210 mi
Registration #8	2017-08-16	10.531 mi
Registration #9		11.177 es
Registration #10		71.777 es
Registration #11		11.177 mi
Registration #12		11.117 es
Registration #13		11.177 mi
Registration #14		11.117 es
Registration #15		11.177 es

7070.70.70

More info >

77. 777 mg

CarCheck.co.uk page 11/12



report date: 2024-03-29

Car features

	Air conditionin
50295	
50482	
50501	
50566	
60567	
50569	

Safety ratings

NCAP rating	★★★★ ★
Video	see crash video



Dimensions & weight

Width	1660 mm
Height	1544 mm
Length	3828 mm
Wheel base	2465 mm
Kerb weight	1069 kg
Max. allowed weight	1480 kg

Additional information

Fuel tank capacity	50 l
Fuel delivery	Multi-Point Injection
Number of doors	3
CarChaeleeaule	maga 12/12

CarCheck.co.uk page 12/12

Number of seats	4
Number of axles	2
Engine number	BMD 378141