





report date: 2024-03-29

General information

Make	PEUGEOT
Model	107 URBAN
Colour	Yellow
Year of manufacture	2007
Top speed	100 mph
0 - 60 mph	14.2 seconds
Gearbox	5 speed Manual

Engine & fuel consumption

Power	67 BHP
Max. torque	93 Nm at 3.600 rpm
Engine capacity	998 сс
Cylinders	3
Fuel type	Petrol
Consumption city	51.4 mpg
Consumption extra urban	68.9 mpg
Consumption combined	61.4 mpg
CO2 emission	109 g/km
CO2 label	В



CarCheck.co.uk page 1/14



Internet history

_	_	_		_	-
드	n	C	ľν	7	1

Life y 1	
Date	2021-02-03
Pictures	0
Listing price	View report

source: autoonline.co.uk

CarCheck.co.uk page 2/14



MOT history

MOT expiry date	2024-09-07
MOT pass rate	94 %
MOT passed	15
Failed MOT tests	1
Total advice items	33
Total items failed	2

MOT #16	2023-09-08 09:30
MOT test number	120631534861
Result	✓ Passed
Next expiry date	2024-09-07
Minor Offside Obligatory mirror slightly damaged (3.3 (b) (i))	

MOT #15	2022-08-11 09:48
MOT test	number 753710075601
Result	✓ Passed
Minor	Nearside Front Lower Suspension arm ball joint dust cover severely deteriorated (5.3.4 (b) (i))
Minor	Offside Front Lower Suspension arm ball joint dust cover severely deteriorated (5.3.4 (b) (i))

MOT #14	2022-08-11 09:48		
MOT test number	173159610263		
Result	★ Failed		
Pass with rectification	Nearside Headlamp aim projected beam image is obviously incorrect (4.1.2 (c))		
Minor Nearside Front Lower Suspension arm ball joint dust cover severely deteriorated (5.3.4 (b) (i))			
Pass with rectification	Offside Headlamp aim projected beam image is obviously incorrect (4.1.2 (c))		
Minor Offside Front Lower Suspension arm ball joint dust cover severely deteriorated (5.3.4 (b) (i))			

CarCheck.co.uk page 3/14



Result

HN07CFJ report date: 2024-03-29

✓ Passed

MOT #13 2021-08-17 13:19

MOT test number 311832712372

Advice Tyre slightly damaged/cracking or perishing both front`s (5.2.3 (d) (ii))

Minor Offside Front Obligatory mirror slightly damaged (3.3 (b) (i))

Advice Offside Rear Service brake binding but not excessively (1.2.1 (f))

Advice Nearside Rear Tyre worn close to legal limit/worn on edge 2mm (5.2.3 (e))

Advice Headlamp has a product on the lens but not seriously reducing light output both front's (4.1.4 (b))

Advice Offside Rear Tyre worn close to legal limit/worn on edge on 1.6mm (5.2.3 (e))

MOT #12 2020-08-21 12:29

MOT test number 926851109340

Advice Offside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))

Advice Nearside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))

MOT #11 2020-03-06 13:17

MOT test number 982582953869

Result ✓ Passed

Advice Coil spring corroded all (5.3.1 (b) (i))

Advice Coolant leak

Advice Front Anti-roll bar linkage pin or bush worn but not resulting in excessive movement (5.3.4 (a) (i))

Advice Front Brake disc worn, but not excessively (1.1.14 (a) (i))

CarCheck.co.uk page 4/14



MOT #10 2019-03-15 13:37

MOT test number 872726100085

Result \rightarrow Passed

Advice Front Anti-roll bar linkage pin or bush worn but not resulting in excessive movement (5.3.4 (a) (i))

MOT #9 2018-02-26 11:01

MOT test number 506621314484

Result \(\sqrt{Passed} \)

Advice Advise condition of exhaust

Advice Front Anti-roll bar linkage rubber mounting deteriorated but not resulting in excessive movement

(2.4.G.2)

(2.4.G.2)

MOT #8 2017-03-13 10:14

MOT test number 638440655542

Result
✓ Passed

Advice O/s/f tyre wearing very badly on inner edge[only just legal]

Advice Front Anti-roll bar linkage rubber bush deteriorated but not resulting in excessive movement both (2.4.G.2)

Advice Advise n/s/f tyre wearing on edges

MOT #7 2016-03-11 15:10

MOT test number 175287605591

Result \rightarrow Passed

Advice Front Anti-roll bar linkage rubber mounting deteriorated but not resulting in excessive movement

Advice Front brake disc worn, pitted or scored, but not seriously weakened (3.5.1i)

Advice Advise both rear tyres badly worn on outer edges[raised shoulders] and perished

CarCheck.co.uk page 5/14



Result

HN07CFJ report date: 2024-03-29

✓ Passed

MOT test number

117638765451

Result

Notice Advise n/s/r tyre starting to wear on edges

Advice Front brake disc worn, pitted or scored, but not seriously weakened (3.5.1i)

Notice Advise both front tyres wearing badly on edges[raised shoulders]and perished

Advice Front Anti-roll bar linkage rubber mounting deteriorated but not resulting in excessive movement (2.4.G.2)

MOT #5

MOT test number

Result

Advice Front brake disc worn, pitted or scored, but not seriously weakened (3.5.1i)

MOT #4

MOT test number

179817863013

Result

Notice Nearside front tyre worn low on outer edge

 MOT #3
 2012-03-15 12:52

 MOT test number
 748535472009

 Result
 ✓ Passed

 MOT #2
 2011-03-18 10:43

 MOT test number
 957557471044

CarCheck.co.uk page 6/14



MOT #1

MOT test number

423108070045

Result

Notice Nail in n/s/f tyre

CarCheck.co.uk page 7/14



Tax & MOT check



Tax status	Valid until 1 January
Days left	246
MOT expiry date	7 September 2024
Full MOT history	See MOT history

Tax calculation

Vehicle class	48
Band	В
Single payment (12 months)	£ 20,00,-
Single six month payment	Not applicable
Total payable by 12 monthly instalments	£ 21,00,-

CarCheck.co.uk page 8/14



Damage history

Check the damage history for this PEUGEOT. See if, where and when this PEUGEOT had damage and the car repair costs. We also check if this PEUGEOT was scrapped. Download the premium report here for the results.

Damage 1
Date
Category
Type
Damage 2
Date
Category
Type



Extra PEUGEOT salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report <u>here</u> for more information.

More info >

CarCheck.co.uk page 9/14



Vehicle valuation

What is this car worth? See the vehicle value of this PEUGEOT in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value

Auction value

Average private trade value

More info >

CarCheck.co.uk page 10/14



Owner history

,		
For how long did the current and previous owner(s) have this PEUGEOT? How many owner have? Check it in the premium report and see all owner registrations. Download the full respectively.		IGEOT

	More info	
	More into	
Plate changes		
See in this check if this PEUGEOT had different number plates.		
Number of plates		,
Current registration	UK UK	
Plate since		
Current registration	UK UK	
Plate since		
	More info	>

CarCheck.co.uk page 11/14



Finance check

Check if this PEUGEOT is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this PEUGEOT has been settled.

If not, and you buy this PEUGEOT then you could lose the money and the car you paid for.

Download the premium report <u>here</u> and check if this PEUGEOT is financed.

Finance company	
Date of agreement	
Agreement type	
Agreement term	
Agreement number	
Courts at info	

Contact info

More info >

CarCheck.co.uk page 12/14



Mileage check

Odometer	In miles
Mileage registrations	18
First mileage registration	2007-04-12
Last registration	2023-09-08
Complete history	See info



Registration #1	2007-04-12	12 mi
Registration #2	2010-03-19	10.832 mi
Registration #3	2011-03-18	14.271 mi
Registration #4	2012-03-15	16.736 mi
Registration #5	2013-03-08	18.956 mi
Registration #6	2014-03-19	20.626 mi
Registration #7	2015-03-09	25.089 mi
Registration #8	2016-03-11	29.915 mi
Registration #9	2017-03-13	34.435 mi
Registration #10		71.777 es
Registration #11		11.777 es
Registration #12		71.777 es
Registration #13		11.777 es
Registration #14		71.777 es
Registration #15		11.777 es
Registration #16		71.777 es
Registration #17		11.777 es
Registration #18		11.777 es

More info >

CarCheck.co.uk page 13/14



Car features

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

Safety ratings

NCAP rating	****
Video	see crash video



Dimensions & weight

Width	1630 mm
Height	1465 mm
Length	3430 mm
Wheel base	2340 mm
Kerb weight	825 kg
Max. allowed weight	1190 kg

Additional information

Fuel tank capacity	35 I
Fuel delivery	Multi-Point Injection
Number of doors	5
Number of seats CarCheck.co.uk	4 page 14/1