



report date: 2024-03-29

General information

Make	FIAT
Model	SCUDO DELUXE LWB P/V 120 MULTIJET
Colour	Grey
Year of manufacture	2008
Top speed	99 mph
0 - 60 mph	13.0 seconds
Gearbox	6 speed Manual

Engine & fuel consumption

Power	120 BHP
Max. torque	300 Nm at 2.000 rpm
Engine capacity	1.997 cc
Cylinders	4
Fuel type	Diesel



LABEL UNKNOWN



MOT history

MOT expiry date	2024-05-09
MOT pass rate	71 %
MOT passed	12
Failed MOT tests	5
Total advice items	34
Total items failed	4

MOT #17	2023-05-10 08:33
MOT test number	928744846589
Result	✓ Passed
Next expiry date	2024-05-09

MOT #16	2022-05-05 09:08
MOT test number	576093966320
Result	✓ Passed
Minor	Nearside Front Lower Anti-roll bar ball joint dust cover severely deteriorated (5.3.4 (b) (i))
Advice	Oil leak, but not excessive (8.4.1 (a) (i))
Minor	Front Windscreen wiper blade defective both sides (3.4 (b) (i))

MOT #15	2021-04-30 09:00
MOT test number	781938100474
Result	✓ Passed
Advice	Front Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))
Advice	Under Seal Coated

**MOT #14** 2021-04-30 09:00**MOT test number** 404413445487**Result** ✗ Failed**Pass with rectification** Offside Front Headlamp aim too high (4.1.2 (a))**Advice** Under Seal Coated**Pass with rectification** Nearside Front Headlamp aim too low (4.1.2 (a))**Advice** Front Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))**MOT #13** 2019-10-04 11:14**MOT test number** 250807562564**Result** ✓ Passed**MOT #12** 2019-09-27 13:40**MOT test number** 747968668708**Result** ✗ Failed**MAJOR** Nearside Rear Parking brake inoperative on one side (1.4.1 (a))**MAJOR** Nearside Front Outer Drive shaft joint constant velocity boot split or insecure, no longer prevents the ingress of dirt (6.1.7 (g) (ii))**MAJOR** Parking brake efficiency below requirements (1.4.2 (a) (i))**MOT #11** 2018-10-02 14:20**MOT test number** 555332605804**Result** ✓ Passed

**MOT #10** 2018-09-28 09:57**MOT test number** 518719164929**Result** ✗ Failed

- MAJOR** Offside Rear fog lamp not working (4.5.1 (a) (ii))
- MAJOR** Offside Front Position lamp not working (4.2.1 (a))
- MAJOR** Parking brake efficiency below requirements (1.4.2 (a) (i))
- MAJOR** Offside Direction indicator not working (4.4.1 (a) (ii))
- MAJOR** Offside Parking brake inoperative on one side (1.4.1 (a))

MOT #9 2017-09-20 14:08**MOT test number** 793133615222**Result** ✓ Passed

- Advice** Nearside Front Nail in tyre
- Advice** Nearside Front Tyre worn close to the legal limit (4.1.E.1)

MOT #8 2017-09-20 14:08**MOT test number** 803003611785**Result** ✗ Failed

- Pass with rectification** Offside Headlamp not working on dipped beam (1.7.5a)
- Advice** Nearside Front Nail in tyre
- Advice** Nearside Front Tyre worn close to the legal limit (4.1.E.1)

MOT #7 2016-08-27 09:00**MOT test number** 392058361104**Result** ✓ Passed

- Advice** Nsr tyre unevenly worn
- Advice** Nsf tyre wearing low

**MOT #6** 2015-09-12 09:42**MOT test number** 320055010460**Result** ✓ Passed**Advice** Os wiper blade torn on edge**Advice** Exhaust corroding**MOT #5** 2014-09-27 11:32**MOT test number** 608690174247**Result** ✓ Passed**Notice** Both rear tyres wearing slightly uneven across tread**Advice** Offside front brake fluctuating, but not excessively (3.7.B.3)**Notice** Items removed from driver's view prior to test**Advice** Front brake disc worn, pitted or scored, but not seriously weakened (3.5.1i)**Advice** Nearside front brake fluctuating, but not excessively (3.7.B.3)**MOT #4** 2014-09-27 11:32**MOT test number** 895010474266**Result** ✗ Failed**Advice** Front brake disc worn, pitted or scored, but not seriously weakened (3.5.1i)**Advice** Nearside front brake fluctuating, but not excessively (3.7.B.3)**Notice** Items removed from driver's view prior to test**Pass with rectification** Offside Front Upper Windscreen has a sticker or other obstruction encroaching into the swept area by more than 40mm outside zone 'A' (8.3.1e)**Advice** Offside front brake fluctuating, but not excessively (3.7.B.3)**Notice** Both rear tyres wearing slightly uneven across tread



MOT #3	2013-09-14 10:50
MOT test number	646857853222
Result	✓ Passed
Advice	Front brake disc worn, pitted or scored, but not seriously weakened (3.5.1i)

MOT #2	2012-06-26 11:44
MOT test number	865528372112
Result	✓ Passed

MOT #1	2011-06-30 15:27
MOT test number	216591481135
Result	✓ Passed



Tax & MOT check

✓
Taxed

Tax due:
1 October 2024

✓
MOT

Expires:
9 May 2024

Tax status		Valid until 1 October
Days left		154
MOT expiry date		9 May 2024
Full MOT history		See MOT history



Damage history

Check the damage history for this FIAT. See if, where and when this FIAT had damage and the car repair costs. We also check if this FIAT was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	

Damage 2

Date	
Category	
Type	



Extra FIAT salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this FIAT in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,999
Auction value	£ 19,999
Average private trade value	£ 19,999

More info >



Owner history

For how long did the current and previous owner(s) have this FIAT? How many owners did this FIAT have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration

More info >

Plate changes

See in this check if this FIAT had different number plates.

Number of plates	1
Current registration	
Plate since	2024-03-29
Current registration	
Plate since	2024-03-29

More info >



Finance check

Check if this FIAT is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this FIAT has been settled.

If not, and you buy this FIAT then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this FIAT is financed.

Finance company	XXXXXXXX XX
Date of agreement	XXXXXXXX XX
Agreement type	XXXXXXXX XX
Agreement term	XXXXXXXX XX
Agreement number	XXXXXXXX XX
Contact info	XXXXXXXX XX

More info >



Mileage check

Odometer	In miles
Mileage registrations	17
First mileage registration	2008-06-30
Last registration	2023-05-10
Complete history	See info



Registration #1	2008-06-30	23 mi
Registration #2	2011-06-30	41.471 mi
Registration #3	2012-06-26	43.014 mi
Registration #4	2013-09-14	49.597 mi
Registration #5	2014-09-27	56.248 mi
Registration #6	2015-09-12	60.567 mi
Registration #7	2016-08-27	65.609 mi
Registration #8	2017-09-20	72.184 mi
Registration #9	2017-09-20	72.184 mi
Registration #10	2018-05-20	75.277 mi
Registration #11	2018-05-20	75.277 mi
Registration #12	2018-05-20	75.277 mi
Registration #13	2018-05-20	75.277 mi
Registration #14	2018-05-20	75.277 mi
Registration #15	2018-05-20	75.277 mi
Registration #16	2018-05-20	75.277 mi
Registration #17	2018-05-20	75.277 mi

More info >



Car features

The FIAT factory car options list is only available in the premium report.

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

View the complete FIAT factory list for this vehicle [here](#).

More info >

Dimensions & weight

Width	1895 mm
Height	1942 mm
Length	4805 mm
Kerb weight	1702 kg

Additional information

Fuel tank capacity	80 l
Fuel delivery	Direct Injection
Number of doors	5
Number of seats	2
Engine number	4052884