



report date: 2024-03-28

General information

Make	FORD
Model	FOCUS C-MAX GHIA
Colour	Blue
Year of manufacture	-
Top speed	127 mph
0 - 60 mph	9.8 seconds
Gearbox	4 speed automatic

Engine & fuel consumption

Power	143 BHP
Max. torque	185 Nm at 4.500 rpm
Cylinders	4
Fuel type	Petrol
Consumption city	25.0 mpg
Consumption extra urban	45.6 mpg
Consumption combined	34.9 mpg



LABEL UNKNOWN



Internet history

Entry 1

Date	2021-10-25
Pictures	21
Listing price	View report



source: autotrader.co.uk

**MOT history**

MOT #20	2023-07-14 09:43
MOT test number	322858407984
Result	✓ Passed
Next expiry date	2024-08-09

MOT #19	2022-07-15 10:34
MOT test number	311735293828
Result	✓ Passed
Advice	REAR SUSPENSION SHOWING SIGNS OF AGE RELATED CORROSION

MOT #18	2021-08-02 14:31
MOT test number	952021839995
Result	✓ Passed

MOT #17	2021-08-02 08:18
MOT test number	551913361936
Result	✗ Failed
Fail	Nearside Front Suspension arm ball joint excessively worn (5.3.4 (a) (i))
Fail	Nearside Front Lower Anti-roll bar linkage ball joint dust cover no longer prevents the ingress of dirt (5.3.4 (b) (ii))

MOT #16	2020-08-01 11:09
MOT test number	487413338791
Result	✓ Passed
Advice	Nearside Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))

**MOT #15** 2020-08-01 11:09**MOT test number** 802222823643**Result** ✗ Failed**Pass with rectification** Nearside Front Headlamp aim too high (4.1.2 (a))**Advice** Nearside Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))**Pass with rectification** Nearside Front Position lamp not working (4.2.1 (a) (ii))**MOT #14** 2019-07-22 14:54**MOT test number** 574919789658**Result** ✓ Passed**MOT #13** 2019-07-22 08:19**MOT test number** 236728526919**Result** ✗ Failed**Advice** Offside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))**Advice** Nearside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))**Fail** Nearside Front Headlamp lens seriously defective (4.1.1 (b) (ii))**MOT #12** 2018-07-12 08:24**MOT test number** 376664943499**Result** ✓ Passed**MOT #11** 2017-08-05 16:04**MOT test number** 146736703924**Result** ✓ Passed**Advice** Exhaust in rusty condition**Advice** Nearside Headlamp deteriorated but light output not reduced (1.7.5a)



MOT #102017-08-04 09:09

MOT test number206477589862

Result

Failed

- Fail

Offside Front coil spring broken (2.4.C.1a)
- Fail

Offside Headlamp excessively deteriorated so that the light output is severely reduced (1.7.5a)
- Fail

Offside Inner Front constant velocity joint gaiter deteriorated to the extent that it no longer prevents the ingress of dirt etc (2.5.C.1a)
- Advice

Exhaust in rusty condition
- Advice

Nearside Headlamp deteriorated but light output not reduced (1.7.5a)
- Fail

Offside Rear Seat belt retracting mechanism defective (5.2.5b)

MOT #92016-08-01 17:12

MOT test number454414237323

Result

Passed

- Advice

Nearside Rear Child Seat fitted not allowing full inspection of adult belt
- Advice

Nsr parking brake little effort on application in rollers
- Advice

Offside Rear seat belt dose not retract fully into cowl
- Advice

Offside Front Inner Drive shaft which forms part of the suspension slightly damaged (2.4.G.4a)

**MOT #8**

2016-08-01 09:05

MOT test number

995428531349

Result**✗ Failed****Fail**

Nearside Front Suspension arm rubber bush deteriorated resulting in excessive movement rear bush (2.4.G.2)

Advice

Offside Rear seat belt dose not retract fully into cowling

Fail

Offside Front Suspension arm rubber bush deteriorated resulting in excessive movement rear bush (2.4.G.2)

Advice

Nearside Rear Child Seat fitted not allowing full inspection of adult belt

Advice

Offside Front Suspension arm rubber bush deteriorated but not resulting in excessive movement rear bush (2.4.G.2)

Advice

Nsr parking brake little effort on application in rollers

MOT #7

2015-08-10 10:24

MOT test number

715232925268

Result**✓ Passed****Advice**

Offside Front Suspension arm rubber bush deteriorated but not resulting in excessive movement (2.4.G.2)

Advice

Nearside Front Suspension arm rubber bush deteriorated but not resulting in excessive movement (2.4.G.2)

MOT #6

2014-09-09 15:00

MOT test number

375342454203

Result**✓ Passed****MOT #5**

2013-09-13 12:00

MOT test number

498726553201

Result**✓ Passed****MOT #4**

2012-10-16 12:39

MOT test number

639200592299

Result**✓ Passed****Advice**

Rear Brake pad(s) wearing thin (3.5.1g)



MOT #3	2011-10-15 08:38
MOT test number	306758981214
Result	✓ Passed
MOT #2	2010-09-15 13:37
MOT test number	652348950273
Result	✓ Passed
MOT #1	2009-10-15 11:32
MOT test number	941668389257
Result	✓ Passed



Damage history

Check the damage history for this FORD. See if, where and when this FORD had damage and the car repair costs. We also check if this FORD was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	

Damage 2

Date	
Category	
Type	



Extra FORD salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this FORD in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,999
Auction value	£ 19,999
Average private trade value	£ 19,999

More info >



Owner history

For how long did the current and previous owner(s) have this FORD? How many owners did this FORD have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since

More info >

Plate changes

See in this check if this FORD had different number plates.

Number of plates	1
Current registration	YH56UGN
Plate since	2019-09-29
Current registration	YH56UGN
Plate since	2019-09-29

More info >



Finance check

Check if this FORD is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this FORD has been settled.

If not, and you buy this FORD then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this FORD is financed.

Finance company	XXXXXXXXXX	XXXX
Date of agreement	XXXXXXXXXX	XXXX
Agreement type	XXXXXXXXXX	XXXX
Agreement term	XXXXXXXXXX	XXXX
Agreement number	XXXXXXXXXX	XXXX
Contact info	XXXXXXXXXX	XXXX

More info >



Mileage check

Odometer	In miles
Mileage registrations	22
First mileage registration	2006-11-29
Last registration	2023-07-14
Complete history	See info



Registration #1	2006-11-29	25 mi
Registration #2	2009-10-15	18.654 mi
Registration #3	2010-09-15	22.048 mi
Registration #4	2011-10-15	27.487 mi
Registration #5	2012-10-16	30.179 mi
Registration #6	2013-09-13	33.751 mi
Registration #7	2014-09-09	36.864 mi
Registration #8	2015-08-10	40.212 mi
Registration #9	2016-08-01	42.146 mi
Registration #10	2016-08-01	42.146 mi
Registration #11	2017-08-04	43.167 mi
Registration #12	2018-08-01	44.188 mi
Registration #13	2019-08-01	45.209 mi
Registration #14	2020-08-01	46.230 mi
Registration #15	2021-08-01	47.251 mi
Registration #16	2022-08-01	48.272 mi
Registration #17	2023-08-01	49.293 mi
Registration #18	2024-08-01	50.314 mi
Registration #19	2025-08-01	51.335 mi
Registration #20	2026-08-01	52.356 mi
Registration #21	2027-08-01	53.377 mi
Registration #22	2028-08-01	54.398 mi

More info >



Car features

The FORD factory car options list is only available in the premium report.

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

View the complete FORD factory list for this vehicle [here](#).

More info >

Safety ratings

NCAP rating ★★★★★

Video [see crash video](#)



Dimensions & weight

Width	2022 mm
Height	1595 mm
Length	4333 mm
Wheel base	2640 mm
Kerb weight	1441 kg
Max. allowed weight	1930 kg

Additional information

Fuel tank capacity	55 l
Fuel delivery	Multi-Point Injection
Number of doors	5
Number of seats	5

Engine number	6B25639
---------------	---------