




report date: 2024-03-29

General information

Make	VOLKSWAGEN
Model	TIGUAN MATCH TDI 4MOTION DSG
Colour	Blue
Year of manufacture	2011
Top speed	114 mph
0 - 100 km/h	10.7 seconds
Gearbox	7 speed Semi Auto

Engine & fuel consumption

Power	103 kW / 140 HP / 138 BHP
Max. torque	320 Nm at 1.750 rpm
Engine capacity	1.968 cc
Cylinders	4
Fuel type	Diesel
Consumption city	36.2 mpg
Consumption extra urban	49.6 mpg
Consumption combined	44.1 mpg
CO2 emission	169 g/km
CO2 label	H





Internet history

Entry 1

Date	2022-03-23
Pictures	12
Listing price	View report



source: [cargurus.co.uk](https://www.cargurus.co.uk)



MOT history

MOT expiry date	2025-04-15
MOT pass rate	92 %
MOT passed	12
Failed MOT tests	1
Total advice items	30
Total items failed	4

MOT #13 2024-04-16 14:27

MOT test number 641447939502

Result ✔ Passed

Next expiry date 2025-04-15

- Advice** Offside Rear Anti-roll bar pin or bush worn but not resulting in excessive movement D bush (5.3.4 (a) (i))
- Advice** Nearside Rear Anti-roll bar pin or bush worn but not resulting in excessive movement D bush (5.3.4 (a) (i))
- Advice** Offside Front Shock absorbers has light misting of oil (5.3.2 (b))
- Advice** Offside Anti-roll bar linkage pin or bush worn but not resulting in excessive movement (5.3.4 (a) (i))
- Advice** Nearside Front Shock absorbers has light misting of oil (5.3.2 (b))



MOT #12

2024-04-16 13:03

MOT test number

546287514606

Result

✓ Passed

Advice Nearside Front Shock absorbers has light misting of oil (5.3.2 (b))

Advice Nearside Rear Brake disc worn, but not excessively (1.1.14 (a) (i))

Advice Offside Rear Anti-roll bar linkage pin or bush worn but not resulting in excessive movement (5.3.4 (a) (i))

Advice Offside Rear Anti-roll bar pin or bush worn but not resulting in excessive movement D bush (5.3.4 (a) (i))

Advice Offside Front Shock absorbers has light misting of oil (5.3.2 (b))

Advice Offside Rear Brake disc worn, but not excessively (1.1.14 (a) (i))

Advice Nearside Rear Anti-roll bar pin or bush worn but not resulting in excessive movement D bush (5.3.4 (a) (i))



MOT #11 2024-04-12 08:15

MOT test number 706527091270

Result ✗ Failed

- Advice** Nearside Front Brake disc worn, but not excessively (1.1.14 (a) (i))
- Advice** Offside Front Shock absorbers has light misting of oil (5.3.2 (b))
- Advice** Offside Rear Brake disc worn, but not excessively (1.1.14 (a) (i))
- Fail** Offside Front Suspension arm pin or bush excessively worn Rear bush (5.3.4 (a) (i))
- Advice** Nearside Rear Anti-roll bar pin or bush worn but not resulting in excessive movement D bush (5.3.4 (a) (i))
- Fail** Offside Front Brake disc significantly and obviously worn (1.1.14 (a) (i))
- Advice** Offside Front Brake pad(s) wearing thin (1.1.13 (a) (ii))
- Advice** Nearside Front Shock absorbers has light misting of oil (5.3.2 (b))
- Advice** Nearside Rear Brake disc worn, but not excessively (1.1.14 (a) (i))
- Fail** Offside Front Service brake excessively fluctuating (1.2.1 (e))
- Fail** Nearside Front Suspension arm pin or bush excessively worn Rear bush (5.3.4 (a) (i))
- Advice** Offside Rear Anti-roll bar linkage pin or bush worn but not resulting in excessive movement (5.3.4 (a) (i))
- Advice** Nearside Front Brake pad(s) wearing thin (1.1.13 (a) (ii))
- Advice** Offside Rear Anti-roll bar pin or bush worn but not resulting in excessive movement D bush (5.3.4 (a) (i))

MOT #10 2023-04-13 09:21

MOT test number 673299156655

Result ✔ Passed

MOT #9 2022-03-23 12:35

MOT test number 746393717043

Result ✔ Passed



MOT #8	2021-03-18 09:36
MOT test number	660241411388
Result	✓ Passed
Advice	Nearside Front Upper Suspension arm pin or bush worn but not resulting in excessive movement rearward (5.3.4 (a) (i))
Advice	Offside Front Lower Suspension arm pin or bush worn but not resulting in excessive movement rearward (5.3.4 (a) (i))

MOT #7	2020-03-02 09:50
MOT test number	989615759605
Result	✓ Passed

MOT #6	2019-04-01 09:25
MOT test number	137045887535
Result	✓ Passed
Advice	Nearside Front Suspension arm pin or bush worn but not resulting in excessive movement rearward bush (5.3.4 (a) (i))
Advice	Nearside Front Shock absorbers light misting of oil or has limited damping effect (5.3.2 (b))
Advice	Offside Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))
Advice	Offside Front Suspension arm pin or bush worn but not resulting in excessive movement rearward bush (5.3.4 (a) (i))
Advice	Offside Front Shock absorbers light misting of oil or has limited damping effect (5.3.2 (b))
Advice	Nearside Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))

MOT #5	2018-03-09 13:03
MOT test number	632920715375
Result	✓ Passed

MOT #4	2017-03-28 09:45
MOT test number	856643845616
Result	✓ Passed



MOT #3 2016-03-24 16:09

MOT test number 959332093236

Result ✓ Passed

MOT #2 2015-03-27 11:51

MOT test number 276346285045

Result ✓ Passed

MOT #1 2014-03-25 14:39

MOT test number 659894384028

Result ✓ Passed



Tax & MOT check

✓
Taxed

Tax due:
1 March 2025

✓
MOT

Expires:
15 April 2025

Tax status	Valid until 1 March
Days left	305
MOT expiry date	15 April 2025
Full MOT history	See MOT history

Tax calculation

Vehicle class	49
Band	H
Single payment (12 months)	£ 290,00,-
Single six month payment	£ 159,50,-
Total payable by 12 monthly instalments	£ 304,50,-




Damage history

Check the damage history for this VOLKSWAGEN. See if, where and when this VOLKSWAGEN had damage and the car repair costs. We also check if this VOLKSWAGEN was scrapped. Download the premium report [here](#) for the results.


Damage 1

Date	
Category	
Type	



Damage 2

Date	
Category	
Type	



Extra VOLKSWAGEN salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this VOLKSWAGEN in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,999
Auction value	£ 19,999
Average private trade value	£ 19,999

[More info >](#)



Owner history

For how long did the current and previous owner(s) have this VOLKSWAGEN? How many owners did this VOLKSWAGEN have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

XXXXXXXXXX	XXXXXXXXXX

More info >

Plate changes

See in this check if this VOLKSWAGEN had different number plates.

Number of plates 1

Current registration  **XXXXXX**

Plate since 2024-03-29

Current registration  **XXXXXX**

Plate since 2024-03-29

More info >



Finance check

Check if this VOLKSWAGEN is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this VOLKSWAGEN has been settled.

If not, and you buy this VOLKSWAGEN then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this VOLKSWAGEN is financed.


Finance company	XXXXXXXX XX
Date of agreement	XXXXXXXX XX
Agreement type	XXXXXXXX XX
Agreement term	XXXXXXXX XX
Agreement number	XXXXXXXX XX
Contact info	XXXXXXXX XX

More info >



Mileage check

Odometer	In miles
Mileage registrations	15
First mileage registration	2011-03-30
Last registration	2024-04-16
Complete history	See info



Registration #1	2011-03-30	12 mi
Registration #2	2014-03-25	17.503 mi
Registration #3	2015-03-27	22.787 mi
Registration #4	2016-03-24	27.332 mi
Registration #5	2017-03-28	32.951 mi
Registration #6	2018-03-09	37.044 mi
Registration #7	2019-04-01	41.839 mi
Registration #8	2020-03-02	45.213 mi
Registration #9	2021-03-02	48.587 mi
Registration #10	2022-03-02	51.961 mi
Registration #11	2023-03-02	55.335 mi
Registration #12	2024-03-02	58.709 mi
Registration #13	2024-03-02	62.083 mi
Registration #14	2024-03-02	65.457 mi
Registration #15	2024-03-02	68.831 mi

[More info >](#)



Car features

The VOLKSWAGEN factory car options list is only available in the premium report.

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

View the complete VOLKSWAGEN factory list for this vehicle [here](#).

More info >

Safety ratings

NCAP rating	★★★★★
Adult	87%
Children	79%
Pedestrian	48%
Safety systems	71%
Overall rating	76%
Video	see crash video



Dimensions & weight

Width	1809 mm
Height	1686 mm
Length	4427 mm
Wheel base	2604 mm
Kerb weight	1675 kg

Additional information

Fuel tank capacity	64 l
Fuel delivery	Direct Injection
Number of doors	5
Number of seats	5

Number of axles

2

Engine number

CFF 403844