





report date: 2024-03-28

General information

Make	MINI
Model	MINI COOPER
Colour	Black
Year of manufacture	2013
Top speed	118 mph
0 - 60 mph	10.5 seconds
Gearbox	6 speed Manual

Engine & fuel consumption

Power	122 BHP
Max. torque	160 Nm at 4.250 rpm
Engine capacity	1.598 cc
Cylinders	4
Fuel type	Petrol
Consumption city	38.2 mpg
Consumption extra urban	54.3 mpg
Consumption combined	47.1 mpg
CO2 emission	140 g/km
CO2 lahel	F



CarCheck.co.uk page 1/11



Internet history

Entry 2

Date 2021-09-06

Pictures 2

Listing price <u>View report</u>





source: autotrader.co.uk

Entry 1

Date	2021-06-08
Pictures	14

Listing price <u>View report</u>









source: autotrader.co.uk

CarCheck.co.uk page 2/11



MOT history

MOT expiry date	2024-05-19
MOT pass rate	89 %
MOT passed	8
Failed MOT tests	1
Total advice items	12
Total items failed	2

MOT #9		2023-05-03 09:11
MOT test nu	mber	299422311047
Result		✓ Passed
Next expiry	date	2024-05-19
Advice R	ear tyres have uneven tread wear	
Advice Nearside Front Lower Suspension arm pin or bush worn but not resulting in excessive movement inner rear (5.3.4 (a) (i))		
Advice R	ear Brake pad(s) wearing thin (1.1.13 (a) (ii))	

MOT #8		2023-05-03 09:11
MOT test number		159475327362
Result		★ Failed
Advice Nearside Front Linner rear (5.3.4 (a) (i))	ower Suspension arm pin or bush worn b	ut not resulting in excessive movement
Advice Rear Brake pad(s) wearing thin (1.1.13 (a) (ii))	
Pass with rectification	Nearside Headlamp aim projected beam	n image is obviously incorrect (4.1.2 (c))
Advice Rear tyres have uneven tread wear		
Pass with rectification	Offside Headlamp aim too low (4.1.2 (a)))

MOT #7	2022-05-16 11:51
MOT test number	112915280827
Result	✓ Passed

CarCheck.co.uk page 3/11



MOT test number

Result

Advice Nearside Front Road wheel slightly distorted inner rim (5.2.2 (c) (i))

Advice Nearside Rear Nail in tyre

Advice Front Tyre worn close to legal limit/worn on edge both n/s and o/s (5.2.3 (e))

MOT #5

MOT test number

Result

MOT #4

2019-05-09 12:55

MOT test number

596524639515

Result

Advice Nearside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))

MOT test number

Result

Advice Offside Front tyre slightly worn on the edges

Advice Nearside Front tyre worn on the outer edge.

 MOT #2
 2017-05-18 07:35

 MOT test number
 198611281221

 Result
 ✓ Passed

 MOT #1
 2016-05-23 11:56

 MOT test number
 751231046988

 Result
 ✓ Passed

CarCheck.co.uk page 4/11



Tax & MOT check



Tax status	Valid until 1 June
Days left	33
MOT expiry date	19 May 2024
Full MOT history	See MOT history

Tax calculation

Vehicle class	48
Band	Е
Single payment (12 months)	£ 180,00,-
Single six month payment	£ 99,00,-
Total payable by 12 monthly instalments	£ 189,00,-

CarCheck.co.uk page 5/11



Damage history

Check the damage history for this MINI. See if, where and when this MINI had damage and the car repair costs. We also check if this MINI was scrapped. Download the premium report <u>here</u> for the results.

Damage 1
Date
Category
Type
Damage 2
Date
Category
Type



Extra MINI salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report <u>here</u> for more information.

More info >

CarCheck.co.uk page 6/11



Vehicle valuation

What is this car worth? See the vehicle value of this MINI in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value

Auction value

Average private trade value

More info >

CarCheck.co.uk page 7/11



Owner	hictor.
UMMIAI	nisiaiv

For how long did the current and previous owner(s) have this MINI? How many owners di Check it in the premium report and see all owner registrations. Download the full report		e?

	More info	>
Plate changes		
See in this check if this MINI had different number plates.		
Number of plates		
Current registration	UK UK	
Plate since		
Current registration	UK NE	
Plate since		
	More info	>

CarCheck.co.uk page 8/11



Finance check

Check if this MINI is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this MINI has been settled.

If not, and you buy this MINI then you could lose the money and the car you paid for.

Download the premium report <u>here</u> and check if this MINI is financed.

Finance company	
Date of agreement	
Agreement type	
Agreement term	
Agreement number	
Contact info	

Contact info

More info >

CarCheck.co.uk page 9/11



Mileage check

Odometer	In miles
Mileage registrations	12
First mileage registration	2013-11-01
Last registration	2023-05-03
Complete history	See info



Registration #1	2013-11-01	13 mi
Registration #2	2016-05-23	16.867 mi
Registration #3	2017-05-18	20.926 mi
Registration #4	2018-05-17	25.655 mi
Registration #5	2019-05-09	31.058 mi
Registration #6	2020-05-20	41.059 mi
Registration #7		11.777 es
Registration #8		11.777 es
Registration #9		9.777 es
Registration #10		11.777 es
Registration #11		11.777 es
Registration #12		11.777 es

More info >

CarCheck.co.uk page 10/11



Car features

50225	Air conditioning
50295	
50482	
50501	
50566	
50567	
50569	

Safety ratings

NCAP rating	****
Adult	84%
Children	83%
Pedestrian	63%
Safety systems	71%
Overall rating	78%
Video	see crash video



Dimensions & weight

Width	1789 mm
Height	1561 mm
Length	4097 mm
Wheel base	2595 mm
Max. allowed weight	1735 kg

Additional information

Fuel tank capacity	47
Fuel delivery	Multi-Point Injection
Number of doors	5
Number of axles	2
Engine number CarCheck.co.uk	B202J438 page 11/11