





report date: 2024-03-29

#### General information

Make	CITROEN
Model	C2 LX
Colour	Silver
Year of manufacture	2005
Top speed	98 mph
Gearbox	5 speed Manual

## Engine & fuel consumption

Power	59 BHP
Max. torque	94 Nm at 3.200 rpm
Engine capacity	1.124 cc
Cylinders	4
Fuel type	Petrol
Consumption city	36.7 mpg
Consumption extra urban	58.9 mpg
Consumption combined	48.7 mpg
CO2 emission	138 g/km
CO2 label	E



CarCheck.co.uk page 1/13



## Internet history

#### Entry 1

Date 2022-03-19

Pictures 19

Listing price <u>View report</u>









source: yesauto.com

CarCheck.co.uk page 2/13



MOT history

MOT expiry date	2024-08-07
MOT pass rate	85 %
MOT passed	17
Failed MOT tests	3
Total advice items	6
Total items failed	6

MOT #20	2023-08-02 08:00
MOT test number	819407561713
Result	✓ Passed
Next expiry date	2024-08-07
Advice Offside Front Anti-roll bar linkage ball joint has slight play (5.3.4 (a) (i))	
Advice Offside Side repeater slightly discoloured (4.4.3 (a))	
Advice Nearside Side repeater slightly discoloured (4.4.3 (a))	
Advice Nearside Front Play in steering rack inner joint(s)	

MOT #19	2022-08-08 09:04
MOT test number	393814777115
Result	✓ Passed
MOT #18	2022-08-01 12:59
MOT test number	643417260904
Result	<b>×</b> Failed
Fail Offside Front Inner Suspension arm pin or bush excessively worn (5.3.4 (a) (i))	

MOT #17	2022-03-16 11:29
MOT test number	556703597179
Result	<b>✓</b> Passed

CarCheck.co.uk page 3/13



MOT #16 2022-02-21 10:32

**MOT test number** 855817399333

Result X Failed

Fail Offside Front Windscreen wiper does not clear the windscreen effectively (3.4 (b) (ii))

Advice Offside Front Headlamp has a product on the lens but not seriously reducing light output (4.1.4 (b))

Fail All direction indicators incorrect colour (4.4.3 (a))

Advice Nearside Front Headlamp has a product on the lens but not seriously reducing light output (4.1.4 (b))

Fail Nearside Front Anti-roll bar ball joint excessively worn (5.3.4 (a) (i))

**MOT #15** 2021-03-08 15:19

**MOT test number** 658239725535

**Result** ✓ Passed

**MOT #14** 2020-03-03 13:55

**MOT test number** 854650936994

**MOT #13** 2019-03-11 09:38

**MOT test number** 866061364514

**Result** 
✓ Passed

**MOT #12** 2018-03-08 09:27

MOT test number 887505572850

**MOT #11** 2017-03-07 09:24

**MOT test number** 707829251975

Result \( \sqrt{Passed} \)

CarCheck.co.uk page 4/13



PJ05JYY

. , ,
report date: 2024-03-29

MOT #10		2016-03-07 09:32
MOT test number		104863229933
Result		<b>✓</b> Passed
MOT #9		2015-03-10 09:40
MOT test number		867979265014
Result		✓ Passed
MOT #8		2014-03-03 10:59
MOT test number		168152064478
Result		✓ Passed
MOT #7		2013-03-06 11:13
MOT test number		216395163088
Result		<b>✓</b> Passed
		****
MOT #6		2012-03-05 10:49
MOT test number		176585762405
Result		✓ Passed
MOT #5		2011-03-02 11:06
MOT test number		237621161047
Result		✓ Passed
Result		Viassed
MOT #4		2011-03-02 11:06
MOT test number		108121261060
Result		<b>×</b> Failed
B		
Pass with rectification	Offside Front Headlamp aim too high (1.8)	
Pass with rectification	Nearside Front Headlamp aim too high (1.8)	

CarCheck.co.uk page 5/13



MOT #3	2010-03-04 10:20
MOT test number	923643560086
Result	<b>✓</b> Passed
MOT #2	2009-03-05 12:05
MOT test number	482534669001
Result	<b>✓</b> Passed
MOT #1	2008-03-03 14:29
MOT test number	173173768450
Result	✓ Passed

CarCheck.co.uk page 6/13



## Tax & MOT check



Tax status	Valid until 1 February
Days left	278
MOT expiry date	7 August 2024
Full MOT history	See MOT history

#### Tax calculation

Vehicle class	48
Band	Е
Single payment (12 months)	£ 180,00,-
Single six month payment	£ 99,00,-
Total payable by 12 monthly instalments	£ 189,00,-


CarCheck.co.uk page 7/13



#### Damage history

Check the damage history for this CITROEN. See if, where and when this CITROEN had damage and the car repair costs. We also check if this CITROEN was scrapped. Download the premium report <a href="https://example.com/here">here</a> for the results.

Damage 1
Date
Category
Type
Damage 2
Date
Category
Type



#### Extra CITROEN salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report <u>here</u> for more information.

More info >

CarCheck.co.uk page 8/13



#### Vehicle valuation

What is this car worth? See the vehicle value of this CITROEN in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

**Trade retail value** 

**Auction value** 

Average private trade value

More info >

CarCheck.co.uk page 9/13



## Owner history

For how long did the current and previous owner(s) have this CITROEN? How many owne have? Check it in the premium report and see all owner registrations. Download the full r	
*******	
***************************************	
************	
	More info >
Plate changes	
See in this check if this CITROEN had different number plates.	
Number of plates	,
Current registration	NIK NIK
Plate since	
Current registration	UK UK
Plate since	
	More info >

CarCheck.co.uk page 10/13



#### Finance check

Check if this CITROEN is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this CITROEN has been settled.

If not, and you buy this CITROEN then you could lose the money and the car you paid for.

Download the premium report <u>here</u> and check if this CITROEN is financed.

Finance company	
Date of agreement	
Agreement type	
Agreement term	
Agreement number	
0.1.116	

**Contact info** 

 $\quad \text{More info} \quad > \quad$ 

CarCheck.co.uk page 11/13



## Mileage check

Odometer	In miles
Mileage registrations	21
First mileage registration	2005-04-21
Last registration	2023-08-02
Complete history	See info



Registration #1	2005-04-21	25 mi
Registration #2	2008-03-03	11.141 mi
Registration #3	2009-03-05	14.663 mi
Registration #4	2010-03-04	18.079 mi
Registration #5	2011-03-02	21.089 mi
Registration #6	2012-03-05	24.269 mi
Registration #7	2013-03-06	27.355 mi
Registration #8	2014-03-03	30.332 mi
Registration #9	2015-03-10	33.730 mi
Registration #10	2016-03-07	36.610 mi
Registration #11	2017-03-07	39.044 mi
Registration #12		11.777 es
Registration #13		11.777 es
Registration #14		11.177 es
Registration #15		11.777 es
Registration #16		11.777 es
Registration #17		11.777 es
Registration #18		11.777 es
Registration #19		11.777 es
Registration #20		11.777 es
Registration #21		11.777 ms

More info >

CarCheck.co.uk page 12/13



## Safety ratings

NCAP rating	***
Video	see crash video



# Dimensions & weight

Width	1654 mm
Height	1461 mm
Length	3666 mm
Wheel base	2315 mm
Kerb weight	932 kg
Max. allowed weight	1340 kg

## Additional information

Fuel tank capacity	41
Fuel delivery	Multi-Point Injection
Number of doors	3
Number of seats	4
Number of axles	2
Engine number	FP7P4598891

CarCheck.co.uk page 13/13