



TJA89IR


report date: 2024-03-28

General information

Make	LAND ROVER
Model	RANGE ROVER SPORT SDV6 AUTOBIOGRAPHY DYNAMIC
Colour	Black
Year of manufacture	2015
Top speed	140 mph
0 - 100 km/h	7.2 seconds
Gearbox	8 speed automatic

Engine & fuel consumption

Power	225 kW / 306 HP / 306 BHP
Max. torque	700 Nm at 1.500 rpm
Engine capacity	2.993 cc
Cylinders	6
Fuel type	Diesel
Consumption city	35.8 mpg
Consumption extra urban	44.1 mpg
Consumption combined	40.4 mpg
CO2 emission	185 g/km
CO2 label	I





Internet history

Entry 2

Date	2023-07-12
Pictures	0
Listing price	<a href="#">View report</a>

source: carcraft.co.uk

Entry 1

Date	2021-11-12
Pictures	8
Listing price	<a href="#">View report</a>



source: cargurus.co.uk



## MOT history

MOT expiry date	2025-04-14
MOT pass rate	100 %
MOT passed	7
Failed MOT tests	0
Total advice items	19
Total items failed	0

## MOT #7 2024-04-15 11:57

MOT test number 433564343515

Result ✓ Passed

Next expiry date 2025-04-14

- Advice** Offside Front Outer Road wheel slightly distorted rim (5.2.2 (c) (i))
- Advice** Offside Rear Upper Brake pipe corroded, covered in grease or other material pipe at rear top arm corroded (1.1.11 (c))
- Advice** Offside Front Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))
- Advice** Offside Rear Outer Tyre slightly damaged/cracking or perishing wall sliced (5.2.3 (d) (ii))
- Advice** Rear Oil leak, but not excessive diff (8.4.1 (a) (i))
- Advice** Nearside Rear Upper Brake pipe corroded, covered in grease or other material pipe at rear top arm corroded (1.1.11 (c))
- Advice** Nearside Front Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))
- Advice** Nearside Rear Bumper mountings corroded but not likely to become detached bumper damaged (6.1.4 (a) (i))
- Advice** Nearside Front Inner Brake pad(s) wearing thin (1.1.13 (a) (ii))

## MOT #6 2023-04-11 15:19

MOT test number 545657510163

Result ✓ Passed

- Advice** Under trays fitted

**MOT #5** 2022-04-13 13:53**MOT test number** 527029003550**Result** ✓ Passed**MOT #4** 2021-03-24 13:24**MOT test number** 496142054128**Result** ✓ Passed**MOT #3** 2020-01-29 17:37**MOT test number** 235960979132**Result** ✓ Passed**MOT #2** 2019-01-21 17:39**MOT test number** 577072390794**Result** ✓ Passed**Advice** Oil leak, but not excessive Rear Diff Input Seal Leaking (8.4.1 (a) (i))**Advice** Nearside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))**Advice** Front Brake pad(s) wearing thin (1.1.13 (a) (ii))**Advice** Offside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))**MOT #1** 2018-02-02 14:37**MOT test number** 396443134085**Result** ✓ Passed**Advice** Offside Rear brake disc worn, pitted or scored, but not seriously weakened (3.5.1i)**Advice** Nearside Rear Inner Brake pad(s) wearing thin (3.5.1g)**Advice** Nearside Rear brake disc worn, pitted or scored, but not seriously weakened (3.5.1i)**Advice** Nearside Rear Child Seat fitted not allowing full inspection of adult belt**Advice** Offside Rear Brake pad(s) wearing thin very low (3.5.1g)



Tax & MOT check

✓  
**Taxed**  
**Tax due:**  
1 March 2025

✓  
**MOT**  
**Expires:**  
14 April 2025

<b>Tax status</b>	Valid until 1 March
<b>Days left</b>	307
<b>MOT expiry date</b>	14 April 2025
<b>Full MOT history</b>	<a href="#">See MOT history</a>

Tax calculation

<b>Vehicle class</b>	49
<b>Band</b>	I
<b>Single payment (12 months)</b>	£ 320,00,-
<b>Single six month payment</b>	£ 176,00,-
<b>Total payable by 12 monthly instalments</b>	£ 336,00,-



Damage history

Check the damage history for this LAND ROVER. See if, where and when this LAND ROVER had damage and the car repair costs. We also check if this LAND ROVER was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	



Damage 2

Date	
Category	
Type	



Extra LAND ROVER salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this LAND ROVER in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,999
Auction value	£ 19,999
Average private trade value	£ 19,999

More info >



Owner history

For how long did the current and previous owner(s) have this LAND ROVER? How many owners did this LAND ROVER have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	From	To
Owner	From	To
Owner	From	To
Owner	From	To
Owner	From	To
Owner	From	To
Owner	From	To

More info >

Plate changes

See in this check if this LAND ROVER had different number plates.

Number of plates	1
Current registration	<b>XXXXXX</b>
Plate since	2024-03-28
Current registration	<b>XXXXXX</b>
Plate since	2024-03-28

More info >





Finance check

Check if this LAND ROVER is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this LAND ROVER has been settled.

If not, and you buy this LAND ROVER then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this LAND ROVER is financed.

Finance company	REDACTED	REDACTED
Date of agreement	REDACTED	REDACTED
Agreement type	REDACTED	REDACTED
Agreement term	REDACTED	REDACTED
Agreement number	REDACTED	REDACTED
Contact info	REDACTED	REDACTED

More info >



Mileage check

Odometer	In miles
Mileage registrations	10
First mileage registration	2015-02-04
Last registration	2024-04-15
Complete history	<a href="#">See info</a>



Registration #1	2015-02-04	19 mi
Registration #2	2018-02-02	55.937 mi
Registration #3	2019-01-21	74.349 mi
Registration #4	2020-01-29	90.664 mi
Registration #5	2021-03-24	92.890 mi
Registration #6	2022-05-20	95.277 mi
Registration #7	2023-05-20	95.277 mi
Registration #8	2023-05-20	95.277 mi
Registration #9	2023-05-20	95.277 mi
Registration #10	2024-04-15	95.277 mi

More info >



Safety ratings

NCAP rating	★★★★★
Adult	91%
Children	84%
Pedestrian	63%
Safety systems	86%
Overall rating	84%
Video	<a href="#">see crash video</a>



Dimensions & weight

Width	2220 mm
Height	1801 mm
Length	4856 mm
Wheel base	2923 mm
Kerb weight	2115 kg
Max. allowed weight	3000 kg

Additional information

Fuel tank capacity	89 l
Fuel delivery	Direct Injection
Number of doors	5
Number of seats	5
Number of axles	2
Engine number	0906461306DT