



report date: 2024-03-28

General information

Make	FIAT
Model	BRAVO DYNAMIC 120 MULTIJET
Colour	Silver
Year of manufacture	2007
Top speed	121 mph
Gearbox	5 speed Manual

Engine & fuel consumption

Power	120 BHP
Max. torque	255 Nm at 2.000 rpm
Engine capacity	1.910 cc
Cylinders	4
Fuel type	Diesel
Consumption city	40.9 mpg
Consumption extra urban	65.7 mpg
Consumption combined	53.3 mpg
CO2 emission	139 g/km
CO2 label	E






Internet history

Entry 3



Date	2021-06-26
Pictures	14
Listing price	View report



source: [autotrader.co.uk](#)

Entry 2



Date	2021-06-14
Pictures	5
Listing price	View report



source: [autotrader.co.uk](#)

Entry 1

Date	2021-05-23
Pictures	4
Listing price	View report



source: [autotrader.co.uk](#)



MOT history

MOT expiry date	2021-11-01
MOT pass rate	65 %
MOT passed	11
Failed MOT tests	6
Total advice items	32
Total items failed	17

MOT #17	2020-11-02 15:54
MOT test number	850910309470
Result	✓ Passed
Next expiry date	2021-11-01
Advice	Nearside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))
Advice	Front Tyre worn close to legal limit/worn on edge Both wearing on inner edges (5.2.3 (e))

MOT #16	2020-11-02 10:50
MOT test number	750763097293
Result	✗ Failed
Advice	Nearside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))
Fail	Offside Headlamp aim projected beam image is obviously incorrect (4.1.2 (c))
Fail	Offside Front Service brake lagging in operation (1.2.1 (d))
Advice	Front Tyre worn close to legal limit/worn on edge Both wearing on inner edges (5.2.3 (e))
Fail	Nearside Rear Hydraulic brake calliper leaking (1.1.16 (b) (i))

MOT #15	2019-10-24 09:54
MOT test number	195123662975
Result	✓ Passed
Advice	Nearside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))

**MOT #14** 2019-10-14 10:38**MOT test number** 882252651872**Result** ✗ Failed**Advice** Nearside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))**Fail** Offside Front Coil spring fractured or broken (5.3.1 (b) (i))**Fail** Offside Track rod end ball joint has excessive play (2.1.3 (b) (i))**Fail** Offside Front Headlamp aim projected beam image is obviously incorrect (4.1.2 (c))**Fail** Offside Front Suspension arm ball joint excessively worn (5.3.4 (a) (i))**MOT #13** 2018-10-03 10:00**MOT test number** 423719584568**Result** ✓ Passed**Advice** Front Brake disc worn, but not excessively (1.1.14 (a) (i))**MOT #12** 2017-10-19 13:46**MOT test number** 552927540067**Result** ✓ Passed**Advice** Offside Front Tyre worn close to the legal limit (4.1.E.1)**Advice** Nearside Front Tyre worn close to the legal limit (4.1.E.1)**MOT #11** 2016-10-26 14:07**MOT test number** 749784949021**Result** ✓ Passed**Advice** Exhaust back box outer skin split**Advice** Child Seat fitted not allowing full inspection of adult belt

**MOT #10**

2016-10-20 14:06

MOT test number

979532966754

Result**✗ Failed****Fail**

Offside Headlamp does not operate immediately when selected on dipped beam main beam stuck on (1.7.4a)

Fail

Nearside Headlamp does not operate immediately when selected on dipped beam main beam stuck on (1.7.4a)

Advice

Exhaust back box outer skin split

Advice

Child Seat fitted not allowing full inspection of adult belt

MOT #9

2015-10-15 10:06

MOT test number

302839925115

Result**✓ Passed****Advice**

Exhaust back box in poor condition

MOT #8

2014-10-17 14:02

MOT test number

656620994254

Result**✓ Passed****Advice**

Offside Front Tyre worn close to the legal limit (4.1.E.1)

Notice

Child seat fitted not allowing full inspection of adult belt

MOT #7

2013-10-28 13:10

MOT test number

688121303303

Result**✓ Passed****Notice**

Offside rear tyre is cracking on the side walls

Advice

Offside Front Tyre worn close to the legal limit (4.1.E.1)

Notice

Back box shell is corroded

Advice

Offside Rear Tyre worn close to the legal limit (4.1.E.1)

**MOT #6**

2013-10-25 12:06

MOT test number

379858893475

Result**✗ Failed**

- Notice** Offside rear tyre is cracking on the side walls
- Fail** Nearside Front Tyre tread depth below requirements of 1.6mm (4.1.E.1)
- Advice** Offside Front Tyre worn close to the legal limit (4.1.E.1)
- Notice** Back box shell is corroded
- Fail** Offside Side repeater insecure (1.4.A.2b)
- Advice** Offside Rear Tyre worn close to the legal limit (4.1.E.1)

MOT #5

2012-10-08 17:21

MOT test number

886432482229

Result**✓ Passed****MOT #4**

2012-10-08 14:17

MOT test number

218992182275

Result**✗ Failed**

- Fail** Nearside Front Track rod end ball joint has excessive play (2.2.B.1f)
- Pass with rectification** Nearside Headlamp aim too high (1.8)
- Advice** Rear Brake pad(s) wearing thin (3.5.1g)
- Fail** Nearside Rear Registration plate lamp not working (1.1.C.1d)
- Pass with rectification** Offside Headlamp aim too high (1.8)

**MOT #3** 2011-10-05 14:04**MOT test number** 709328671285**Result** ✓ Passed**Notice** Front discs corroded**Advice** Offside Front Tyre worn close to the legal limit (4.1.E.1)**Notice** Child seat fitted not allowing full inspection of adult belt**MOT #2** 2011-10-05 10:04**MOT test number** 728638471219**Result** ✗ Failed**Advice** Offside Rear Tyre worn close to the legal limit (4.1.E.1)**Fail** Windscreen washer provides insufficient washer liquid (8.2.3)**Notice** Front discs corroded**Advice** Offside Front Tyre worn close to the legal limit (4.1.E.1)**Fail** Offside Rear Tyre has a cut in excess of the requirements deep enough to reach the ply or cords (4.1.D.1a)**Notice** Child seat fitted not allowing full inspection of adult belt**MOT #1** 2010-09-20 15:07**MOT test number** 643053560215**Result** ✓ Passed



Tax & MOT check

✕
Untaxed

Tax expired:
30 September 2021

✕
MOT

Expired:
1 November 2021

Tax status	Expired at 30 September
Days left	941 days too late
MOT expiry date	1 November 2021
Full MOT history	See MOT history

Tax calculation


Vehicle class	49
Band	E
Single payment (12 months)	£ 180,00,-
Single six month payment	£ 99,00,-
Total payable by 12 monthly instalments	£ 189,00,-



Damage history

Check the damage history for this FIAT. See if, where and when this FIAT had damage and the car repair costs. We also check if this FIAT was scrapped. Download the premium report [here](#) for the results.

Damage 1	
Date	
Category	
Type	
Damage 2	
Date	
Category	
Type	



Extra FIAT salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this FIAT in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,999
Auction value	£ 19,999
Average private trade value	£ 19,999

More info >



Owner history

For how long did the current and previous owner(s) have this FIAT? How many owners did this FIAT have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	Period
Owner	Period
Owner	Period
Owner	Period
Owner	Period
Owner	Period
Owner	Period

More info >

Plate changes

See in this check if this FIAT had different number plates.

Number of plates	1
Current registration	
Plate since	2019-09-28
Current registration	
Plate since	2019-09-28

More info >



Finance check

Check if this FIAT is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this FIAT has been settled.

If not, and you buy this FIAT then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this FIAT is financed.


Finance company	REDACTED	REDACTED
Date of agreement	REDACTED	REDACTED
Agreement type	REDACTED	REDACTED
Agreement term	REDACTED	REDACTED
Agreement number	REDACTED	REDACTED
Contact info	REDACTED	REDACTED

More info >



Mileage check

Odometer	In miles
Mileage registrations	21
First mileage registration	2007-09-24
Last registration	2020-11-02
Complete history	See info



Registration #1	2007-09-24	21 mi
Registration #2	2010-09-20	28.151 mi
Registration #3	2011-10-05	41.339 mi
Registration #4	2011-10-05	41.385 mi
Registration #5	2012-10-08	59.459 mi
Registration #6	2012-10-08	59.459 mi
Registration #7	2013-10-25	73.459 mi
Registration #8	2013-10-28	73.462 mi
Registration #9	2014-10-17	77.130 mi
Registration #10	2015-10-15	80.929 mi
Registration #11	2016-10-20	84.808 mi
Registration #12	2017-10-20	85.377 mi
Registration #13	2018-10-20	85.377 mi
Registration #14	2019-10-20	85.377 mi
Registration #15	2020-11-02	85.377 mi
Registration #16	2020-11-02	85.377 mi
Registration #17	2020-11-02	85.377 mi
Registration #18	2020-11-02	85.377 mi
Registration #19	2020-11-02	85.377 mi
Registration #20	2020-11-02	85.377 mi
Registration #21	2020-11-02	85.377 mi

More info >



Car features

The FIAT factory car options list is only available in the premium report.

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

View the complete FIAT factory list for this vehicle [here](#).

More info >

Safety ratings

NCAP rating	★★★★★
Video	see crash video



Dimensions & weight

Width	1792 mm
Height	1498 mm
Length	4336 mm
Wheel base	2600 mm
Kerb weight	1320 kg
Max. allowed weight	1830 kg

Additional information

Fuel tank capacity	58 l
Fuel delivery	Direct Injection
Number of doors	5
Number of seats	5

Number of axles	2
Engine number	5594642