



report date: 2024-03-28

General information

Make	CITROEN
Model	DS5 HDI VTR PLUS PICASSO
Colour	Silver
Year of manufacture	2013
Top speed	108 mph
0 - 60 mph	13.5 seconds
Gearbox	5 speed Manual

Engine & fuel consumption

Power	91 BHP
Max. torque	312 Nm at 1.750 rpm
Engine capacity	1.560 cc
Cylinders	4
Fuel type	Diesel
Consumption city	60.1 mpg
Consumption extra urban	76.4 mpg
Consumption combined	68.9 mpg
CO2 emission	112 g/km
CO2 label	C






Internet history

Entry 1

Date	2021-06-29
Pictures	6
Listing price	View report



source: [cargurus.co.uk](https://www.cargurus.co.uk)

**MOT history**

MOT expiry date	2024-08-22
MOT pass rate	73 %
MOT passed	8
Failed MOT tests	3
Total advice items	43
Total items failed	1

MOT #11 2023-08-23 09:57**MOT test number** 793145258305**Result** Passed**Next expiry date** 2024-08-22**Advice** Nearside Front Suspension arm ball joint has slight play (5.3.4 (a) (i))**Minor** Nearside Registration plate lamp inoperative in the case of multiple lamps or light sources (4.7.1 (b) (i))**Advice** Offside Front Road wheel slightly distorted (5.2.2 (c) (i))**Minor** Windscreen damaged but not adversely affecting driver's view (3.2 (a) (i))**Advice** Nearside Front Road wheel slightly distorted (5.2.2 (c) (i))**MOT #10** 2023-08-15 14:21**MOT test number** 769798699688**Result** Passed**Minor** Windscreen damaged but not adversely affecting driver's view (3.2 (a) (i))**Advice** Rear brake discs corroded**Advice** Nearside Front Inner Road wheel slightly distorted (5.2.2 (c) (i))**Minor** Nearside Registration plate lamp inoperative in the case of multiple lamps or light sources (4.7.1 (b) (i))**Advice** Offside Front Inner Road wheel slightly distorted (5.2.2 (c) (i))

**MOT #9**

2023-08-09 10:35

MOT test number

620723101121

Result**✗ Failed**

MAJOR Offside Front Outer Drive shaft joint constant velocity boot split or insecure, no longer prevents the ingress of dirt -insecure (6.1.7 (g) (ii))

Advice Nearside Front Inner Road wheel slightly distorted (5.2.2 (c) (i))

MAJOR Nearside Front Seat belt buckle not functioning as intended (7.1.2 (d))

Minor Nearside Registration plate lamp inoperative in the case of multiple lamps or light sources (4.7.1 (b) (i))

Advice Rear brake discs corroded

Advice Offside Front Inner Road wheel slightly distorted (5.2.2 (c) (i))

DANGEROUS Nearside Rear Brake pad(s) less than 1.5 mm thick (1.1.13 (a) (ii))

Minor Windscreen damaged but not adversely affecting driver's view (3.2 (a) (i))

MOT #8

2022-08-15 13:28

MOT test number

690055035858

Result**✓ Passed**

Advice Rear Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))

Advice Brake pedal rubber missing but pedal has grooves

Advice Child Seat fitted not allowing full inspection of adult belt

Advice Offside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))

Minor Registration plate lamp inoperative in the case of multiple lamps or light sources (4.7.1 (b) (i))

Advice Child Seat fitted not allowing full inspection of adult belt

Advice Rear Brake pad(s) wearing thin (1.1.13 (a) (ii))

Minor Windscreen damaged but not adversely affecting driver's view borderline (3.2 (a) (i))

**MOT #7** 2022-08-10 14:54**MOT test number** 404264670678**Result** ✗ Failed**Advice** Rear Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))**MAJOR** Offside Front Outer Drive shaft joint constant velocity boot split or insecure, no longer prevents the ingress of dirt (6.1.7 (g) (ii))**Minor** Registration plate lamp inoperative in the case of multiple lamps or light sources (4.7.1 (b) (i))**DANGEROUS** Nearside Front Tyre has a lump, caused by separation or partial failure of its structure (5.2.3 (d) (ii))**Advice** Child Seat fitted not allowing full inspection of adult belt**MAJOR** Nearside Front Headlamp aim projected beam image is obviously incorrect (4.1.2 (c))**Advice** Offside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))**Advice** Brake pedal rubber missing but pedal has grooves**Minor** Windscreen damaged but not adversely affecting driver's view borderline (3.2 (a) (i))**Advice** Rear Brake pad(s) wearing thin (1.1.13 (a) (ii))**MAJOR** Nearside Front Tyre not fitted in accordance with side wall instructions (5.2.3 (i))**Advice** Nearside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))**Advice** Child Seat fitted not allowing full inspection of adult belt**MAJOR** Parking brake efficiency below requirements (1.4.2 (a) (i))**MOT #6** 2021-08-12 09:02**MOT test number** 505357738540**Result** ✓ Passed**Minor** Nearside Registration plate lamp inoperative in the case of multiple lamps or light sources (4.7.1 (b) (i))

**MOT #5** 2020-10-16 15:43**MOT test number** 941635510237**Result** ✓ Passed**Minor** Nearside Registration plate lamp inoperative in the case of multiple lamps or light sources (4.7.1 (b) (i))**MOT #4** 2019-04-26 12:34**MOT test number** 603297024272**Result** ✓ Passed**Advice** Tyre worn close to legal limit/worn on edge all four (5.2.3 (e))**MOT #3** 2018-05-03 08:33**MOT test number** 637570327594**Result** ✓ Passed**MOT #2** 2018-05-01 15:38**MOT test number** 418862728468**Result** ✗ Failed**Fail** Parking brake: efficiency below requirements (3.7.B.7)**MOT #1** 2016-09-27 16:15**MOT test number** 468072831777**Result** ✓ Passed



Tax & MOT check

✓
Taxed
Tax due:
1 September 2024

✓
MOT
Expires:
22 August 2024

Tax status	Valid until 1 September
Days left	125
MOT expiry date	22 August 2024
Full MOT history	See MOT history

Tax calculation

Vehicle class	49
Band	C
Single payment (12 months)	£ 35,00,-
Single six month payment	Not applicable
Total payable by 12 monthly instalments	£ 36,75,-



Damage history

Check the damage history for this CITROEN. See if, where and when this CITROEN had damage and the car repair costs. We also check if this CITROEN was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	

Damage 2

Date	
Category	
Type	



Extra CITROEN salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this CITROEN in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 10,000
Auction value	£ 10,000
Average private trade value	£ 10,000

More info >



Owner history

For how long did the current and previous owner(s) have this CITROEN? How many owners did this CITROEN have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration

More info >

Plate changes

See in this check if this CITROEN had different number plates.

Number of plates	1
Current registration	
Plate since	2024-03-28
Current registration	
Plate since	2024-03-28

More info >



Finance check

Check if this CITROEN is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this CITROEN has been settled.

If not, and you buy this CITROEN then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this CITROEN is financed.

Finance company	XXXXXXXX	XXXX
Date of agreement	XXXXXXXX	XXXX
Agreement type	XXXXXXXX	XXXX
Agreement term	XXXXXXXX	XXXX
Agreement number	XXXXXXXX	XXXX
Contact info	XXXXXXXX	XXXX

More info >



Mileage check

Odometer	In miles
Mileage registrations	13
First mileage registration	2013-09-23
Last registration	2023-08-23
Complete history	See info



Registration #1	2013-09-23	9 mi
Registration #2	2016-09-27	19.569 mi
Registration #3	2018-05-01	19.791 mi
Registration #4	2018-05-03	19.799 mi
Registration #5	2019-04-26	43.540 mi
Registration #6	2020-10-16	54.687 mi
Registration #7	2023-08-23	55.277 mi
Registration #8	2023-08-23	55.277 mi
Registration #9	2023-08-23	55.277 mi
Registration #10	2023-08-23	55.277 mi
Registration #11	2023-08-23	55.277 mi
Registration #12	2023-08-23	55.277 mi
Registration #13	2023-08-23	55.277 mi

More info >



Safety ratings

NCAP rating	★★★★☆
Adult	83%
Children	74%
Pedestrian	33%
Safety systems	40%
Overall rating	67%
Video	see crash video



Dimensions & weight

Width	1766 mm
Height	1631 mm
Length	4078 mm
Wheel base	2540 mm
Kerb weight	1404 kg
Max. allowed weight	1779 kg

Additional information

Fuel delivery	Direct Injection
Number of doors	5
Number of seats	5
Number of axles	2
Engine number	JBFM3035866