





report date: 2024-03-28

## General information

| Make                | VAUXHALL       |
|---------------------|----------------|
| Model               | VIVA SL        |
| Colour              | Grey           |
| Year of manufacture | 2017           |
| Top speed           | 106 mph        |
| 0 - 60 mph          | 13.1 seconds   |
| Gearbox             | 5 speed Manual |

## Engine & fuel consumption

| Power                   | 74 BHP             |
|-------------------------|--------------------|
| Max. torque             | 95 Nm at 4.500 rpm |
| Engine capacity         | 999 сс             |
| Cylinders               | 3                  |
| Fuel type               | Petrol             |
| Consumption city        | 50.4 mpg           |
| Consumption extra urban | 72.4 mpg           |
| Consumption combined    | 62.8 mpg           |
| CO2 emission            | 104 g/km           |
| CO2 label               | В                  |



CarCheck.co.uk page 1/11



## Internet history

## Entry 2

Date 2021-07-25

Pictures 14

Listing price <u>View report</u>









source: yesauto.com

Entry 1

Date 2021-07-23

Pictures 15

Listing price <u>View report</u>









source: autotrader.co.uk

CarCheck.co.uk page 2/11



# MOT history

| MOT expiry date    | 2024-07-20 |
|--------------------|------------|
| MOT pass rate      | 80 %       |
| MOT passed         | 4          |
| Failed MOT tests   | 1          |
| Total advice items | 4          |
| Total items failed | 1          |

| MOT #5    |  | 2023-07-14 13:00 |
|-----------|--|------------------|
| MOT test  | number   | 303600603500     |
| Result    |  | ✓ Passed         |
| Next expi | ry date  | 2024-07-20       |
| Advice    | Offside Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))  |                  |
| Advice    | Nearside Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii)) |                  |

| MOT #4          | 2022-07-21 11:53 |
|-----------------|------------------|
| MOT test number | 539974518519     |
| Result          | ✓ Passed         |

| Result   |  | ✓ Passed         |
|----------|--|------------------|
|          |  |                  |
| MOT #3   |  | 2021-07-21 11:17 |
| MOT test | number   | 170819101228     |
| Result   |  | ✓ Passed         |
| Advice   | Offside Front Tyre worn close to legal limit/worn on edge worn on inner ed | ge (5.2.3 (e))   |
| Advice   | Nearside Front Tyre worn close to legal limit/worn on edge worn on edges   | (5.2.3 (e))      |

| MOT #2          | 2020-06-16 13:28 |
|-----------------|------------------|
| MOT test number | 849565698721     |
| Result          | <b>✓</b> Passed  |

CarCheck.co.uk page 3/11



MOT #1 2020-06-16 13:28

**MOT test number** 426497475741

Result X Failed

**Pass with rectification** 

Windscreen wiper does not clear the windscreen effectively (3.4 (b) (ii))

CarCheck.co.uk page 4/11



# Tax & MOT check



| Tax status       | Valid until 1 July |
|------------------|--------------------|
| Days left        | 63                 |
| MOT expiry date  | 20 July 2024       |
| Full MOT history | See MOT history    |

# Tax calculation

| Vehicle class                 | 48         |
|-------------------------------|------------|
| Band                          | F          |
| First licence fee (12 months) | £ 185,00,- |
| Standard rate (12 months)     | £ 180,00,- |
| Standard rate (6 months)      | £ 99,00,-  |
| Premium rate (12 months)      | £ 570,00,- |
| Premium rate (6 months)       | £ 313,50,- |
|                               |            |

CarCheck.co.uk page 5/11



### Damage history

Check the damage history for this VAUXHALL. See if, where and when this VAUXHALL had damage and the car repair costs. We also check if this VAUXHALL was scrapped. Download the premium report <u>here</u> for the results.

#### Damage 1

| Date     |  |
|----------|--|
| Category |  |
| Туре     |  |

#### Damage 2

| Date     |  |
|----------|--|
| Category |  |

**Type** 



#### Extra VAUXHALL salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report <u>here</u> for more information.

More info >

CarCheck.co.uk page 6/11



### Vehicle valuation

What is this car worth? See the vehicle value of this VAUXHALL in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

**Trade retail value** 

**Auction value** 

Average private trade value

More info >

CarCheck.co.uk page 7/11



More info >

## Owner history

| For how long did the current and previous owner(s) have this VAUXHALL? How many own VAUXHALL have? Check it in the premium report and see all owner registrations. Downloaner. |             |
|--|-------------|
| ***********  |             |
| ***************************************  |             |
| ***************************************  |             |
|  |             |
|  |             |
|  |             |
| ***************************************  |             |
|  | More info > |
| Plate changes  |             |
| See in this check if this VAUXHALL had different number plates.  |             |
| Number of plates   |             |
| Current registration   | NK NK       |
| Plate since  |             |
| Current registration   | SK UK       |
| Plate since  |             |

CarCheck.co.uk page 8/11



### Finance check

Check if this VAUXHALL is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this VAUXHALL has been settled.

If not, and you buy this VAUXHALL then you could lose the money and the car you paid for.

Download the premium report <u>here</u> and check if this VAUXHALL is financed.

| Finance company   |  |
|-------------------|--|
| Date of agreement |  |
| Agreement type    |  |
| Agreement term    |  |
| Agreement number  |  |
|                   |  |

**Contact info** 

More info >

CarCheck.co.uk page 9/11



# Mileage check

| Odometer                   | In miles   |
|----------------------------|------------|
| Mileage registrations      | 8          |
| First mileage registration | 2017-06-30 |
| Last registration          | 2023-07-14 |
| Complete history           | See info   |



| Registration #1 | 2017-06-30 | 14 mi     |
|-----------------|------------|-----------|
| Registration #2 | 2020-06-16 | 23.519 mi |
| Registration #3 | 2020-06-16 | 23.519 mi |
| Registration #4 | 2021-07-21 | 33.507 mi |
| Registration #5 |            | 11.777 es |
| Registration #6 |            | 11.777 es |
| Registration #7 |            | 11.777 es |
| Registration #8 |            | 11.777 es |

More info >

CarCheck.co.uk page 10/11



# Safety ratings

| NCAP rating    | ***             |
|----------------|-----------------|
| Adult          | 52%             |
| Children       | 91%             |
| Pedestrian     | 53%             |
| Safety systems | 57%             |
| Overall rating | 61%             |
| Video          | see crash video |



# Dimensions & weight

| Width               | 1876 mm |
|---------------------|---------|
| Height              | 1485 mm |
| Length              | 3675 mm |
| Wheel base          | 2385 mm |
| Kerb weight         | 864 kg  |
| Max. allowed weight | 1353 kg |

# Additional information

| Fuel tank capacity | 32 I                  |
|--------------------|-----------------------|
| Fuel delivery      | Multi-Point Injection |
| Number of doors    | 5                     |
| Number of seats    | 5                     |
| Number of axles    | 2                     |
| Engine number      | L5Q 163080842L5Q      |

CarCheck.co.uk page 11/11