





### General information

Make	ΤΟΥΟΤΑ
Model	VERSO VALVEMATIC TR
Colour	Black
Year of manufacture	2009
Top speed	115 mph
0 - 60 mph	11.1 seconds
Gearbox	7 speed CVT

## Engine & fuel consumption

Power	145 BHP
Max. torque	180 Nm at 4.000 rpm
Engine capacity	1.798 cc
Cylinders	4
Fuel type	Petrol
Consumption city	32.5 mpg
Consumption extra urban	47.9 mpg
Consumption combined	40.4 mpg
CO2 emission	165 g/km
CO2 label	G







### Internet history

Entry 1

Date Pictures 2021-10-22

12

Listing price

View report



source: cargurus.co.uk



## MOT history

MOT expiry date	2024-12-13
MOT pass rate	72 %
MOT passed	13
Failed MOT tests	5
Total advice items	22
Total items failed	3

MOT #18	2023-12-08 14:25
MOT test number	812295300316
Result	✓ Passed
Next expiry date	2024-12-13

MOT #17		2023-12-08 09:00
MOT test	number	565243731767
Result		🗙 Failed
MAJOR	Offside Rear Coil spring fractured or broken (5.3.1 (b) (i))	

MOT #16	2022-12-12 17:05
MOT test number	134236372735
Result	✓ Passed

MOT #15		2022-12-12 12:16
MOT test numbe	er	282731341706
Result		🗙 Failed
DANGEROUS	Offside Front Tyre has ply or cords exposed (5.2.3 (d) (ii))	
DANGEROUS	Nearside Front Tyre tread depth below requirements of 1.6mm (5.2.3 (e))	
DANGEROUS	Offside Rear Tyre tread depth below requirements of 1.6mm (5.2.3 (e))	



P	0	5	9)	K	G	Ν
	repo	rt c	late:	20	24-0	)3-28

MOT #14	2021-12-14 13:18
MOT test number	942377642776
Result	✓ Passed
MOT #13	2021-05-21 11:11
MOTION	217/2002/200

MOT test number	217439634368
Result	✓ Passed
Advice Rear Brake disc worn, but not excessively (both) (1.1.14 (a) (i))	
Advice Front Brake disc worn, but not excessively (both) (1.1.14 (a) (i))	

MOT #12	2019-12-09 17:19
MOT test number	717352729649
Result	✓ Passed

Advice Vehicle underside corroded

MOT #11	2019-12-05 10:04
MOT test ı	number 155989898338
Result	× Failed
<b>MAJOR</b> (3.2 (c) (i))	Nearside Front Window in an unacceptable condition glass broken inside vehicle could cause injury
MAJOR	Nearside Front Windscreen wiper does not clear the windscreen effectively (3.4 (b) (ii))
Advice	Vehicle underside corroded
MAJOR	Horn not working (7.7 (a) (ii))
MAJOR	Nearside Rear Position lamp not working (4.2.1 (a) (ii))
DANGER	OUS Undertray likely to become detached (6.2.1 (a) (ii))
MAJOR	Engine MIL inoperative or indicates a malfunction (8.2.1.2 (h))





MOT #10	2018-07-07 13:13
MOT test number	942473580374
Result	✓ Passed
МОТ #9	2017-08-18 15:06
MOT test number	647641657143
Result	✓ Passed
MOT #8	2017-08-18 08:16

MOT #8	2017-08-18 08:16
MOT test number	575306341475
Result	🗙 Failed
Advice Offside Front Tyre worn close to the legal limit 205/60R16 (4.1.E.1)	
<b>Fail</b> Front Brake pad(s) less than 1.5 mm thick (3.5.1g)	
Advice Nearside Front Tyre worn close to the legal limit 205/60R16 (4.1.E.1)	
Advice Rear brake disc worn, pitted or scored, but not seriously weakened (3.5.1i)	

MOT #7		2016-09-02 09:00
MOT test	number	430008810079
Result		✓ Passed
Advice	Nearside Rear brake disc worn, pitted or scored, but not seriously weakened (	(3.5.1i)
Advice	N/s/r tyre outer wall perished	
Advice Offside Rear brake disc worn, pitted or scored, but not seriously weakened (3.5.1i)		

MOT #6	2015-08-03 16:35
MOT test number	933367453221
Result	✓ Passed
Advice Front Brake pad(s) wearing thin (3.5.1g)	





MOT #5	2014-08-12 11:10
MOT test number	365344824243
Result	✓ Passed
MOT #4	2014-08-12 09:34
MOT test number	788604124279
Result	🗙 Failed
Fail Offside Front Tyre tread depth below requirements of 1.6mm (4.1.E.1)	
Fail Nearside Front Tyre tread depth below requirements of 1.6mm (4.1.E.1)	
MOT #3	2013-08-20 11:44
MOT test number	408862133218
Result	🗸 Passed

MOT #2	2013-01-12 09:44
MOT test number	687702813048
Result	✓ Passed
Notice Slight wear /pitting rear brake discs	

MOT #1	2012-08-30 10:36
MOT test number	309783442406
Result	✓ Passed



Tax & MOT check

✓ Taxed	✓ MOT Expires:
1 December 2024 Tax status	13 December 2024 Valid until 1 December
Days left	217
MOT expiry date	13 December 2024
Full MOT history	See MOT history

## Tax calculation

Vehicle class	48
Band	G
Single payment (12 months)	£ 240,00,-
Single six month payment	£ 132,00,-
Total payable by 12 monthly instalments	£ 252,00,-





#### Damage history

Check the damage history for this TOYOTA. See if, where and when this TOYOTA had damage and the car repair costs. We also check if this TOYOTA was scrapped. Download the premium report <u>here</u> for the results.

Damage 1	
Date	
Category	 Lamp
Туре	K K K K K K K K K K K K K K K K K K K
Damage 2	AMPLE
Damage 2	
Date	 *
Category	 amer
Туре	

#### Extra TOYOTA salvage check

If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report <u>here</u> for more information.





#### Vehicle valuation

What is this car worth? See the vehicle value of this TOYOTA in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	6 10.200
Auction value	4 10.000
Average private trade value	4 11 200





### Owner history

For how long did the current and previous owner(s) have this TOYOTA? How many owners did this TOYOTA have? Check it in the premium report and see all owner registrations. Download the full report <u>here</u>.

ana	
***********	
*******	
******	
***********	
*******	
	More info >
Plate changes	
See in this check if this TOYOTA had different number plates.	
Number of plates	,
Current registration	
Plate since	
Current registration	
Plate since	





#### Finance check

Check if this TOYOTA is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this TOYOTA has been settled.

If not, and you buy this TOYOTA then you could lose the money and the car you paid for.

Download the premium report <u>here</u> and check if this TOYOTA is financed.

Finance company	
Date of agreement	
Agreement type	
Agreement term	
Agreement number	
Contact info	





## Mileage check

Odometer	In miles
Mileage registrations	20
First mileage registration	2009-09-02
Last registration	2023-12-08
Complete history	See info



Registration #1	2009-09-02	13 mi
Registration #2	2012-08-30	13.447 mi
Registration #3	2013-01-12	14.188 mi
Registration #4	2013-08-20	18.174 mi
Registration #5	2014-08-12	24.432 mi
Registration #6	2014-08-12	24.436 mi
Registration #7	2015-08-03	30.025 mi
Registration #8	2016-09-02	36.192 mi
Registration #9	2017-08-18	41.803 mi
Registration #10	2017-08-18	41.803 mi
Registration #11		11.777 mi
Registration #12		11.777 esi
Registration #13		11.777 mi
Registration #14		11.777 esi
Registration #15		11.777 mi
Registration #16		11.777 esi
Registration #17		11.777 mi
Registration #18		01.777 mi
Registration #19		11.777 mi
Registration #20		11.117 mi





### Car features

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

# Safety ratings

Number of axles

**NCAP** rating

Video

see crash video



Dimensions & weight				
Width	1790 mm			
Height	1620 mm			
Length	4440 mm			
Wheel base	2780 mm			
Kerb weight	1525 kg			
Max. allowed weight	2125 kg			
Additional information				
Fuel delivery	Multi-Point Injection			
Number of doors	5			
Number of seats	7			

2