



report date: 2024-03-28

General information

Make	FIAT
Model	500C S
Colour	Purple
Year of manufacture	2014
Top speed	99 mph
0 - 60 mph	12.9 seconds
Gearbox	5 speed Manual

Engine & fuel consumption

Power	69 BHP
Max. torque	102 Nm at 6.000 rpm
Engine capacity	1.242 cc
Cylinders	4
Fuel type	Petrol
Consumption city	49.6 mpg
Consumption extra urban	65.7 mpg
Consumption combined	58.9 mpg
CO2 emission	113 g/km
CO2 label	C





Internet history

Entry 1

Date	2021-12-19
Pictures	13
Listing price	View report



source: [autotrader.co.uk](https://www.autotrader.co.uk)



MOT history

MOT expiry date	2025-01-15
MOT pass rate	67 %
MOT passed	8
Failed MOT tests	4
Total advice items	28
Total items failed	4

MOT #12	2023-12-18 09:28
MOT test number	134338704283
Result	✓ Passed
Next expiry date	2025-01-15
Advice	Offside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))
Advice	Offside Front Shock absorbers has light misting of oil (5.3.2 (b))

MOT #11	2023-01-16 17:05
MOT test number	996434519079
Result	✓ Passed
Advice	Nearside Front Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))
Advice	Nearside Rear Parking brake efficiency only just met. It would appear that the braking system requires adjustment or repair. (1.4.2 (a) (i))
Advice	Nearside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))
Advice	Offside Front Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))
Advice	Front Service brake fluctuating, but not excessively (1.2.1 (e))

**MOT #10** 2022-01-12 09:00**MOT test number** 738915952742**Result** ✓ Passed

- Advice** Offside Rear Shock absorbers has a slightly worn bush (5.3.2 (c))
- Advice** Nearside Front Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))
- Advice** Offside Front Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))

MOT #9 2022-01-11 16:47**MOT test number** 563298670798**Result** ✗ Failed

- Advice** Rear Exhaust mounting defective (6.1.2 (a))
- Advice** Offside Front Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))
- Advice** Offside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))
- Advice** Nearside Front Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))
- Advice** Offside Rear Shock absorbers has a slightly worn bush (5.3.2 (c))
- Advice** Nearside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))
- Fail** Nearside Front Lower Suspension arm ball joint likely to become detached incorrect ball joint securing device used (5.3.4 (a) (ii))

MOT #8 2021-11-25 08:42**MOT test number** 800737286818**Result** ✓ Passed

- Advice** Offside Rear Hydraulic brake cylinder corroded but not seriously weakened (1.1.16 (d) (i))

**MOT #7** 2021-11-15 13:51**MOT test number** 243266365869**Result** ✗ Failed**Advice** Offside Rear Hydraulic brake cylinder corroded but not seriously weakened (1.1.16 (d) (i))**Fail** Parking brake efficiency below requirements (1.4.2 (a) (i))**MOT #6** 2020-11-10 12:07**MOT test number** 235050613830**Result** ✓ Passed**Advice** Front oil sump corroded**Advice** Nearside Front Lower Suspension arm ball joint has slight play (5.3.4 (a) (i))**MOT #5** 2019-11-05 14:23**MOT test number** 230132697768**Result** ✓ Passed**Advice** Offside Front Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))**Advice** Nearside Front Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))**MOT #4** 2019-11-05 12:01**MOT test number** 792983732109**Result** ✗ Failed**Fail** Offside Front Tyre has ply or cords exposed (5.2.3 (d) (ii))**Advice** Nearside Front Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))**Advice** Nearside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))**Advice** Offside Front Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))

**MOT #3** 2018-11-05 10:28**MOT test number** 361915898637**Result** ✓ Passed**Advice** Nearside Front Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))**MOT #2** 2017-11-10 10:56**MOT test number** 690307096198**Result** ✓ Passed**Advice** Nearside Front tyre has some damage to sidewall**MOT #1** 2017-11-08 09:10**MOT test number** 349988012404**Result** ✗ Failed**Fail** Offside Headlamp aim too low (1.8)**Advice** Nearside Front tyre has some damage to sidewall



Tax & MOT check

✓
Taxed

Tax due:
1 January 2025

✓
MOT

Expires:
15 January 2025

Tax status	Valid until 1 January
Days left	247
MOT expiry date	15 January 2025
Full MOT history	See MOT history

Tax calculation

Vehicle class	48
Band	C
Single payment (12 months)	£ 35,00,-
Single six month payment	Not applicable
Total payable by 12 monthly instalments	£ 36,75,-



Damage history

Check the damage history for this FIAT. See if, where and when this FIAT had damage and the car repair costs. We also check if this FIAT was scrapped. Download the premium report [here](#) for the results.

Damage 1	
Date	
Category	
Type	
Damage 2	
Date	
Category	
Type	



Extra FIAT salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this FIAT in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,999
Auction value	£ 19,999
Average private trade value	£ 19,999

More info >



Owner history

For how long did the current and previous owner(s) have this FIAT? How many owners did this FIAT have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since

More info >

Plate changes

See in this check if this FIAT had different number plates.

Number of plates	1
Current registration	
Plate since	2019-09-29
Current registration	
Plate since	2019-09-29

More info >



Finance check

Check if this FIAT is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this FIAT has been settled.

If not, and you buy this FIAT then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this FIAT is financed.

Finance company	XXXXXXXXXX	XXXX
Date of agreement	XXXXXXXXXX	XXXX
Agreement type	XXXXXXXXXX	XXXX
Agreement term	XXXXXXXXXX	XXXX
Agreement number	XXXXXXXXXX	XXXX
Contact info	XXXXXXXXXX	XXXX

More info >



Mileage check

Odometer	In miles
Mileage registrations	14
First mileage registration	2014-11-26
Last registration	2023-12-18
Complete history	See info



Registration #1	2014-11-26	8 mi
Registration #2	2017-11-08	17.496 mi
Registration #3	2017-11-10	17.500 mi
Registration #4	2018-11-05	22.220 mi
Registration #5	2019-11-05	26.835 mi
Registration #6	2019-11-05	26.835 mi
Registration #7	2020-11-10	32.201 mi
Registration #8	2020-11-10	32.201 mi
Registration #9	2020-11-10	32.201 mi
Registration #10	2020-11-10	32.201 mi
Registration #11	2020-11-10	32.201 mi
Registration #12	2020-11-10	32.201 mi
Registration #13	2020-11-10	32.201 mi
Registration #14	2020-11-10	32.201 mi

More info >



Car features

The FIAT factory car options list is only available in the premium report.

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

View the complete FIAT factory list for this vehicle [here](#).

More info >

Safety ratings

NCAP rating	★★★★★
Video	see crash video



Dimensions & weight

Width	1627 mm
Height	1488 mm
Length	3546 mm
Wheel base	2300 mm
Kerb weight	865 kg
Max. allowed weight	1305 kg

Additional information

Fuel tank capacity	35 l
Fuel delivery	Multi-Point Injection
Number of doors	3
Number of seats	4

Number of axles	2
Engine number	0709926