



report date: 2024-03-28

General information

Make	CITROEN
Model	DS4 HDI DSTYLE
Colour	Black
Year of manufacture	2013
Top speed	118 mph
Gearbox	5 speed Manual

Engine & fuel consumption

Power	110 BHP
Max. torque	270 Nm at 1.750 rpm
Engine capacity	1.560 cc
Cylinders	4
Fuel type	Diesel
Consumption city	47.9 mpg
Consumption extra urban	70.6 mpg
Consumption combined	60.1 mpg
CO2 emission	122 g/km
CO2 label	D





MOT history

MOT expiry date	2024-07-07
MOT pass rate	73 %
MOT passed	8
Failed MOT tests	3
Total advice items	25
Total items failed	2

MOT #11	2023-07-08 12:14
MOT test number	522719949785
Result	✓ Passed
Next expiry date	2024-07-07

**MOT #10**

2023-07-04 15:49

MOT test number

465766649412

Result**✗ Failed**

- MAJOR** Offside Front Suspension arm pin or bush excessively worn (5.3.4 (a) (i))
- MAJOR** Offside Front Anti-roll bar linkage ball joint excessively worn (5.3.4 (a) (i))
- DANGEROUS** Nearside Front Tyre tread depth below requirements of 1.6mm (5.2.3 (e))
- MAJOR** Offside Front Electronic parking brake warning indicates a malfunction (1.1.6 (e))
- DANGEROUS** Offside Rear Outer Brake disc in such a condition that it is seriously weakened (1.1.14 (a) (ii))
- MAJOR** Offside Headlamp aim too low (4.1.2 (a))
- MAJOR** Offside Front Coil spring fractured or broken (5.3.1 (b) (i))
- MAJOR** Nearside Front Outer Drive shaft joint constant velocity boot split or insecure, no longer prevents the ingress of dirt (6.1.7 (g) (ii))
- DANGEROUS** Nearside Front Suspension arm pin or bush likely to become detached (5.3.4 (a) (ii))
- MAJOR** Central Electronic parking brake control inoperative (1.1.6 (d))
- DANGEROUS** Offside Front Tyre tread depth below requirements of 1.6mm (5.2.3 (e))
- MAJOR** Nearside Headlamp aim too low (4.1.2 (a))
- DANGEROUS** Parking brake efficiency less than 50% of the required value (1.4.2 (a) (ii))

MOT #9

2022-06-21 13:38

MOT test number

669420318342

Result**✓ Passed**

**MOT #8** 2022-06-20 13:29**MOT test number** 458207556390**Result** ✗ Failed**MAJOR** Offside Headlamp aim projected beam image is obviously incorrect (4.1.2 (c))**MAJOR** Offside Windscreen washer provides insufficient washer liquid (3.5 (a))**MAJOR** Nearside Front Anti-roll bar linkage ball joint excessively worn (5.3.4 (a) (i))**MAJOR** Nearside Windscreen washer provides insufficient washer liquid (3.5 (a))**MOT #7** 2021-03-27 11:05**MOT test number** 532881488195**Result** ✓ Passed**MOT #6** 2020-02-06 13:15**MOT test number** 427095868630**Result** ✓ Passed**Advice** Nearside Rear Coil spring worn (5.3.1 (b) (i))**MOT #5** 2018-11-29 13:10**MOT test number** 899750850218**Result** ✓ Passed**Advice** Offside Front Anti-roll bar linkage ball joint has slight play (5.3.4 (a) (i))**Advice** Offside Rear Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))**Advice** Nearside Front Anti-roll bar linkage ball joint has slight play (5.3.4 (a) (i))**Minor** Nearside Front Windscreen wiper blade defective wiper smearing (3.4 (b) (i))**MOT #4** 2017-12-20 15:01**MOT test number** 448753651065**Result** ✓ Passed



MOT #3	2017-04-24 11:10
MOT test number	732280323057
Result	✓ Passed
Advice	Nearside Front Tyre worn close to the legal limit (4.1.E.1)
Advice	Nearside Rear Child Seat fitted not allowing full inspection of adult belt
Advice	Offside Front Tyre worn close to the legal limit (4.1.E.1)

MOT #2	2016-04-14 15:18
MOT test number	482541588443
Result	✓ Passed

MOT #1	2016-04-14 13:29
MOT test number	662320950933
Result	✗ Failed
Fail	Nearside Front Tyre tread depth below requirements of 1.6mm (4.1.E.1)
Fail	Offside Front Tyre tread depth below requirements of 1.6mm (4.1.E.1)



Tax & MOT check

✓
Taxed
Tax due:
1 March 2025

✓
MOT
Expires:
7 July 2024

Tax status	Valid until 1 March
Days left	307
MOT expiry date	7 July 2024
Full MOT history	See MOT history

Tax calculation

Vehicle class	49
Band	D
Single payment (12 months)	£ 150,00,-
Single six month payment	£ 82,50,-
Total payable by 12 monthly instalments	£ 157,50,-



Damage history

Check the damage history for this CITROEN. See if, where and when this CITROEN had damage and the car repair costs. We also check if this CITROEN was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	

Damage 2

Date	
Category	
Type	



Extra CITROEN salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this CITROEN in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 15,200
Auction value	£ 15,200
Average private trade value	£ 15,200

More info >



Owner history

For how long did the current and previous owner(s) have this CITROEN? How many owners did this CITROEN have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration

More info >

Plate changes

See in this check if this CITROEN had different number plates.

Number of plates	1
Current registration	KP13VVC
Plate since	2024-03-28
Current registration	KP13VVC
Plate since	2024-03-28

More info >



Finance check

Check if this CITROEN is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this CITROEN has been settled.

If not, and you buy this CITROEN then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this CITROEN is financed.

Finance company	XXXXXXXX	XXXX
Date of agreement	XXXXXXXX	XXXX
Agreement type	XXXXXXXX	XXXX
Agreement term	XXXXXXXX	XXXX
Agreement number	XXXXXXXX	XXXX
Contact info	XXXXXXXX	XXXX

More info >



Mileage check

Odometer	In miles
Mileage registrations	12
First mileage registration	2013-04-25
Last registration	2023-07-08
Complete history	See info



Registration #1	2013-04-25	16 mi
Registration #2	2016-04-14	41.547 mi
Registration #3	2016-04-14	41.547 mi
Registration #4	2017-04-24	51.944 mi
Registration #5	2017-12-20	58.852 mi
Registration #6	2018-11-29	64.190 mi
Registration #7	2019-05-29	70.277 mi
Registration #8	2019-05-29	70.277 mi
Registration #9	2019-05-29	70.277 mi
Registration #10	2019-05-29	70.277 mi
Registration #11	2019-05-29	70.277 mi
Registration #12	2019-05-29	70.277 mi

More info >



Safety ratings

NCAP rating	★★★★★
Adult	90%
Children	80%
Pedestrian	43%
Safety systems	97%
Overall rating	79%
Video	see crash video



Dimensions & weight

Width	1810 mm
Height	1523 mm
Length	4275 mm
Wheel base	2612 mm
Kerb weight	1320 kg
Max. allowed weight	1805 kg

Additional information

Fuel delivery	Direct Injection
Number of doors	3
Number of seats	5
Number of axles	2
Engine number	JBET0001963