





report date: 2024-03-29

General information

Make	CITROEN
Model	DS3 DSIGN PLUS
Colour	Grey
Year of manufacture	2014
Top speed	108 mph
0 - 60 mph	14.2 seconds
Gearbox	5 speed Manual

Engine & fuel consumption

Power	82 BHP
Max. torque	118 Nm at 2.750 rpm
Engine capacity	1.199 cc
Cylinders	3
Fuel type	Petrol
Consumption city	51.4 mpg
Consumption extra urban	72.4 mpg
Consumption combined	62.8 mpg
CO2 emission	104 g/km
CO2 label	В



CarCheck.co.uk page 1/12



report date: 2024-03-29

Internet history

Entry 2

Date 2021-07-23

Pictures 3

Listing price <u>View report</u>







source: cargurus.co.uk

Entry 1

Date	2021-07-20
Pictures	0
Listing price	View report

source: autotrader.co.uk

CarCheck.co.uk page 2/12



report date: 2024-03-29

N/I	α		TC:	-	r\/
101	•		115		ıv
	•	Γh			. ,

MOT expiry date	2024-09-02
MOT pass rate	70 %
MOT passed	7
Failed MOT tests	3
Total advice items	14
Total items failed	6

MOT #10	2023-08-22 14:10
MOT test number	856133194121
Result	✓ Passed
Next expiry date	2024-09-02
Advice Exhaust has a minor leak of exhaust gases front section (6.1.2 (a))	

MOT #9	2023-08-22 09:30
MOT test number	365351602753
Result	X Failed
Fail Offside Rear Coil spring fractured or broken (5.3.1 (b) (i)) Advice Exhaust has a minor leak of exhaust gases front section (6.1.2 (a))	

MOT #8		2022-09-01 12:56
MOT test	number	888210554443
Result		✓ Passed
Advice	Offside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))	
Advice	Nearside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))	

CarCheck.co.uk page 3/12



HN64OZD

report date: 2024-03-29

MOT #7 2022-09-01 08:29 **MOT** test number 631668607977 Result × Failed Fail Exhaust Lambda reading after 2nd fast idle outside specified limits (8.2.1.2 (c)) Fail Tyre pressure monitoring system malfunctioning or obviously inoperative (5.2.3 (h)) **Advice** Nearside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e)) Offside Windscreen wiper does not clear the windscreen effectively (3.4 (b) (ii)) Fail Fail Exhaust has a major leak of exhaust gases (6.1.2 (a)) **Advice** Offside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))

 MOT #6
 2021-09-03 13:48

 MOT test number
 963515443046

 Result
 ✓ Passed

 MOT #5
 2020-11-03 11:30

 MOT test number
 267194911037

 Result
 ✓ Passed

Advice Nearside Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))

Advice Offside Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))

MOT #4

MOT test number

Result

Advice Nearside Rear Outer Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))

Advice Offside Rear Outer Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))

CarCheck.co.uk page 4/12



Pass with rectification

Result

HN640ZD

report date: 2024-03-29

X Failed

MOT #3 2018-11-13 09:35

MOT test number 265338946107

Result
✓ Passed

Advice Tyre slightly damaged/cracking or perishing all tyres on outer sidewalls (5.2.3 (d) (ii))

Advice Nearside Front Tyre worn close to legal limit/worn on edge 2.8mm (5.2.3 (e))

MOT #2 2018-11-13 09:35

MOT test number 311098395227

Advice Tyre slightly damaged/cracking or perishing all tyres on outer sidewalls (5.2.3 (d) (ii))

Advice Nearside Front Tyre worn close to legal limit/worn on edge 2.8mm (5.2.3 (e))

MOT #1 2017-11-27 11:15

Exhaust system insecure rear mounting adrift (6.1.2 (a))

MOT test number 995290923688

CarCheck.co.uk page 5/12



report date: 2024-03-29

Tax & MOT check





Expires: 2 September 2024

Tax status	Valid until 1 September
Days left	124
MOT expiry date	2 September 2024
Full MOT history	See MOT history

Tax calculation

Vehicle class	48
Band	В
Single payment (12 months)	£ 20,00,-
Single six month payment	Not applicable
Total payable by 12 monthly instalments	£ 21,00,-

CarCheck.co.uk page 6/12



HN64OZD

report date: 2024-03-29

Damage history

Check the damage history for this CITROEN. See if, where and when this CITROEN had damage and the car repair costs. We also check if this CITROEN was scrapped. Download the premium report here for the results.

Damage 1
Date
Category
Type
Damage 2
Date
Category
Type



Extra CITROEN salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report <u>here</u> for more information.

More info >

CarCheck.co.uk page 7/12



HN64OZD

report date: 2024-03-29

Vehicle valuation

What is this car worth? See the vehicle value of this CITROEN in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value

Auction value

Average private trade value

More info >

CarCheck.co.uk page 8/12



report date: 2024-03-29

Owner history

For how long did the current and previous owner(s) have this CITROEN? How many owne have? Check it in the premium report and see all owner registrations. Download the full r		OEN

	More info	>
Plate changes		
See in this check if this CITROEN had different number plates.		
Number of plates		
Current registration	UK UK	
Plate since		
Current registration	UK UK	
Plate since		
	More info	>

CarCheck.co.uk page 9/12



report date: 2024-03-29

Finance check

Check if this CITROEN is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this CITROEN has been settled.

If not, and you buy this CITROEN then you could lose the money and the car you paid for.

Download the premium report <u>here</u> and check if this CITROEN is financed.

Finance company

Date of agreement

Agreement type

Agreement term

Agreement number

Contact info

More info >

CarCheck.co.uk page 10/12



report date: 2024-03-29

Mileage check

Odometer	In miles
Mileage registrations	13
First mileage registration	2014-12-05
Last registration	2023-08-22
Complete history	See info



Registration #1	2014-12-05	28 mi
Registration #2	2017-11-27	22.853 mi
Registration #3	2018-11-13	29.060 mi
Registration #4	2018-11-13	29.060 mi
Registration #5	2019-11-26	37.176 mi
Registration #6	2020-11-03	40.563 mi
Registration #7		11.777 mi
Registration #8		11.177 es
Registration #9		11.777 mi
Registration #10		11.777 es
Registration #11		11.177 mi
Registration #12		11.777 es
Registration #13		11.777 mi

More info >

CarCheck.co.uk page 11/12



report date: 2024-03-29

Safety ratings

NCAP rating	****
Adult	87%
Children	71%
Pedestrian	35%
Safety systems	83%
Overall rating	73%
Video	see crash video



Dimensions & weight

Width	1708 mm
Height	1460 mm
Length	3948 mm
Wheel base	2464 mm
Kerb weight	1075 kg
Max. allowed weight	1496 kg

Additional information

Fuel tank capacity	48
Fuel delivery	Multi-Point Injection
Number of doors	3
Number of seats	5
Number of axles	2
Engine number	B2080285752

CarCheck.co.uk page 12/12