





report date: 2024-03-28

### General information

Make	BMW
Model	525 525D SE
Colour	Blue
Year of manufacture	2004
Top speed	141 mph
0 - 60 mph	8.3 seconds
Gearbox	6 speed automatic

### Engine & fuel consumption

Power	177 BHP	
Max. torque	400 Nm at 2.000 rpm	
Engine capacity	2.497 сс	
Cylinders	6	
Fuel type	Diesel	
Consumption city	26.6 mpg	
Consumption extra urban	45.6 mpg	
Consumption combined	36.2 mpg	
CO2 emission	208 g/km	
CO2 label	K	



CarCheck.co.uk page 1/14



FN54XAR report date: 2024-03-28

# Internet history

### Entry 1

Date 2021-09-14

Pictures 20

Listing price <u>View report</u>









source: autotrader.co.uk

CarCheck.co.uk page 2/14



report date: 2024-03-28

## MOT history

MOT expiry date	2022-10-05
MOT pass rate	79 %
MOT passed	15
Failed MOT tests	4
Total advice items	28
Total items failed	7

MOT #19	2021-10-06 15:02
MOT test number	556026191489
Result	<b>✓</b> Passed
Next expiry date	2022-10-05

MOT #18	2021-07-07 09:31
MOT test number	624250778663
Result	🗙 Failed
Advice Rear Brake pad(s) wearing thin (1.1.13 (a) (ii))	
Fail Nearside Front Steering linkage ball joint has excessive play Inner balljoint on near excessive play (2.1.3 (b) (i))	rside tie rod has
Minor Brake fluid warning lamp illuminated (1.1.10 (f))	
Fail Front Brake pad(s) less than 1.5 mm thick (1.1.13 (a) (ii))	
Fail Windscreen washer not working (3.5 (a))	

MOT #17	2020-06-04 09:03
MOT test number	894060013898
Result	<b>✓</b> Passed

CarCheck.co.uk page 3/14



report date: 2024-03-28

MOT #16

MOT test number

Result

Pass with rectification

Exhaust silencer insecure front clamp rusted (8.1.1 (b) (i))

MOT #15

MOT test number

Result

MOT #14

2019-06-12 15:52

855927579959

Result

2018-08-29 09:56

**MOT test number** 272137184119

Minor Offside Front Anti-roll bar linkage ball joint dust cover severely deteriorated (5.3.4 (b) (i))

Advice Front Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))

**Advice** Offside Rear Brake pipe corroded, covered in grease or other material (1.1.11 (c))

MOT #13 2017-08-31 12:12 MOT test number 807339371287

Advice Nearside Front Tyre worn close to the legal limit edges (4.1.E.1)

**Advice** Offside Rear Brake pipe slightly corroded (3.6.B.2c)

**Advice** Offside Front Tyre worn close to the legal limit edges (4.1.E.1)

CarCheck.co.uk page 4/14



report date: 2024-03-28

**MOT #12** 2017-08-30 10:04

**MOT test number** 595831119475

**Result** X Failed

**Fail** Nearside Front Upper Anti-roll bar linkage ball joint dust cover excessively damaged so that it no longer prevents the ingress of dirt (2.4.G.2)

**Advice** Offside Front Suspension arm rubber bush deteriorated but not resulting in excessive movement front bush (2.4.G.2)

**Advice** Offside Front Tyre worn close to the legal limit edges (4.1.E.1)

**Advice** Nearside Front Suspension arm rubber bush deteriorated but not resulting in excessive movement front bush (2.4.G.2)

**Advice** Nearside Front Tyre worn close to the legal limit edges (4.1.E.1)

**Advice** Offside Rear Brake pipe slightly corroded (3.6.B.2c)

**MOT #11** 2016-09-02 08:06

MOT test number 521912441173

**Result** ✓ Passed

**MOT #10** 2015-08-18 17:02

**MOT test number** 499850535279

**Result** 
✓ Passed

Notice Oil leak

MOT #9 2015-08-17 12:19

MOT test number 656539725255

**Result** ★ Failed

Notice Oil leak

**Fail** Offside Rear Lower Suspension arm has excessive play in a ball joint (2.4.G.2)

**Advice** Parking brake lever has little reserve travel (3.1.6b)

**Notice** Under-trays fitted obscuring some underside components

**Fail** Parking brake: efficiency below requirements (3.7.B.7)

CarCheck.co.uk page 5/14



**Advice** 

FN54XAR

report date: 2024-03-28

**MOT #8** 2014-08-14 11:44 **MOT** test number 677656124246 Result ✓ Passed **Notice** Oil leak Advice Offside Front Macpherson strut has slight movement at the upper attachment (2.5.A.1c) Advice Front Brake pad(s) wearing thin (3.5.1g) Notice Under-trays fitted obscuring some underside components Advice Nearside Side repeater slightly discoloured (1.4.A.2f) **Advice** Front brake disc worn, pitted or scored, but not seriously weakened (3.5.1i)

MOT #7

MOT test number

846835543279

Result

Notice Low efort near side rear parking brake

MOT #6 2012-08-22 12:37

MOT test number 936675732255

Result ✓ Passed

MOT #5

MOT test number

715915151247

Result

✓ Passed

Advice Offside Outer Rear Brake pipe slightly corroded (3.6.B.2c)

Nearside Front Tyre worn close to the legal limit (4.1.E.1)

CarCheck.co.uk page 6/14



report date: 2024-03-28

MOT #4		2010-09-02 09:47
MOT test	number	960985040254
Result		✓ Passed
Advice	Nearside Rear Tyre worn close to the legal limit (4.1.E.1)	
Advice	Offside Rear Tyre worn close to the legal limit (4.1.E.1)	

MOT #3	2009-09-04 09:20
MOT test number	343017349244
Result	<b>✓</b> Passed
MOT #2	2008-11-18 12:08
MOT test number	193803928333
Result	✓ Passed
MOT #1	2006 11 17 14.27

MOT #1	2006-11-17 14:27
MOT test number	701581526366
Result	✓ Passed

CarCheck.co.uk page 7/14



report date: 2024-03-28

#### Tax & MOT check



X MOT

Tax expired: 1 January 2022

**Expired:** 5 October 2022

Tax status	Expired at 1 January 2022
Days left	850 days too late
MOT expiry date	5 October 2022
Full MOT history	See MOT history

#### Tax calculation

Vehicle class	49
Band	K
Single payment (12 months)	£ 395,00,-
Single six month payment	£ 217,25,-
Total payable by 12 monthly instalments	£ 414,75,-

CarCheck.co.uk page 8/14



report date: 2024-03-28

#### Damage history

Check the damage history for this BMW. See if, where and when this BMW had damage and the car repair costs. We also check if this BMW was scrapped. Download the premium report <a href="here">here</a> for the results.

Damage 1	
Date	
Category	
Туре	
Damage 2	
Date	
Category	
Туре	



#### Extra BMW salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report <u>here</u> for more information.

More info >

CarCheck.co.uk page 9/14



report date: 2024-03-28

#### Vehicle valuation

What is this car worth? See the vehicle value of this BMW in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

**Trade retail value** 

**Auction value** 

Average private trade value

More info >

CarCheck.co.uk page 10/14



report date: 2024-03-28

## Owner history

For how long did the current and previous owner(s) have this BMW? How many owners defect it in the premium report and see all owner registrations. Download the full report	
manus .	
***************************************	
manus .	
***************************************	
***************************************	
	More info >
Plate changes	
See in this check if this BMW had different number plates.	
· ·	
Number of plates	
Current registration	IK UK
Flate since	
Current registration	NK NK
Made since	UN CONTRACTOR
	More info >
	, , ,

CarCheck.co.uk page 11/14



report date: 2024-03-28

#### Finance check

Check if this BMW is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this BMW has been settled.

If not, and you buy this BMW then you could lose the money and the car you paid for.

Download the premium report <u>here</u> and check if this BMW is financed.

Finance company	
Date of agreement	
Agreement type	
Agreement term	
Agreement number	
Contact info	

More info >

CarCheck.co.uk page 12/14



report date: 2024-03-28

# Mileage check

Odometer	In miles
Mileage registrations	21
First mileage registration	2004-09-01
Last registration	2021-10-06
Complete history	See info



Registration #1	2004-09-01	15 mi
Registration #2	2006-11-17	15.307 mi
Registration #3	2008-11-18	33.562 mi
Registration #4	2009-09-04	39.928 mi
Registration #5	2010-09-02	50.992 mi
Registration #6	2011-09-12	58.059 mi
Registration #7	2012-08-22	63.692 mi
Registration #8	2013-09-02	70.179 mi
Registration #9	2014-08-14	76.351 mi
Registration #10	2015-08-17	82.073 mi
Registration #11	2015-08-18	82.071 mi
Registration #12		11.777 es
Registration #13		11.777 es
Registration #14		11.117 es
Registration #15		11.777 es
Registration #16		11.777 es
Registration #17		11.777 es
Registration #18		11.777 es
Registration #19		11.777 es
Registration #20		11.777 es
Registration #21		11.777 ms

More info >

CarCheck.co.uk page 13/14



report date: 2024-03-28

## Car features

S0225	Air conditioning
S0295	
S0482	
S0501	
50566	
50567	
S0569	

# Safety ratings

NCAP rating	****
Video	see crash video



# Dimensions & weight

Width	1846 mm
Height	1469 mm
Length	4841 mm
Wheel base	2888 mm
Kerb weight	1685 kg
Max. allowed weight	2155 kg

### Additional information

Fuel tank capacity	70 I	
Fuel delivery	Direct Injection	
Number of doors	4	
Number of seats CarCheck.co.uk	5	page 14/14