



TOYOTA



report date: 2024-03-28

General information

Make	TOYOTA
Model	RAV-4 D-4D XTR
Colour	Grey
Year of manufacture	2007
Top speed	112 mph
0 - 60 mph	10.5 seconds
Gearbox	6 speed Manual

Engine & fuel consumption

Power	134 BHP
Max. torque	310 Nm at 2.000 rpm
Engine capacity	2.231 cc
Cylinders	4
Fuel type	Diesel
Consumption city	34.9 mpg
Consumption extra urban	50.4 mpg
Consumption combined	42.8 mpg
CO2 emission	173 g/km
CO2 label	H





Internet history

Entry 1

Date	2021-10-26
Pictures	12
Listing price	View report



source: cargurus.co.uk



MOT history

MOT expiry date	2024-11-06
MOT pass rate	74 %
MOT passed	14
Failed MOT tests	5
Total advice items	29
Total items failed	14

MOT #19	2023-10-18 13:05
MOT test number	673467807569
Result	✓ Passed
Next expiry date	2024-11-06
Advice	Nearside Front Suspension arm pin or bush worn but not resulting in excessive movement (5.3.4 (a) (i))
Advice	Front Brake disc worn, but not excessively (1.1.14 (a) (i))
Advice	Offside Front Suspension arm pin or bush worn but not resulting in excessive movement (5.3.4 (a) (i))
Advice	Rear Brake disc worn, but not excessively (1.1.14 (a) (i))

**MOT #18**

2023-10-16 12:47

MOT test number

633556697657

Result**✗ Failed**

Fail Offside Front Outer Drive shaft joint constant velocity boot split or insecure, no longer prevents the ingress of dirt (6.1.7 (g) (ii))

Fail Nearside Rear Shock absorbers has a serious fluid leak (5.3.2 (b))

Advice Nearside Front Suspension arm pin or bush worn but not resulting in excessive movement (5.3.4 (a) (i))

Advice Front Brake disc worn, but not excessively (1.1.14 (a) (i))

Fail Nearside Rear Anti-roll bar linkage ball joint excessively worn (5.3.4 (a) (i))

Fail Nearside Rear Coil spring fractured or broken (5.3.1 (b) (i))

Fail Offside Rear Shock absorbers has a serious fluid leak (5.3.2 (b))

Advice Offside Front Suspension arm pin or bush worn but not resulting in excessive movement (5.3.4 (a) (i))

Advice Rear Brake disc worn, but not excessively (1.1.14 (a) (i))

MOT #17

2022-10-11 15:34

MOT test number

288475864617

Result**✓ Passed**

Advice Offside Rear Shock absorbers has light misting of oil (5.3.2 (b))

MOT #16

2021-10-20 15:17

MOT test number

661684558032

Result**✓ Passed**

Advice Offside Rear Shock absorbers has light misting of oil (5.3.2 (b))

Advice Suspension arm pin or bush worn but not resulting in excessive movement Nearside/Offside Front. (5.3.4 (a) (i))

Advice Nearside Rear Service brake fluctuating, but not excessively (1.2.1 (e))

**MOT #15**

2021-10-20 15:17

MOT test number

418818589396

Result**✗ Failed****Advice** Offside Rear Shock absorbers has light misting of oil (5.3.2 (b))**Pass with rectification** Exhaust emissions exceed manufacturer's specified limit (8.2.2.2 (a))**Advice** Suspension arm pin or bush worn but not resulting in excessive movement Nearside/Offside Front. (5.3.4 (a) (i))**Advice** Nearside Rear Service brake fluctuating, but not excessively (1.2.1 (e))**MOT #14**

2021-10-04 12:07

MOT test number

629761122907

Result**✗ Failed****Fail** Brake lever has insufficient reserve travel (1.1.2 (a))**Fail** Rear Brakes imbalanced across an axle (1.2.1 (b) (i))**Fail** Offside Front Suspension arm pin or bush excessively worn (5.3.4 (a) (i))**Advice** Front Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))**Fail** Offside Rear Shock absorbers has a serious fluid leak (5.3.2 (b))**Fail** Rear Service brake excessively fluctuating (1.2.1 (e))**Fail** Nearside Front Suspension arm pin or bush excessively worn (5.3.4 (a) (i))**Advice** Nearside Front Outer Tyre worn close to legal limit/worn on edge (5.2.3 (e))

**MOT #13** 2020-10-28 14:06**MOT test number** 416123764011**Result** ✓ Passed**Advice** Nearside Front Suspension arm pin or bush worn but not resulting in excessive movement (5.3.4 (a) (i))**Advice** Nearside Front Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))**Advice** Offside Front Suspension arm pin or bush worn but not resulting in excessive movement (5.3.4 (a) (i))**Advice** Offside Front Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))**MOT #12** 2019-11-07 10:48**MOT test number** 343389654775**Result** ✓ Passed**MOT #11** 2019-11-07 10:48**MOT test number** 608042628842**Result** ✗ Failed**Pass with rectification** Offside Headlamp aim too high (4.1.2 (a))**MOT #10** 2019-01-02 15:24**MOT test number** 662988101588**Result** ✓ Passed**MOT #9** 2017-12-21 11:17**MOT test number** 522252413947**Result** ✓ Passed**MOT #8** 2016-12-14 14:22**MOT test number** 377418785330**Result** ✓ Passed

**MOT #7** 2015-12-30 10:19**MOT test number** 319167223497**Result** ✓ Passed**MOT #6** 2015-01-06 14:12**MOT test number** 539566405021**Result** ✓ Passed**MOT #5** 2013-11-15 12:08**MOT test number** 458029413343**Result** ✓ Passed**Advice** Nearside Rear Brake pad(s) wearing thin (3.5.1g)**Advice** Offside Rear Brake pad(s) wearing thin (3.5.1g)**Notice** Both front rear most wishbone arm bushes slightly separating.**MOT #4** 2012-11-28 16:30**MOT test number** 427913532336**Result** ✓ Passed**Advice** Offside Front Lower Suspension arm rubber bush deteriorated but not resulting in excessive movement (2.4.G.2)**Advice** Nearside Front Lower Suspension arm rubber bush deteriorated but not resulting in excessive movement (2.4.G.2)**MOT #3** 2012-11-28 10:56**MOT test number** 479093932442**Result** ✗ Failed**Advice** Nearside Front Lower Suspension arm rubber bush deteriorated but not resulting in excessive movement (2.4.G.2)**Notice** Oil level low**Fail** Nearside Rear Anti-roll bar linkage fractured (2.4.G.1)**Advice** Offside Front Lower Suspension arm rubber bush deteriorated but not resulting in excessive movement (2.4.G.2)



MOT #2	2011-11-23 14:24
MOT test number	597807021342
Result	✓ Passed

MOT #1	2010-11-18 16:09
MOT test number	891102120352
Result	✓ Passed



Tax & MOT check

✓
Taxed
Tax due:
1 October 2024

✓
MOT
Expires:
6 November 2024

Tax status	Valid until 1 October
Days left	155
MOT expiry date	6 November 2024
Full MOT history	See MOT history

Tax calculation

Vehicle class	49
Band	H
Single payment (12 months)	£ 290,00,-
Single six month payment	£ 159,50,-
Total payable by 12 monthly instalments	£ 304,50,-




Damage history

Check the damage history for this TOYOTA. See if, where and when this TOYOTA had damage and the car repair costs. We also check if this TOYOTA was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	



Damage 2

Date	
Category	
Type	

Extra TOYOTA salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this TOYOTA in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,999
Auction value	£ 19,999
Average private trade value	£ 19,999

More info >



Owner history

For how long did the current and previous owner(s) have this TOYOTA? How many owners did this TOYOTA have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

*****	*****
*****	*****
*****	*****
*****	*****
*****	*****
*****	*****
*****	*****

More info >

Plate changes

See in this check if this TOYOTA had different number plates.

Number of plates	1
Current registration	*****
Plate since	2019-06-29
Current registration	*****
Plate since	2019-06-29

More info >



Finance check

Check if this TOYOTA is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this TOYOTA has been settled. If not, and you buy this TOYOTA then you could lose the money and the car you paid for. Download the premium report [here](#) and check if this TOYOTA is financed.

Finance company	XXXXXXXXXX	XXXX
Date of agreement	XXXXXXXXXX	XXXX
Agreement type	XXXXXXXXXX	XXXX
Agreement term	XXXXXXXXXX	XXXX
Agreement number	XXXXXXXXXX	XXXX
Contact info	XXXXXXXXXX	XXXX

More info >



Mileage check

Odometer	In miles
Mileage registrations	21
First mileage registration	2007-12-01
Last registration	2023-10-18
Complete history	See info



Registration #1	2007-12-01	15 mi
Registration #2	2010-11-18	47.444 mi
Registration #3	2011-11-23	57.850 mi
Registration #4	2012-11-28	66.395 mi
Registration #5	2012-11-28	66.396 mi
Registration #6	2013-11-15	72.216 mi
Registration #7	2015-01-06	79.017 mi
Registration #8	2015-12-30	83.979 mi
Registration #9	2016-12-14	88.782 mi
Registration #10	2017-12-21	93.853 mi
Registration #11	2019-01-02	99.535 mi
Registration #12	2019-01-02	99.535 mi
Registration #13	2019-01-02	99.535 mi
Registration #14	2019-01-02	99.535 mi
Registration #15	2019-01-02	99.535 mi
Registration #16	2019-01-02	99.535 mi
Registration #17	2019-01-02	99.535 mi
Registration #18	2019-01-02	99.535 mi
Registration #19	2019-01-02	99.535 mi
Registration #20	2019-01-02	99.535 mi
Registration #21	2019-01-02	99.535 mi

More info >



Car features

The TOYOTA factory car options list is only available in the premium report.

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

View the complete TOYOTA factory list for this vehicle [here](#).

More info >

Safety ratings

NCAP rating ★★★★★

Video [see crash video](#)



Dimensions & weight

Width	1815 mm
Height	1685 mm
Length	4395 mm
Wheel base	2560 mm
Kerb weight	1640 kg
Max. allowed weight	2190 kg

Additional information

Fuel tank capacity	60 l
Fuel delivery	Direct Injection
Number of doors	5
Number of seats	5

Number of axles	2
Engine number	2AD0090619