





report date: 2024-03-28

General information

Make	HYUNDAI
Model	I20 MPI SE
Colour	Red
Year of manufacture	2015
Top speed	106 mph
0 - 60 mph	13.1 seconds
Gearbox	7 speed Manual

Engine & fuel consumption

Power	83 BHP
Max. torque	122 Nm at 4.000 rpm
Engine capacity	1.248 cc
Cylinders	4
Fuel type	Petrol
Consumption city	42.8 mpg
Consumption extra urban	67.3 mpg
Consumption combined	55.4 mpg
CO2 emission	119 g/km
CO2 label	С



CarCheck.co.uk page 1/11



Internet history

Εı	n	tı	'V	,	1

Elitiy 1	
Date	2021-01-31
Pictures	0
Listing price	View report

source: autoonline.co.uk

CarCheck.co.uk page 2/11



report date: 2024-03-28

MOT history

MOT expiry date	2024-05-04
MOT pass rate	67 %
MOT passed	6
Failed MOT tests	3
Total advice items	9
Total items failed	3

MOT #9		2024-04-27 08:16
MOT test	number	385091998026
Result		X Failed
Minor	Windscreen damaged but not adversely affecting driver's view (3.2 (a)	(i))
MAJOR dust cove	Nearside Front Lower Suspension arm ball joint dust cover no longer per is split (5.3.4 (b) (ii))	prevents the ingress of dirt
MAJOR	Nearside Windscreen wiper does not clear the windscreen effectively	blade is torn (3.4 (b) (ii))

MOT #8	2023-04-22 08:56
MOT test number	187158668521
Result	✓ Passed
Advice Front Brake pad(s) wearing thin front worn to about 3 to 4mm (1.1.13 (a) (ii))	

MOT #7		2023-04-22 08:56
MOT test number		372943442626
Result		X Failed
Advice Front Brake pad	s) wearing thin front worn to about 3 to 4mm (1.1.13 (a) (ii))
Pass with rectification	Offside Windscreen wiper does not clear the windscre	een effectively (3.4 (b) (ii))
Pass with rectification (ii))	Nearside Windscreen wiper does not clear the windsc	creen effectively (3.4 (b)

CarCheck.co.uk page 3/11



report date: 2024-03-28

MOT test number

Result

Advice

Offside Rear Tyre worn close to legal limit/worn on edge worn to 3mm (5.2.3 (e))

Advice

Nearside Rear Tyre worn close to legal limit/worn on edge worn to 2mm (5.2.3 (e))

MOT test number

Result

Pass with rectification

Nearside Stop lamp(s) not working (4.3.1 (a) (ii))

Advice

Offside Rear Tyre worn close to legal limit/worn on edge worn to 3mm (5.2.3 (e))

Advice

Nearside Rear Tyre worn close to legal limit/worn on edge worn to 2mm (5.2.3 (e))

Advice Nearside Rear Tyre worn close to legal limit/worn on edge worn to 2mm (5.2.3 (e))		
MOT #4		2021-05-05 15:26
MOT test nur	nber	536193206632
Result		✓ Passed
MOT #3		2020-02-20 08:36
MOT test nur	nber	690708933584
Result		✓ Passed
MOT #2		2019-02-05 09:34
MOT test nur	nber	543803912629
Result		✓ Passed
MOT #1		2018-02-16 12:36
MOT test nur	nber	380459981494
Result		✓ Passed

CarCheck.co.uk page 4/11



Tax & MOT check



Tax status	Valid until 1 May
Days left	366
MOT expiry date	4 May 2024
Full MOT history	See MOT history

Tax calculation

Vehicle class	48
Band	С
Single payment (12 months)	£ 35,00,-
Single six month payment	Not applicable
Total payable by 12 monthly instalments	£ 36,75,-

CarCheck.co.uk page 5/11



report date: 2024-03-28

Damage history

Check the damage history for this HYUNDAI. See if, where and when this HYUNDAI had damage and the car repair costs. We also check if this HYUNDAI was scrapped. Download the premium report <u>here</u> for the results.

Damage 1
Date
Category
Type
Damage 2
Date
Category
Type



Extra HYUNDAI salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report <u>here</u> for more information.

More info >

CarCheck.co.uk page 6/11



Vehicle valuation

What is this car worth? See the vehicle value of this HYUNDAI in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value

Auction value

Average private trade value

More info >

CarCheck.co.uk page 7/11



report date: 2024-03-28

More info >

Owner history

, <u> </u>	
For how long did the current and previous owner(s) have this HYUNDAI? How many owner have? Check it in the premium report and see all owner registrations. Download the full report and see all owner registrations.	

	More info >
Plate changes	
See in this check if this HYUNDAI had different number plates.	
Number of plates	
Current registration	NK NK
	UK C
Plate since	
Current registration	UK NEW YEAR
Plate since	

CarCheck.co.uk page 8/11



report date: 2024-03-28

Finance check

Check if this HYUNDAI is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this HYUNDAI has been settled.

If not, and you buy this HYUNDAI then you could lose the money and the car you paid for.

Download the premium report <u>here</u> and check if this HYUNDAI is financed.

Finance company	
Date of agreement	
Agreement type	
Agreement term	
Agreement number	
Contact info	

More info >

CarCheck.co.uk page 9/11



report date: 2024-03-28

Mileage check

Odometer	In miles
Mileage registrations	11
First mileage registration	2015-03-02
Last registration	2024-04-27
Complete history	See info



Registration #1	2015-03-02	6 mi
Registration #2	2018-02-16	33.745 mi
Registration #3	2019-02-05	53.253 mi
Registration #4	2020-02-20	69.900 mi
Registration #5		11.777 es
Registration #6	2021-05-05	78.052 mi
Registration #7		11.777 es
Registration #8		71,777 46
Registration #9		77,777 66
Registration #10		11.777 es
Registration #11		71.777 mg

More info >

CarCheck.co.uk page 10/11



Car features

S0225	Air conditionin
S0295	
50482	
60501	
60566	
60567	
50569	

Safety ratings

NCAP rating	****
Adult	85%
Children	73%
Pedestrian	79%
Safety systems	64%
Overall rating	77%
Video	see crash video



Dimensions & weight

Width	1734 mm
Height	1474 mm
Length	4035 mm
Wheel base	2570 mm
Kerb weight	1158 kg
Max. allowed weight	1580 kg

Additional information

Fuel tank capacity	50 I
Fuel delivery	Multi-Point Injection
Number of doors	2
Number of seats CarCheck.co.uk	5 page 11/11

Number of axles 2

Engine number G4LAFM685362