





report date: 2024-03-29

General information

| Make | SUZUKI |
|---------------------|--------------------|
| Model | IGNIS SZ-T DUALJET |
| Colour | Red |
| Year of manufacture | 2018 |
| Top speed | 105 mph |
| 0 - 60 mph | 11.8 seconds |
| Gearbox | 5 speed Manual |

Engine & fuel consumption

| Power | 89 BHP |
|-------------------------|---------------------|
| Max. torque | 120 Nm at 4.400 rpm |
| Engine capacity | 1.242 cc |
| Cylinders | 4 |
| Fuel type | Petrol |
| Consumption city | 51.4 mpg |
| Consumption extra urban | 68.9 mpg |
| Consumption combined | 61.4 mpg |
| CO2 emission | 104 g/km |
| CO2 label | В |



CarCheck.co.uk page 1/11



report date: 2024-03-29

Internet history

Entry 1

Date 2021-02-04

Pictures 10

Listing price <u>View report</u>









source: autoonline.co.uk

CarCheck.co.uk page 2/11



report date: 2024-03-29

| MC | TC | history | |
|----|----|---------|--|
|----|----|---------|--|

| MOT expiry date | 2024-11-19 |
|--------------------|------------|
| MOT pass rate | 80 % |
| MOT passed | 4 |
| Failed MOT tests | 1 |
| Total advice items | 11 |
| Total items failed | 1 |

| MOT #5 | 2023-11-20 13:38 |
|------------------|------------------|
| MOT test number | 171316312960 |
| Result | ✓ Passed |
| Next expiry date | 2024-11-19 |

| MOT #4 | | 2022-11-07 16:46 |
|--|---|------------------|
| MOT test | number | 990869374401 |
| Result | | ✓ Passed |
| Advice | Front Tyre slightly damaged/cracking or perishing both (5.2.3 (d) (ii)) | |
| Advice Offside Front Tyre worn close to legal limit/worn on edge on legal limit (5.2.3 (e)) | |) |
| Advice | Rear Tyre slightly damaged/cracking or perishing both (5.2.3 (d) (ii)) | |
| Advice Nearside Front Tyre worn close to legal limit/worn on edge on legal limit 175 60 16 h (5.2.3 (e)) | | 16 h (5.2.3 (e)) |

CarCheck.co.uk page 3/11



report date: 2024-03-29

MOT #3 2022-11-07 12:23

MOT test number 214676467667

Result X Failed

Advice Offside Front Tyre worn close to legal limit/worn on edge on legal limit (5.2.3 (e))

Advice Rear Tyre slightly damaged/cracking or perishing both (5.2.3 (d) (ii))

Advice Nearside Front Tyre worn close to legal limit/worn on edge on legal limit 175 60 16 h (5.2.3 (e))

Fail Front Windscreen wiper does not clear the windscreen effectively (3.4 (b) (ii))

Advice Front Tyre slightly damaged/cracking or perishing both (5.2.3 (d) (ii))

MOT #2 2021-11-15 13:34

MOT test number 701217676337

Result \rightarrow Passed

Advice Tyre slightly damaged/cracking or perishing all (5.2.3 (d) (ii))

Advice Parking brake efficiency only just met. It would appear that the braking system requires adjustment or repair. (1.4.2 (a) (i))

Advice TPMS light on

MOT #1 2020-11-20 12:03

MOT test number 974230505610

CarCheck.co.uk page 4/11



report date: 2024-03-29

Tax & MOT check





Expires: 19 November 2024

| Tax status | Valid until 1 February |
|------------------|------------------------|
| Days left | 278 |
| MOT expiry date | 19 November 2024 |
| Full MOT history | See MOT history |

Tax calculation

CarCheck.co.uk page 5/11



report date: 2024-03-29

Damage history

Check the damage history for this SUZUKI. See if, where and when this SUZUKI had damage and the car repair costs. We also check if this SUZUKI was scrapped. Download the premium report here for the results.

Damage 1
Date
Category
Type
Damage 2
Date
Category
Type



Extra SUZUKI salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report <u>here</u> for more information.

More info >

CarCheck.co.uk page 6/11



report date: 2024-03-29

Vehicle valuation

What is this car worth? See the vehicle value of this SUZUKI in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value

Auction value

Average private trade value

More info >

CarCheck.co.uk page 7/11



Owner history

WU18ZDP

report date: 2024-03-29

For how long did the current and previous owner(s) have this SUZUKI? How many owners did this SUZUKI have? Check it in the premium report and see all owner registrations. Download the full report here. More info >

Plate changes

More info >

CarCheck.co.uk page 8/11



report date: 2024-03-29

Finance check

Check if this SUZUKI is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this SUZUKI has been settled.

If not, and you buy this SUZUKI then you could lose the money and the car you paid for.

Download the premium report <u>here</u> and check if this SUZUKI is financed.

| Finance company | |
|-------------------|--|
| Date of agreement | |
| Agreement type | |
| Agreement term | |
| Agreement number | |
| Contact info | |

Contact info

More info >

CarCheck.co.uk page 9/11



report date: 2024-03-29

Mileage check

| Odometer | In miles |
|----------------------------|------------|
| Mileage registrations | 7 |
| First mileage registration | 2018-03-01 |
| Last registration | 2023-11-20 |
| Complete history | See info |



| Registration #1 | 2018-03-01 | 20 mi |
|-----------------|------------|-----------|
| Registration #2 | 2020-11-20 | 7.185 mi |
| Registration #3 | | 11.777 es |
| Registration #4 | 2021-11-15 | 9.627 mi |
| Registration #5 | | 11.777 mi |
| Registration #6 | | 71,777 66 |
| Registration #7 | | 11.777 es |

More info >

CarCheck.co.uk page 10/11



report date: 2024-03-29

Safety ratings

| NCAP rating | **** |
|----------------|-----------------|
| Adult | 87% |
| Children | 79% |
| Pedestrian | 77% |
| Safety systems | 60% |
| Overall rating | 78% |
| Video | see crash video |



Dimensions & weight

| Width | 1690 mm |
|---------------------|---------|
| Height | 1595 mm |
| Length | 3700 mm |
| Wheel base | 2435 mm |
| Kerb weight | 885 kg |
| Max. allowed weight | 1330 kg |

Additional information

| Fuel tank capacity | 32 I |
|--------------------|-----------------------|
| Fuel delivery | Multi-Point Injection |
| Number of doors | 5 |
| Number of seats | 4 |
| Number of axles | 2 |
| Engine number | K12C-5248274 |

CarCheck.co.uk page 11/11