





General information

Make	DACIA
Model	LOGAN AMBIANCE SCE
Colour	White
Year of manufacture	2018
Top speed	98 mph
Gearbox	5 speed Manual

Engine & fuel consumption

		6
Power	72 BHP	0 < 101 A
Max. torque	97 Nm at 3.500 rpm	101 - 120
Engine capacity	998 cc	121 - 140
Cylinders	3	141 - 165
Fuel type	Petrol	166 - 185
Consumption city	42.8 mpg	186 - 225
Consumption extra urban	61.4 mpg	225+
Consumption combined	52.3 mpg	
CO2 emission	120 g/km	
CO2 label	С	



Internet history

Entry 1


Date Pictures 2021-05-26

Listing price

View report

9









source: autoonline.co.uk



MOT history

MOT expiry date	2024-07-06
MOT pass rate	57 %
MOT passed	4
Failed MOT tests	3
Total advice items	18
Total items failed	13

MOT #7	2023-07-07 12:37
MOT test number	824268506632
Result	✓ Passed
Next expiry date	2024-07-06
Advice O/s/f tyre wearing thin	

МОТ #6	2023-07-07 11:07
MOT test number	560310149481
Result	🗙 Failed
Fail Windscreen washer provides insufficient washer liquid (3.5 (a))	
Fail Nearside Front Headlamp aim projected beam image is obviously incorrect (4.1.2 (c)))
Fail Nearside Front Tyre tread depth below requirements of 1.6mm (5.2.3 (e))	
Advice O/s/f tyre wearing thin	
Fail Nearside Front Headlamp aim projected beam image is obviously incorrect (4.1.2 (c)))

MOT #5	2023-01-09 17:13
MOT test	number 956919964626
Result	✓ Passed
Minor (b) (i))	Nearside Registration plate lamp inoperative in the case of multiple lamps or light sources (4.7.1





MOT #4	2022-07-08 09:31
MOT test number	423873218268
Result	🗙 Failed
Advice Offside Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))	
Minor Nearside Rear Registration plate lamp inoperative in the case of multiple lamp (4.7.1 (b) (i))	os or light sources
FailExhaust carbon monoxide content after 2nd fast idle exceeds manufacturer's sp(a))	ecified limits (8.2.1.2
Advice Nearside Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))	
Fail Exhaust Lambda reading after 2nd fast idle outside specified limits (8.2.1.2 (c))	
Minor Windscreen damaged but not adversely affecting driver's view (3.2 (a) (i))	
Advice Offside Rear Road wheel slightly distorted (5.2.2 (c) (i))	





MOT #3	2022-07-05 08:23
MOT test number	860997594137
Result	🗙 Failed
Fail Exhaust Lambda reading after 2nd fast idle outside specified limits (8.2.1.2 (c))	
Minor Nearside Rear Registration plate lamp inoperative in the case of multiple lamps or l (4.7.1 (b) (i))	light sources
Advice Offside Rear Road wheel slightly distorted (5.2.2 (c) (i))	
Fail Engine MIL inoperative or indicates a malfunction (8.2.1.2 (h))	
Fail Offside Headlamp aim too low (4.1.2 (a))	
Advice Nearside Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))	
Fail Exhaust hydrocarbon content after 2nd fast idle exceeds manufacturer's specified lim	nits (8.2.1.2 (a))
Fail (a))Exhaust carbon monoxide content after 2nd fast idle exceeds manufacturer's specifie	d limits (8.2.1.2
Minor Windscreen damaged but not adversely affecting driver's view (3.2 (a) (i))	
Fail Nearside Headlamp aim too low (4.1.2 (a))	
Fail Nearside Front Headlamp levelling device inoperative (4.1.5 (a))	
Advice Offside Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))	

MOT #2	2021-06-23 08:19
MOT test number	673324924978
Result	✓ Passed
Advice Tyre slightly damaged/cracking or perishing all tyres (5.2.3 (d) (ii))	





MOT #1	2021	-05-07 15:36
MOT test	number 71	5489490913
Result		✓ Passed
Advice	Offside Front Tyre slightly damaged/cracking or perishing starting to perish (5.2.3 (d) (ii))
Advice	Offside Rear Tyre slightly damaged/cracking or perishing starting to perish (5.2.3 (d) (i	i))
Advice	Nearside Front Tyre slightly damaged/cracking or perishing starting to perish (5.2.3 (d)	(ii))
Advice	Nearside Rear Tyre slightly damaged/cracking or perishing starting to perish (5.2.3 (d)	(ii))



Tax & MOT check

✓ Taxed	√ МОТ
Tax due: 1 June 2024	Expires: 6 July 2024
Tax status	Valid until 1 June
Days left	34
MOT expiry date	6 July 2024
Full MOT history	See MOT history

Tax calculation

Vehicle class	48
Band	G
First licence fee (12 months)	£ 210,00,-
Standard rate (12 months)	£ 180,00,-
Standard rate (6 months)	£ 99,00,-
Premium rate (12 months)	£ 570,00,-
Premium rate (6 months)	£ 313,50,-





Damage history

Check the damage history for this DACIA. See if, where and when this DACIA had damage and the car repair costs. We also check if this DACIA was scrapped. Download the premium report <u>here</u> for the results.

Damage 1	
Date	FEIDO
Category	Lamp
Туре	
Damage 2	VAMPL
Date	
Category	AMP
Туре	

Extra DACIA salvage check

If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report <u>here</u> for more information.

More info \rightarrow





Vehicle valuation

What is this car worth? See the vehicle value of this DACIA in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	4 10.000
Auction value	4 10.000
Average private trade value	4

More info \rightarrow





Owner history

For how long did the current and previous owner(s) have this DACIA? How many owners did this DACIA have? Check it in the premium report and see all owner registrations. Download the full report <u>here</u>.

And a second sec	

	More info >
Plate changes	
See in this check if this DACIA had different number plates.	
Number of plates	
Carrent registration	
Plate since	
Carrent registration	
Plate since	





Finance check

Check if this DACIA is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this DACIA has been settled.

If not, and you buy this DACIA then you could lose the money and the car you paid for.

Download the premium report <u>here</u> and check if this DACIA is financed.

Finance company	
Date of agreement	
Agreement type	
Agreement term	
Agreement number	
Contact info	


More info \rightarrow





Mileage check

Odometer	In miles
Mileage registrations	9
First mileage registration	2018-05-17
Last registration	2023-07-07
Complete history	See info



Registration #1	2018-05-17	12 mi
Registration #2	2021-05-07	12.417 mi
Registration #3		11.777 esi
Registration #4	2021-06-23	12.585 mi
Registration #5	2022-07-05	62.725 mi
Registration #6		11.117 esi
Registration #7		11.117 esi
Registration #8		11.117 esi
Registration #9		11.777 esi

More info >



RO18HZE report date: 2024-03-28

Safety ratings

NCAP rating

Video

see crash video



Dimensions & weight	
Width	1994 mm
Height	1552 mm
Length	4501 mm
Wheel base	2635 mm
Kerb weight	1071 kg
Max. allowed weight	1555 kg
Additional information	
Additional information Fuel tank capacity	50 I
	50 l Multi-Point Injection
Fuel tank capacity	
Fuel tank capacity Fuel delivery	Multi-Point Injection
Fuel tank capacity Fuel delivery Number of doors	Multi-Point Injection 5