



report date: 2024-03-29

General information

Make	CITROEN
Model	DS3 HDI DSPORT PLUS
Colour	White
Year of manufacture	2011
Top speed	118 mph
Gearbox	5 speed Manual

Engine & fuel consumption

Power	110 BHP
Max. torque	270 Nm at 2.000 rpm
Engine capacity	1.560 cc
Cylinders	4
Fuel type	Diesel
Consumption city	52.3 mpg
Consumption extra urban	80.7 mpg
Consumption combined	67.3 mpg
CO2 emission	109 g/km
CO2 label	B






Internet history

Entry 1

Date	2021-06-17
Pictures	4
Listing price	View report



source: autotrader.co.uk





MOT history

MOT expiry date	2023-01-08
MOT pass rate	56 %
MOT passed	9
Failed MOT tests	7
Total advice items	31
Total items failed	19

MOT #16	2022-01-06 14:50
MOT test number	187619610289
Result	✓ Passed
Next expiry date	2023-01-08
Advice	Nearside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))
Advice	Rear under vehicle corrosion at chassis surface
Advice	Offside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))
Advice	Exhaust heat shield loose
Advice	Offside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))

**MOT #15**

2022-01-05 11:14

MOT test number

432221658290

Result**✗ Failed**

- Advice** Offside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))
- Fail** Registration plate lamp inoperative in the case of a single lamp or all lamps (4.7.1 (b) (ii))
- Advice** Rear under vehicle corrosion at chassis surface
- Fail** Nearside Rear Coil spring fractured or broken (5.3.1 (b) (i))
- Advice** Nearside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))
- Advice** Exhaust heat shield loose
- Advice** Offside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))
- Fail** Offside Front Headlamp aim projected beam image is obviously incorrect (4.1.2 (c))
- Fail** Front Brake disc significantly and obviously worn both sides (1.1.14 (a) (i))
- Fail** Nearside Front Tyre tread depth below requirements of 1.6mm (5.2.3 (e))

MOT #14

2021-01-09 10:07

MOT test number

156655665410

Result**✓ Passed**

- Advice** Rear Exhaust mounting defective (6.1.2 (a))
- Advice** Oil leak, but not excessive (8.4.1 (a) (i))
- Advice** Emission test wont register

**MOT #13**

2021-01-08 09:59

MOT test number

595170322862

Result**✗ Failed**

- Fail** Offside Front Track rod end ball joint has excessive play (2.1.3 (b) (i))
- Advice** Nearside Rear Brake pad(s) wearing thin (1.1.13 (a) (ii))
- Advice** Oil leak, but not excessive (8.4.1 (a) (i))
- Advice** Front Brake pad(s) wearing thin (1.1.13 (a) (ii))
- Advice** Rear Exhaust mounting defective (6.1.2 (a))
- Advice** Emission test wont register
- Fail** Nearside Rear Service brake excessively binding (1.2.1 (f))
- Fail** Offside Rear Brake pad(s) less than 1.5 mm thick (1.1.13 (a) (ii))
- Fail** Offside Front Headlamp aim projected beam image is obviously incorrect (4.1.2 (c))
- Advice** Front Brake pad(s) wearing thin (1.1.13 (a) (ii))
- Advice** Rear Brake disc worn, but not excessively both (1.1.14 (a) (i))

MOT #12

2019-07-09 13:54

MOT test number

340921249015

Result**✓ Passed**

- Advice** Emission test wont register
- Advice** Front Exhaust mounting defective (6.1.2 (a))

**MOT #11** 2019-07-09 13:03**MOT test number** 869828834941**Result** ✗ Failed**Advice** Emission test wont register**Advice** Front Exhaust mounting defective (6.1.2 (a))**Fail** Nearside Front Track rod end ball joint has excessive play (2.1.3 (b) (i))**MOT #10** 2018-06-11 12:26**MOT test number** 291192043353**Result** ✓ Passed**MOT #9** 2018-06-11 10:37**MOT test number** 966537196277**Result** ✓ Passed**MOT #8** 2017-04-20 14:52**MOT test number** 388684449080**Result** ✓ Passed**Advice** Front brake disc worn, pitted or scored, but not seriously weakened (3.5.1i)**Advice** Rear brake disc worn, pitted or scored, but not seriously weakened (3.5.1i)

**MOT #7** 2017-04-19 10:49**MOT test number** 266421946053**Result** ✗ Failed**Fail** Offside Stop lamp not working (1.2.1b)**Advice** Rear brake disc worn, pitted or scored, but not seriously weakened (3.5.1i)**Fail** Windscreen washer provides insufficient washer liquid (8.2.3)**Fail** Rear Exhaust system not adequately supported (7.1.1)**Advice** Front brake disc worn, pitted or scored, but not seriously weakened (3.5.1i)**MOT #6** 2016-03-12 08:30**MOT test number** 798134628732**Result** ✓ Passed**Advice** Rear silencer bracket broken exhaust still supported**MOT #5** 2016-03-12 08:15**MOT test number** 679388197932**Result** ✗ Failed**Fail** Offside Front Tyre tread depth below requirements of 1.6mm (4.1.E.1)**Advice** Rear silencer bracket broken exhaust still supported

**MOT #4** 2016-03-04 11:40**MOT test number** 376365369347**Result** ✗ Failed**Fail** Nearside Front Tyre tread depth below requirements of 1.6mm (4.1.E.1)**Advice** Rear silencer bracket broken exhaust still supported**Fail** Nearside Front Anti-roll bar has excessive play in a ball joint (2.4.G.2)**Fail** Offside Front Tyre tread depth below requirements of 1.6mm (4.1.E.1)**Fail** Offside Front Front constant velocity joint gaiter insecure to the extent that it no longer prevents the ingress of dirt etc (2.5.C.1a)**MOT #3** 2015-03-06 15:45**MOT test number** 878395465083**Result** ✓ Passed**MOT #2** 2014-08-04 11:13**MOT test number** 429396914227**Result** ✓ Passed**MOT #1** 2014-08-04 11:13**MOT test number** 607546514266**Result** ✗ Failed**Pass with rectification** Nearside Headlamp aim too low (1.8)



Tax & MOT check

✕
Untaxed

Tax expired:
31 December 2022

✕
MOT

Expired:
8 January 2023

Tax status	Expired at 31 December 2022
Days left	485 days too late
MOT expiry date	8 January 2023
Full MOT history	See MOT history

Tax calculation

Vehicle class	49
Band	B
Single payment (12 months)	£ 20,00,-
Single six month payment	Not applicable
Total payable by 12 monthly instalments	£ 21,00,-



Damage history

Check the damage history for this CITROEN. See if, where and when this CITROEN had damage and the car repair costs. We also check if this CITROEN was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	

Damage 2

Date	
Category	
Type	



Extra CITROEN salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this CITROEN in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,999
Auction value	£ 19,999
Average private trade value	£ 19,999

More info >



Owner history

For how long did the current and previous owner(s) have this CITROEN? How many owners did this CITROEN have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration

More info >

Plate changes

See in this check if this CITROEN had different number plates.

Number of plates	1
Current registration	SK61VEY
Plate since	2019-03-29
Current registration	SK61VEY
Plate since	2019-03-29

More info >



Finance check

Check if this CITROEN is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this CITROEN has been settled.

If not, and you buy this CITROEN then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this CITROEN is financed.


Finance company	XXXXXXXXXX	XXXX
Date of agreement	XXXXXXXXXX	XXXX
Agreement type	XXXXXXXXXX	XXXX
Agreement term	XXXXXXXXXX	XXXX
Agreement number	XXXXXXXXXX	XXXX
Contact info	XXXXXXXXXX	XXXX

More info >



Mileage check

Odometer	In miles
Mileage registrations	17
First mileage registration	2011-09-01
Last registration	2022-01-06
Complete history	See info



Registration #1	2011-09-01	24 mi
Registration #2	2014-08-04	27.180 mi
Registration #3	2015-03-06	31.012 mi
Registration #4	2016-03-04	44.456 mi
Registration #5	2016-03-12	44.715 mi
Registration #6	2016-03-12	44.715 mi
Registration #7	2017-04-19	56.162 mi
Registration #8	2017-04-20	56.164 mi
Registration #9	2018-06-11	64.399 mi
Registration #10	2019-06-20	75.277 mi
Registration #11	2019-06-20	75.277 mi
Registration #12	2019-06-20	75.277 mi
Registration #13	2019-06-20	75.277 mi
Registration #14	2019-06-20	75.277 mi
Registration #15	2019-06-20	75.277 mi
Registration #16	2019-06-20	75.277 mi
Registration #17	2019-06-20	75.277 mi

More info >



Safety ratings

NCAP rating	★★★★★
Adult	87%
Children	71%
Pedestrian	35%
Safety systems	83%
Overall rating	73%
Video	see crash video



Dimensions & weight

Width	1715 mm
Height	1483 mm
Length	3948 mm
Wheel base	2464 mm
Kerb weight	1172 kg
Max. allowed weight	1612 kg

Additional information

Fuel delivery	Direct Injection
Number of doors	3
Number of seats	5
Number of axles	2
Engine number	JBEF3008982