





report date: 2024-03-29

General information

Make	HYUNDAI
Model	IX35 GDI S
Colour	Black
Year of manufacture	2014
Top speed	111 mph
0 - 60 mph	11.1 seconds
Gearbox	6 speed Manual

Engine & fuel consumption

Power	133 BHP
Max. torque	165 Nm at 4.850 rpm
Engine capacity	1.591 cc
Cylinders	4
Fuel type	Petrol
Consumption city	34.5 mpg
Consumption extra urban	47.1 mpg
Consumption combined	41.5 mpg
CO2 emission	158 g/km
CO2 label	G



CarCheck.co.uk page 1/11



report date: 2024-03-29

Internet history

Entry 1

Date 2021-06-04

Pictures 19

Listing price <u>View report</u>









source: autotrader.co.uk

CarCheck.co.uk page 2/11



report date: 2024-03-29

N/I	α		uc:	t۸	r\/
101	•		115	w	ıv
	•	Γh			. ,

MOT expiry date	2024-07-25
MOT pass rate	78 %
MOT passed	7
Failed MOT tests	2
Total advice items	8
Total items failed	5

MOT #9	2023-07-21 16:33
MOT test number	198811760948
Result	✓ Passed
Next expiry date	2024-07-25
Advice Rear Registration plate deteriorated but not likely to be misread (0.1 (b))	

MOT #8	2023-07-19 15:13	
MOT test number	224692130144	
Result	X Failed	
Fail Front Brake pad(s) less than 1.5 mm thick (1.1.13 (a) (ii))		
Advice Nearside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))		
Fail Tyre pressure monitoring system malfunctioning or obviously inoperative (5.2.3	(h))	
Advice Front Brake disc worn, pitted or scored, but not seriously weakened both sides (1.1.14 (a) (ii))		
Advice Rear Brake pad(s) wearing thin (1.1.13 (a) (ii))		
Advice Offside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))		
Advice Rear Registration plate deteriorated but not likely to be misread (0.1 (b))		

MOT #7	2022-07-26 08:59
MOT test number	319275786682
Result	✓ Passed

CarCheck.co.uk page 3/11



report date: 2024-03-29

MOT #	6	2022-07-18 15:11
MOT te	est number	151876611035
Result		× Failed
Fail	Offside Rear Shock absorbers has a serious fluid leak (5.3.2 (b))	
Fail	Nearside Front Tyre tread depth below requirements of 1.6mm (5.2.3 (e))	
Fail	Offside Front Tyre tread depth below requirements of 1.6mm (5.2.3 (e))	
Advic	Offside Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))	

MOT #5	2021-07-07 09:31
MOT test number	750051670337
Result	✓ Passed
MOT #4	2020-09-26 09:29
MOT test number	629723324563
Result	✓ Passed
Advice Rear tyres slightly perished and cracked	

MOT #3	2019-09-21 11:12
MOT test number	225876789567
Result	✓ Passed
MOT #2	2018-09-26 13:56

MOT #2	2018-09-26 13:56
MOT test number	257377207563
Result	✓ Passed

MOT #1	2017-09-04 07:36
MOT test number	256667905295
Result	✓ Passed

CarCheck.co.uk page 4/11



report date: 2024-03-29

Tax & MOT check



Tax status	Valid until 1 October
Days left	154
MOT expiry date	25 July 2024
Full MOT history	See MOT history

Tax calculation

Vehicle class	48
Band	G
Single payment (12 months)	£ 240,00,-
Single six month payment	£ 132,00,-
Total payable by 12 monthly instalments	£ 252,00,-

CarCheck.co.uk page 5/11



report date: 2024-03-29

Damage history

Check the damage history for this HYUNDAI. See if, where and when this HYUNDAI had damage and the car repair costs. We also check if this HYUNDAI was scrapped. Download the premium report here for the results.

Damage 1	
Date	
Category	
Туре	
Damage 2	
Date	
Category	
Type	



Extra HYUNDAI salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report <u>here</u> for more information.

More info >

CarCheck.co.uk page 6/11



MA64LHL report date: 2024-03-29

Vehicle valuation

What is this car worth? See the vehicle value of this HYUNDAI in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value

Auction value

Average private trade value

More info >

CarCheck.co.uk page 7/11



report date: 2024-03-29

Owner history

For how long did the current and previous owner(s) have this HYUNDAI? How many owner have? Check it in the premium report and see all owner registrations. Download the full is	
	More info >
Plate changes	
See in this check if this HYUNDAI had different number plates.	
Number of plates	,
Current registration	AK UK
Plate since	
Current registration	NE ZIS UK
Plate since	
	More info >

CarCheck.co.uk page 8/11



report date: 2024-03-29

Finance check

Check if this HYUNDAI is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this HYUNDAI has been settled.

If not, and you buy this HYUNDAI then you could lose the money and the car you paid for.

Download the premium report <u>here</u> and check if this HYUNDAI is financed.

Finance company	
Date of agreement	
Agreement type	
Agreement term	
Agreement number	

Contact info

More info >


CarCheck.co.uk page 9/11



MA64LHL report date: 2024-03-29

Mileage check

Odometer	In miles
Mileage registrations	11
First mileage registration	2014-09-24
Last registration	2023-07-21
Complete history	See info



Registration #1	2014-09-24	10 mi
Registration #2	2017-09-04	24.962 mi
Registration #3	2018-09-26	28.584 mi
Registration #4	2019-09-21	33.625 mi
Registration #5	2020-09-26	37.360 mi
Registration #6		11.777 es
Registration #7		11.777 es
Registration #8		11.777 es
Registration #9		11.777 es
Registration #10		11.777 es
Registration #11		11.777 es

More info >

CarCheck.co.uk page 10/11



MA64LHL report date: 2024-03-29

Car features

S0225	Air conditionin
50295	
50482	
50501	
60566	
50567	
50569	

Safety ratings

NCAP rating	****
Adult	90%
Children	88%
Pedestrian	54%
Safety systems	71%
Overall rating	81%
Video	see crash video



Dimensions & weight

Width	1820 mm
Height	1655 mm
Length	4410 mm
Wheel base	2640 mm
Kerb weight	1427 kg
Max. allowed weight	1830 kg

Additional information

Fuel tank capacity	58 I
Fuel delivery	Multi-Point Injection
Number of doors	5
Number of seats CarCheck.co.uk	5 page 11/1

Number of axles 2

Engine number G4FDEZ867300