





report date: 2024-03-28

General information

Make	FIAT
Model	PANDA EASY
Colour	White
Year of manufacture	2014
Top speed	99 mph
0 - 60 mph	14.2 seconds
Gearbox	5 speed Manual

Engine & fuel consumption

Power	69 BHP
Max. torque	102 Nm at 3.000 rpm
Engine capacity	1.242 cc
Cylinders	4
Fuel type	Petrol
Consumption city	42.2 mpg
Consumption extra urban	65.7 mpg
Consumption combined	54.3 mpg
CO2 emission	120 g/km
CO2 label	С



CarCheck.co.uk page 1/12



report date: 2024-03-28

Internet history

Entry 1

Date 2021-07-06

Pictures 42

Listing price <u>View report</u>









source: autotrader.co.uk

CarCheck.co.uk page 2/12



report date: 2024-03-28

	_				
11/1/	TC	n		$\overline{}$	r\/
IVIL	, ,		51	LU.	ıv
					. ,

MOT expiry date	2024-05-15
MOT pass rate	70 %
MOT passed	7
Failed MOT tests	3
Total advice items	14
Total items failed	5

MOT #10	2023-05-16 08:07
MOT test number	655361085568
Result	✓ Passed
Next expiry date	2024-05-15

MOT #9	2022-07-21 10:38
MOT test number	268073366249
Result	✓ Passed
Minor Offside Registration plate lamp inoperative in the case of multiple lamps or li	ight sources (4.7.1 (b)
Advice Nearside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))	
Advice Offside Front Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))	
Advice Offside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))	

MOT #8	2021-07-19 14:09
MOT test number	678191003605
Result	✓ Passed

MOT #7	2021-07-19 14:09
MOT test number	476752229305
Result	★ Failed
Pass with rectification (4.7.1 (b) (ii))	Registration plate lamp inoperative in the case of a single lamp or all lamps

CarCheck.co.uk page 3/12



report date: 2024-03-28

MOT test number

668889940488

Result

Advice

Nearside Rear Nail in tyre

Advice

Nearside Rear Shock absorbers light misting of oil or has limited damping effect (5.3.2 (b))

Advice

Offside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))

Advice

Items removed from driver's view prior to test

MOT #5

MOT test number

2019-11-13 12:59

MOT test number

213771160026

Result

✓ Passed

Advice

Underside covers/under trays fitted limiting visual inspection of some items

MOT #4 2019-11-13 10:44 274504281140 **MOT** test number Result Failed Underside covers/under trays fitted limiting visual inspection of some items **Advice** Fail Nearside Front Windscreen wiper does not clear the windscreen effectively (3.4 (b) (ii)) Fail Nearside Rear Tyre has ply or cords exposed cut exposing cords (5.2.3 (d) (ii)) Fail Front Brake pad(s) less than 1.5 mm thick offside front inner pad (1.1.13 (a) (ii)) **Advice** Nearside Rear Nail in tyre Advice Nearside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e)) Minor Nearside Rear Tyre obviously under inflated (5.2.3 (I))

MOT #3	2018-11-19 13:49
MOT test number	177316662645
Result	✓ Passed

CarCheck.co.uk page 4/12



MOT #2 2018-11-19 12:22 MOT test number 117231018611

Result × Failed

Fail Offside Front Tyre tread depth below requirements of 1.6mm (5.2.3 (e))

Advice Nearside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))

MOT #1 2017-09-22 10:44

MOT test number 744788639424

Result

Passed

CarCheck.co.uk page 5/12



Tax & MOT check



Tax status	Valid until 1 June
Days left	32
MOT expiry date	15 May 2024
Full MOT history	See MOT history

Tax calculation

Vehicle class	48
Band	С
Single payment (12 months)	£ 35,00,-
Single six month payment	Not applicable
Total payable by 12 monthly instalments	£ 36,75,-

CarCheck.co.uk page 6/12



report date: 2024-03-28

Damage history

Check the damage history for this FIAT. See if, where and when this FIAT had damage and the car repair costs. We also check if this FIAT was scrapped. Download the premium report <u>here</u> for the results.

Damage 1	
Date	
Category	
Туре	
Damage 2	
Date	
Category	
Туре	



Extra FIAT salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report <u>here</u> for more information.

More info >

CarCheck.co.uk page 7/12



Vehicle valuation

What is this car worth? See the vehicle value of this FIAT in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value

Auction value

Average private trade value

More info >

CarCheck.co.uk page 8/12



Owner history

For how long did the current and previous owner(s) have this FIAT? How many owners did Check it in the premium report and see all owner registrations. Download the full report <u>I</u>	

	More info >
Plate changes	
See in this check if this FIAT had different number plates.	
Number of plates	,
Current registration	NK NK
Plate since	m-o-o
Current registration	UK UK
Plate since	
	More info >

CarCheck.co.uk page 9/12



report date: 2024-03-28

Finance check

Check if this FIAT is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this FIAT has been settled.

If not, and you buy this FIAT then you could lose the money and the car you paid for.

Download the premium report <u>here</u> and check if this FIAT is financed.

Finance company	
Date of agreement	
Agreement type	
Agreement term	
Agreement number	
Contact info	

Contact info

More info >

CarCheck.co.uk page 10/12



report date: 2024-03-28

Mileage check

Odometer	In miles
Mileage registrations	12
First mileage registration	2014-12-03
Last registration	2023-05-16
Complete history	See info



Registration #1	2014-12-03	24 mi
Registration #2	2017-09-22	21.390 mi
Registration #3	2018-11-19	25.909 mi
Registration #4	2018-11-19	25.909 mi
Registration #5	2019-11-13	27.525 mi
Registration #6	2019-11-13	27.525 mi
Registration #7		11.777 es
Registration #8		11.777 es
Registration #9		11.777 es
Registration #10		11.777 es
Registration #11		11.777 es
Registration #12		

More info >

CarCheck.co.uk page 11/12



Car features

S0225	Air conditioning
S0295	
S0482	
S0501	
50566	
50567	
50569	

Safety ratings

NCAP rating	****
Adult	82%
Children	63%
Pedestrian	49%
Safety systems	43%
Overall rating	68%
Video	see crash video



Dimensions & weight

Width	1643 mm
Height	1551 mm
Length	3653 mm
Wheel base	2300 mm
Kerb weight	1015 kg
Max. allowed weight	1420 kg

Additional information

Fuel tank capacity	37 I
Fuel delivery	Multi-Point Injection
Number of doors	5
Number of seats CarCheck.co.uk	4 page 12/12

Number of axles 2

Engine number 0839737