



HYUNDAI



report date: 2024-03-28

General information

Make	HYUNDAI
Model	I30 COMFORT
Colour	Black
Year of manufacture	2011
Top speed	116 mph
0 - 60 mph	11.6 seconds
Gearbox	5 speed Manual

Engine & fuel consumption

Power	108 BHP
Max. torque	137 Nm at 5.000 rpm
Engine capacity	1.396 cc
Cylinders	4
Fuel type	Petrol
Consumption city	37.7 mpg
Consumption extra urban	53.3 mpg
Consumption combined	46.3 mpg
CO2 emission	142 g/km
CO2 label	F





Internet history

Entry 1

Date	2021-01-31
Pictures	10
Listing price	View report



source: [autoonline.co.uk](#)



MOT history

MOT expiry date	2025-01-21
MOT pass rate	59 %
MOT passed	10
Failed MOT tests	7
Total advice items	24
Total items failed	17

MOT #17	2024-01-09 16:09
MOT test number	394761907758
Result	✓ Passed
Next expiry date	2025-01-21
Advice	Front registration plate damaged
Advice	Nearside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))
Advice	Exhaust rear silencer box support bracket deteriorated

MOT #16	2024-01-09 11:32
MOT test number	625618348807
Result	✗ Failed
Fail	Nearside Stop lamp(s) not working (4.3.1 (a) (ii))
Fail	Front Brakes imbalanced across an axle both brake discs worn (1.2.1 (b) (i))
Advice	Exhaust rear silencer box support bracket deteriorated
Advice	Nearside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))
Fail	Offside Front Position lamp not working (4.2.1 (a) (ii))
Fail	Offside Stop lamp(s) not working (4.3.1 (a) (ii))
Fail	Rear Brakes imbalanced across an axle both brake discs worn (1.2.1 (b) (i))
Advice	Front registration plate damaged

**MOT #15**

2023-01-16 15:55

MOT test number

481461012737

Result

✓ Passed

Advice

Rear Exhaust mounting defective (6.1.2 (a))

MOT #14

2023-01-16 11:52

MOT test number

132523307237

Result

✗ Failed

Fail

Offside Front Tyre tread depth below requirements of 1.6mm (5.2.3 (e))

Advice

Rear Exhaust mounting defective (6.1.2 (a))

MOT #13

2022-01-18 11:24

MOT test number

954744508525

Result

✓ Passed

Advice

Nearside Rear Suspension arm pin or bush worn but not resulting in excessive movement Trailing arm bushes (5.3.4 (a) (i))

Advice

Travel in handbrake lever.

Advice

Nearside Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))

Advice

Offside Rear Suspension arm pin or bush worn but not resulting in excessive movement Trailing arm bushes (5.3.4 (a) (i))

Advice

Child Seat fitted not allowing full inspection of adult belt

**MOT #12**

2022-01-17 14:32

MOT test number

490226301735

Result**✗ Failed****Fail** Nearside Front Direction indicator incorrect colour (4.4.3 (a))**Advice** Offside Rear Suspension arm pin or bush worn but not resulting in excessive movement Trailing arm bushes (5.3.4 (a) (i))**Advice** Child Seat fitted not allowing full inspection of adult belt**Minor** Offside Registration plate lamp inoperative in the case of multiple lamps or light sources (4.7.1 (b) (i))**Advice** Nearside Rear Suspension arm pin or bush worn but not resulting in excessive movement Trailing arm bushes (5.3.4 (a) (i))**Fail** Offside Front Suspension arm pin or bush excessively worn front bush (5.3.4 (a) (i))**Advice** Travel in handbrake lever.**Advice** Nearside Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))**MOT #11**

2021-01-22 15:54

MOT test number

494481910361

Result**✓ Passed****Advice** Nearside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))**MOT #10**

2021-01-19 15:00

MOT test number

903661856011

Result**✗ Failed****Fail** Nearside Rear Brake pad(s) less than 1.5 mm thick (1.1.13 (a) (ii))**Fail** Offside Front Upper Anti-roll bar linkage ball joint dust cover no longer prevents the ingress of dirt (5.3.4 (b) (ii))**Advice** Nearside Front Tyre worn close to legal limit/worn on edge outer edge worn. (5.2.3 (e))**Fail** Offside Rear Brake pad(s) less than 1.5 mm thick (1.1.13 (a) (ii))**Fail** Nearside Front Upper Anti-roll bar linkage ball joint dust cover no longer prevents the ingress of dirt (5.3.4 (b) (ii))

**MOT #9** 2019-07-03 12:24**MOT test number** 723331445273**Result** ✓ Passed**MOT #8** 2019-07-02 09:45**MOT test number** 138798094016**Result** ✗ Failed**Fail** Front Brakes imbalanced across an axle by more than 50% (1.2.1 (b) (ii))**MOT #7** 2018-06-15 09:13**MOT test number** 927779744758**Result** ✓ Passed**Advice** Nearside Parking (secondary brake) grabbing slightly (1.3.1 (c))**MOT #6** 2018-06-15 09:13**MOT test number** 807045544063**Result** ✗ Failed**Pass with rectification** Nearside Position lamp not working (4.2.1 (a))**Pass with rectification** Nearside Stop lamp(s) all not working (4.3.1 (a) (iii))**Pass with rectification** Nearside Registration plate lamp inoperative in the case of a single lamp or all lamps (4.7.1 (b) (ii))**Advice** Nearside Parking (secondary brake) grabbing slightly (1.3.1 (c))**MOT #5** 2017-07-05 13:54**MOT test number** 701266365462**Result** ✓ Passed**Advice** Nearside Rear nsr brake sticking slightly



MOT #4	2016-07-15 10:34
MOT test number	747041949724
Result	✓ Passed
MOT #3	2016-07-15 10:34
MOT test number	919759766911
Result	✗ Failed
<div>Pass with rectification</div> Nearside Stop lamp not working (1.2.1b)	
MOT #2	2015-08-27 10:52
MOT test number	421588025845
Result	✓ Passed
MOT #1	2014-09-15 12:44
MOT test number	527808854243
Result	✓ Passed



Tax & MOT check

✓
Taxed
Tax due:
1 February 2025

✓
MOT
Expires:
21 January 2025

Tax status	Valid until 1 February
Days left	278
MOT expiry date	21 January 2025
Full MOT history	See MOT history

Tax calculation

Vehicle class	48
Band	F
Single payment (12 months)	£ 200,00,-
Single six month payment	£ 110,00,-
Total payable by 12 monthly instalments	£ 210,00,-



Damage history

Check the damage history for this HYUNDAI. See if, where and when this HYUNDAI had damage and the car repair costs. We also check if this HYUNDAI was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	

Damage 2

Date	
Category	
Type	



Extra HYUNDAI salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this HYUNDAI in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,999
Auction value	£ 19,999
Average private trade value	£ 19,999

More info >



Owner history

For how long did the current and previous owner(s) have this HYUNDAI? How many owners did this HYUNDAI have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration

More info >

Plate changes

See in this check if this HYUNDAI had different number plates.

Number of plates	1
Current registration	EX61NPO
Plate since	2019-03-28
Current registration	EX61NPO
Plate since	2019-03-28

More info >



Finance check

Check if this HYUNDAI is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this HYUNDAI has been settled.

If not, and you buy this HYUNDAI then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this HYUNDAI is financed.

Finance company	XXXXXXXX XX
Date of agreement	XXXXXXXX XX
Agreement type	XXXXXXXX XX
Agreement term	XXXXXXXX XX
Agreement number	XXXXXXXX XX
Contact info	XXXXXXXX XX

More info >



Mileage check

Odometer	In miles
Mileage registrations	19
First mileage registration	2011-09-13
Last registration	2024-01-09
Complete history	See info



Registration #1	2011-09-13	9 mi
Registration #2	2014-09-15	38.985 mi
Registration #3	2015-08-27	51.240 mi
Registration #4	2016-07-15	60.678 mi
Registration #5	2016-07-15	60.678 mi
Registration #6	2017-07-05	72.786 mi
Registration #7	2018-06-15	85.095 mi
Registration #8	2018-06-15	85.095 mi
Registration #9	2019-07-02	98.727 mi
Registration #10	2019-07-03	98.727 mi
Registration #11	2019-07-03	98.727 mi
Registration #12	2019-07-03	98.727 mi
Registration #13	2019-07-03	98.727 mi
Registration #14	2019-07-03	98.727 mi
Registration #15	2019-07-03	98.727 mi
Registration #16	2019-07-03	98.727 mi
Registration #17	2019-07-03	98.727 mi
Registration #18	2019-07-03	98.727 mi
Registration #19	2019-07-03	98.727 mi

More info >



Car features

The HYUNDAI factory car options list is only available in the premium report.

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

View the complete HYUNDAI factory list for this vehicle [here](#).

More info >

Safety ratings

NCAP rating ★★★★★

Video [see crash video](#)



Dimensions & weight

Width	1775 mm
Height	1480 mm
Length	4280 mm
Wheel base	2650 mm
Kerb weight	1293 kg
Max. allowed weight	1720 kg

Additional information

Fuel delivery	Multi-Point Injection
Number of doors	5
Number of seats	5
Number of axles	2

Engine number	G4FABZ349089
---------------	--------------