



CITROËN



report date: 2024-03-29

## General information

Make	CITROEN
Model	C4 BLUEHDI FLAIR
Colour	Green
Year of manufacture	2016
Top speed	114 mph
0 - 60 mph	10.6 seconds
Gearbox	5 speed Manual

## Engine & fuel consumption

Power	98 BHP
Max. torque	254 Nm at 1.750 rpm
Engine capacity	1.560 cc
Cylinders	4
Fuel type	Diesel
Consumption city	67.3 mpg
Consumption extra urban	85.6 mpg
Consumption combined	78.5 mpg
CO2 emission	95 g/km
CO2 label	A





Internet history

Entry 2


Date	2021-10-17
Pictures	12
Listing price	<a href="#">View report</a>



source: cargurus.co.uk

Entry 1

Date	2021-10-15
Pictures	29
Listing price	<a href="#">View report</a>



source: autotrader.co.uk



MOT history

MOT expiry date	2025-04-23
MOT pass rate	67 %
MOT passed	6
Failed MOT tests	3
Total advice items	36
Total items failed	11

MOT #9	2024-04-16 15:19
MOT test number	929650376146
Result	✓ Passed
Next expiry date	2025-04-23
Advice	Front Exhaust has a minor leak of exhaust gases flexy (6.1.2 (a))
Advice	Nearside Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))
Advice	Exhaust system is corroded
Advice	Oil leak, but not excessive (8.4.1 (a) (i))
Advice	Tyre worn close to legal limit/worn on edge all tyres (5.2.3 (e))
Advice	Offside Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))
Advice	Front wipers smeary

**MOT #8**

2024-04-15 09:23

**MOT test number**

543733067932

**Result****✗ Failed**

**Advice** Rear Brakes imbalanced requirements only just met. It would appear that the braking system requires adjustment or repair. (1.2.1 (b) (i))

**Advice** Tyre worn close to legal limit/worn on edge all tyres (5.2.3 (e))

**Fail** Engine MIL inoperative or indicates a malfunction (8.2.1.2 (h))

**Advice** Tyre pressure light on

**Advice** Offside Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))

**Fail** Emissions unable to be completed due to air leak on turbo (8.2.2.2 (e))

**Advice** Turbo air inlet hose damaged and insecure, leaking oil

**Minor** Offside Rear Registration plate lamp inoperative in the case of multiple lamps or light sources (4.7.1 (b) (i))

**Fail** Offside Front Outer Drive shaft joint constant velocity boot split or insecure, no longer prevents the ingress of dirt (6.1.7 (g) (ii))

**Advice** Exhaust system is corroded

**Advice** Front Exhaust has a minor leak of exhaust gases flexy (6.1.2 (a))

**Advice** Nearside Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))

**Fail** Nearside Front Headlamp aim projected beam image is obviously incorrect (4.1.2 (c))

**Advice** Front wipers smeary

**Advice** Oil leak, but not excessive (8.4.1 (a) (i))

**Advice** Rear exhaust mount broken

**Fail** Nearside Front Lower Suspension arm ball joint excessively worn (5.3.4 (a) (i))

**MOT #7**

2023-04-24 09:12

**MOT test number**

972369618250

**Result****✓ Passed**

**Advice** Oil leak, but not excessive (8.4.1 (a) (i))

**MOT #6**

2023-04-18 09:01

**MOT test number**

962880822577

**Result****✗ Failed**

- Advice** Oil leak, but not excessive (8.4.1 (a) (i))
- Fail** Nearside Windscreen wiper does not clear the windscreen effectively (3.4 (b) (ii))
- Fail** Nearside Headlamp not working on dipped beam (4.1.1 (a) (ii))
- Fail** Parking brake efficiency below requirements (1.4.2 (a) (i))
- Minor** Nearside Registration plate lamp inoperative in the case of multiple lamps or light sources (4.7.1 (b) (i))
- Fail** Offside Parking brake inoperative on one side (1.4.1 (a))

**MOT #5**

2022-04-05 15:28

**MOT test number**

850330351280

**Result****✓ Passed**

- Advice** Offside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))
- Advice** Nearside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))
- Advice** Front Inner Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))

**MOT #4**

2021-04-09 09:27

**MOT test number**

784468600353

**Result****✓ Passed**

- Advice** Oil leak, but not excessive (8.4.1 (a) (i))
- Advice** Nearside Front Brake disc worn, pitted or scored, but not seriously weakened inner face (1.1.14 (a) (ii))
- Advice** Undertrays fitted
- Advice** Offside Rear Service brake binding but not excessively (1.2.1 (f))
- Advice** Offside Front Brake disc worn, pitted or scored, but not seriously weakened inner face (1.1.14 (a) (ii))

**MOT #3** 2020-04-22 08:41**MOT test number** 822252183964**Result** ✓ Passed**Advice** Undertrays fitted**Advice** Oil leak, but not excessive (8.4.1 (a) (i))**MOT #2** 2020-03-07 15:13**MOT test number** 974507933520**Result** ✗ Failed**Advice** Nearside Rear Child Seat fitted not allowing full inspection of adult belt**Advice** Nearside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))**Advice** No detectable emissions at time of test**Fail** Nearside Front Tyre not fitted in accordance with side wall instructions (5.2.3 (i))**Fail** Offside Front Tyre has a tear, caused by separation or partial failure of its structure (5.2.3 (d) (ii))**Advice** Offside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))**MOT #1** 2019-03-01 10:40**MOT test number** 364734835876**Result** ✓ Passed



Tax & MOT check

✓  
**Taxed**  
**Tax due:**  
1 April 2025

✓  
**MOT**  
**Expires:**  
23 April 2025

<b>Tax status</b>	Valid until 1 April
<b>Days left</b>	336
<b>MOT expiry date</b>	23 April 2025
<b>Full MOT history</b>	<a href="#">See MOT history</a>

Tax calculation

<b>Vehicle class</b>	49
<b>Band</b>	A
<b>Single payment (12 months)</b>	£ 0,00,-
<b>Single six month payment</b>	Not applicable
<b>Total payable by 12 monthly instalments</b>	Not applicable



Damage history

Check the damage history for this CITROEN. See if, where and when this CITROEN had damage and the car repair costs. We also check if this CITROEN was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	

Damage 2

Date	
Category	
Type	



Extra CITROEN salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >





Vehicle valuation

What is this car worth? See the vehicle value of this CITROEN in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 15,200
Auction value	£ 15,200
Average private trade value	£ 15,200

More info >



Owner history

For how long did the current and previous owner(s) have this CITROEN? How many owners did this CITROEN have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since

More info >

Plate changes

See in this check if this CITROEN had different number plates.

Number of plates	1
Current registration	<b>XXXXXX</b>
Plate since	2024-03-29
Current registration	<b>XXXXXX</b>
Plate since	2024-03-29

More info >



Finance check

Check if this CITROEN is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this CITROEN has been settled.

If not, and you buy this CITROEN then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this CITROEN is financed.

Finance company	XXXXXXXX	XXXX
Date of agreement	XXXXXXXX	XXXX
Agreement type	XXXXXXXX	XXXX
Agreement term	XXXXXXXX	XXXX
Agreement number	XXXXXXXX	XXXX
Contact info	XXXXXXXX	XXXX

More info >



Mileage check

Odometer	In miles
Mileage registrations	12
First mileage registration	2016-03-10
Last registration	2024-04-16
Complete history	<a href="#">See info</a>



Registration #1	2016-03-10	29 mi
Registration #2	2019-03-01	38.066 mi
Registration #3	2020-03-07	48.057 mi
Registration #4	2020-04-22	48.576 mi
Registration #5	2021-04-09	55.750 mi
Registration #6	2022-03-29	55.750 mi
Registration #7	2022-03-29	55.750 mi
Registration #8	2022-03-29	55.750 mi
Registration #9	2022-03-29	55.750 mi
Registration #10	2022-03-29	55.750 mi
Registration #11	2022-03-29	55.750 mi
Registration #12	2022-03-29	55.750 mi

More info >



Safety ratings

NCAP rating	★★★★★
Adult	90%
Children	85%
Pedestrian	43%
Safety systems	97%
Overall rating	80%
Video	<a href="#">see crash video</a>



Dimensions & weight

Width	1729 mm
Height	1480 mm
Length	4157 mm
Wheel base	2595 mm
Kerb weight	1068 kg
Max. allowed weight	1610 kg

Additional information

Fuel tank capacity	45 l
Fuel delivery	Direct Injection
Number of doors	5
Number of seats	5
Number of axles	2
Engine number	JBHA0116115