



report date: 2024-03-28

General information

Make	SUZUKI
Model	SX4 SZ4
Colour	White
Year of manufacture	2014
Top speed	112 mph
0 - 60 mph	11.0 seconds
Gearbox	5 speed Manual

Engine & fuel consumption

Power	118 BHP
Max. torque	156 Nm at 4.400 rpm
Engine capacity	1.586 cc
Cylinders	4
Fuel type	Petrol
Consumption city	41.5 mpg
Consumption extra urban	58.9 mpg
Consumption combined	51.4 mpg
CO2 emission	127 g/km
CO2 label	D





Internet history

Entry 1

Date	2021-02-04
Pictures	0
Listing price	<a href="#">View report</a>

source: [autoonline.co.uk](#)



MOT history

MOT expiry date	2025-05-03
MOT pass rate	80 %
MOT passed	8
Failed MOT tests	2
Total advice items	18
Total items failed	0

MOT #10	2024-04-25 13:31
MOT test number	699151822203
Result	✓ Passed
Next expiry date	2025-05-03
Advice	Nearside Rear Road wheel slightly distorted (5.2.2 (c) (i))
Advice	Nearside Front Road wheel slightly distorted (5.2.2 (c) (i))

MOT #9	2024-04-25 09:10
MOT test number	463420356397
Result	✗ Failed
MAJOR	Nearside Rear Tyre(s) with different aspect ratios are fitted on the same axle. (5.2.3 (b))
Advice	Nearside Rear Road wheel slightly distorted (5.2.2 (c) (i))
DANGEROUS	Nearside Rear Tyre has a lump, caused by separation or partial failure of its structure (5.2.3 (d) (ii))
MAJOR	Registration plate lamp inoperative in the case of a single lamp or all lamps (4.7.1 (b) (ii))
Advice	Nearside Front Road wheel slightly distorted (5.2.2 (c) (i))

**MOT #8** 2023-05-02 09:04**MOT test number** 653569540032**Result** ✓ Passed**Advice** Offside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))**Advice** Offside Front Tyre slightly damaged (5.2.3 (d) (ii))**MOT #7** 2022-05-04 12:55**MOT test number** 652174721522**Result** ✓ Passed**Advice** Nearside Front Wheel bearing has slight play (5.1.3 (a) (i))**MOT #6** 2021-04-27 11:56**MOT test number** 783272185456**Result** ✓ Passed**MOT #5** 2020-12-08 10:23**MOT test number** 441138575589**Result** ✗ Failed**Advice** Nearside Front Wheel bearing has slight play (5.1.3 (a) (i))**DANGEROUS** Nearside Rear Brake pad(s) less than 1.5 mm thick (1.1.13 (a) (ii))**Minor** Offside Registration plate lamp inoperative in the case of multiple lamps or light sources (4.7.1 (b) (i))**Advice** Nearside Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))**MAJOR** Nearside Rear Shock absorbers has a serious fluid leak (5.3.2 (b))**Advice** Offside Rear Brake pad(s) wearing thin (3mm) (1.1.13 (a) (ii))

**MOT #4** 2020-07-09 09:51**MOT test number** 611263744699**Result** ✓ Passed

**Minor** Offside Rear Registration plate lamp inoperative in the case of multiple lamps or light sources  
(4.7.1 (b) (i))

**MOT #3** 2019-06-03 09:08**MOT test number** 579866552056**Result** ✓ Passed**MOT #2** 2018-05-24 16:25**MOT test number** 156338115306**Result** ✓ Passed

**Advice** Tyre worn close to legal limit/worn on edge (5.2.3 (e))

**MOT #1** 2017-05-15 11:59**MOT test number** 803504422480**Result** ✓ Passed



Tax & MOT check

✓  
**Taxed**  
**Tax due:**  
1 May 2025

✓  
**MOT**  
**Expires:**  
3 May 2025

<b>Tax status</b>	Valid until 1 May
<b>Days left</b>	367
<b>MOT expiry date</b>	3 May 2025
<b>Full MOT history</b>	<a href="#">See MOT history</a>

Tax calculation

<b>Vehicle class</b>	48
<b>Band</b>	D
<b>Single payment (12 months)</b>	£ 150,00,-
<b>Single six month payment</b>	£ 82,50,-
<b>Total payable by 12 monthly instalments</b>	£ 157,50,-



Damage history

Check the damage history for this SUZUKI. See if, where and when this SUZUKI had damage and the car repair costs. We also check if this SUZUKI was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	

Damage 2

Date	
Category	
Type	



Extra SUZUKI salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this SUZUKI in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,999
Auction value	£ 19,999
Average private trade value	£ 19,999

More info >





Owner history

For how long did the current and previous owner(s) have this SUZUKI? How many owners did this SUZUKI have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration

More info >

Plate changes

See in this check if this SUZUKI had different number plates.

Number of plates	1
Current registration	
Plate since	2019-09-29
Current registration	
Plate since	2019-09-29

More info >



Finance check

Check if this SUZUKI is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this SUZUKI has been settled.

If not, and you buy this SUZUKI then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this SUZUKI is financed.

Finance company	XXXXXXXXXX	XXXX
Date of agreement	XXXXXXXXXX	XXXX
Agreement type	XXXXXXXXXX	XXXX
Agreement term	XXXXXXXXXX	XXXX
Agreement number	XXXXXXXXXX	XXXX
Contact info	XXXXXXXXXX	XXXX

More info >



Mileage check

Odometer	In miles
Mileage registrations	12
First mileage registration	2014-06-10
Last registration	2024-04-25
Complete history	<a href="#">See info</a>



Registration #1	2014-06-10	26 mi
Registration #2	2017-05-15	27.766 mi
Registration #3	2018-05-24	38.146 mi
Registration #4	2019-06-03	54.279 mi
Registration #5	2020-07-09	66.185 mi
Registration #6	2020-12-08	70.209 mi
Registration #7	2020-06-20	70.209 mi
Registration #8	2020-06-20	70.209 mi
Registration #9	2020-06-20	70.209 mi
Registration #10	2020-06-20	70.209 mi
Registration #11	2020-06-20	70.209 mi
Registration #12	2020-06-20	70.209 mi

More info >



Safety ratings

NCAP rating	★★★★★
Adult	92%
Children	80%
Pedestrian	72%
Safety systems	81%
Overall rating	85%
Video	<a href="#">see crash video</a>



Dimensions & weight

Width	1765 mm
Height	1580 mm
Length	4300 mm
Wheel base	2600 mm
Kerb weight	1160 kg
Max. allowed weight	1730 kg

Additional information

Fuel tank capacity	50 l
Fuel delivery	Multi-Point Injection
Number of doors	5
Number of seats	5
Number of axles	2
Engine number	M16A-1788828