



report date: 2024-03-29

General information

Make	VOLVO
Model	XC70 D5 SE LUX AWD
Colour	Blue
Year of manufacture	2010
Top speed	127 mph
0 - 60 mph	8.4 seconds
Gearbox	6 speed automatic

Engine & fuel consumption

Power	202 BHP
Max. torque	420 Nm at 1.500 rpm
Engine capacity	2.400 cc
Cylinders	5
Fuel type	Diesel
Consumption city	29.7 mpg
Consumption extra urban	48.7 mpg
Consumption combined	39.2 mpg
CO2 emission	189 g/km
CO2 label	J






Internet history

Entry 2


Date	2021-06-26
Pictures	12
Listing price	View report



source: cargurus.co.uk

Entry 1

Date	2021-06-26
Pictures	34
Listing price	View report



source: autotrader.co.uk



MOT history

MOT expiry date	2024-07-25
MOT pass rate	100 %
MOT passed	11
Failed MOT tests	0
Total advice items	17
Total items failed	0

MOT #11	2023-07-24 11:17
MOT test number	581889996818
Result	✓ Passed
Next expiry date	2024-07-25
Advice	Nearside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))
Advice	Front Tyre worn close to legal limit/worn on edge both front (5.2.3 (e))

MOT #10	2022-07-26 10:59
MOT test number	991049982652
Result	✓ Passed
Advice	Offside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))

MOT #9	2021-07-24 12:37
MOT test number	860711846827
Result	✓ Passed

MOT #8	2020-10-23 12:30
MOT test number	741703860073
Result	✓ Passed

**MOT #7** 2019-11-14 10:36**MOT test number** 201448109508**Result** ✓ Passed**Advice** Nearside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))**Advice** Offside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))**MOT #6** 2019-02-23 09:03**MOT test number** 356166149348**Result** ✓ Passed**Advice** Nearside Front Tyre has a cut but not deep enough to reach the ply or cords (5.2.3 (d) (i))**Advice** Nearside Rear Tyre has a cut but not deep enough to reach the ply or cords (5.2.3 (d) (i))**Advice** Offside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))**MOT #5** 2018-01-11 09:48**MOT test number** 495310417572**Result** ✓ Passed**Advice** Offside Rear Inner Road wheel with a slightly distorted bead rim (4.2.A.1a)**Advice** Both front tyres are worn on the inner edge (PIRELLI 235/50R18 V**Advice** Rear brake pads are starting to wear thin**MOT #4** 2017-01-17 12:44**MOT test number** 774077897886**Result** ✓ Passed



MOT #3 2015-12-17 13:08

MOT test number 455388352511

Result ✓ Passed

Advice Nearside Rear Brake pad(s) wearing thin inner pads urgent replacement recommended (3.5.1g)

Advice Offside Rear brake disc worn, pitted or scored, but not seriously weakened (3.5.1i)

Advice Offside Rear Brake pad(s) wearing thin inner pads (urgent) (3.5.1g)

Advice Nearside Rear brake disc worn, pitted or scored, but not seriously weakened (3.5.1i)

MOT #2 2014-12-04 10:09

MOT test number 449088234464

Result ✓ Passed

Notice Under-trays fitted obscuring some underside components

Notice Front tyres worn inner edges

MOT #1 2013-12-20 12:25

MOT test number 788834553362

Result ✓ Passed



Tax & MOT check

✓
Taxed
Tax due:
1 August 2024

✓
MOT
Expires:
25 July 2024

Tax status	Valid until 1 August
Days left	94
MOT expiry date	25 July 2024
Full MOT history	See MOT history

Tax calculation

Vehicle class	49
Band	J
Single payment (12 months)	£ 365,00,-
Single six month payment	£ 200,75,-
Total payable by 12 monthly instalments	£ 383,25,-



Damage history

Check the damage history for this VOLVO. See if, where and when this VOLVO had damage and the car repair costs. We also check if this VOLVO was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	

Damage 2

Date	
Category	
Type	



Extra VOLVO salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this VOLVO in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,999
Auction value	£ 19,999
Average private trade value	£ 19,999

More info >



Owner history

For how long did the current and previous owner(s) have this VOLVO? How many owners did this VOLVO have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

*****	*****
*****	*****
*****	*****
*****	*****
*****	*****
*****	*****
*****	*****

More info >

Plate changes

See in this check if this VOLVO had different number plates.

Number of plates	1
Current registration	*****
Plate since	2019-09-29
Current registration	*****
Plate since	2019-09-29

More info >



Finance check

Check if this VOLVO is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this VOLVO has been settled.

If not, and you buy this VOLVO then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this VOLVO is financed.

Finance company	XXXXXXXXXX	XXXX
Date of agreement	XXXXXXXXXX	XXXX
Agreement type	XXXXXXXXXX	XXXX
Agreement term	XXXXXXXXXX	XXXX
Agreement number	XXXXXXXXXX	XXXX
Contact info	XXXXXXXXXX	XXXX

More info >



Mileage check

Odometer	In miles
Mileage registrations	14
First mileage registration	2010-12-21
Last registration	2023-07-24
Complete history	See info



Registration #1	2010-12-21	12 mi
Registration #2	2013-12-20	55.053 mi
Registration #3	2014-12-04	71.749 mi
Registration #4	2015-12-17	88.138 mi
Registration #5	2017-01-17	100.310 mi
Registration #6	2018-01-11	112.257 mi
Registration #7	2019-02-23	125.848 mi
Registration #8	2020-03-20	139.437 mi
Registration #9	2021-03-20	153.026 mi
Registration #10	2022-03-20	166.615 mi
Registration #11	2023-03-20	180.204 mi
Registration #12	2024-03-20	193.793 mi
Registration #13	2025-03-20	207.382 mi
Registration #14	2026-03-20	220.971 mi

More info >



Car features

The VOLVO factory car options list is only available in the premium report.

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

View the complete VOLVO factory list for this vehicle [here](#).

More info >

Dimensions & weight

Width	1861 mm
Height	1604 mm
Length	4838 mm
Wheel base	2815 mm
Kerb weight	1895 kg
Max. allowed weight	2400 kg

Additional information

Fuel tank capacity	70 l
Fuel delivery	Direct Injection
Number of doors	5
Number of seats	5
Number of axles	2
Engine number	848865