




General information

Make	FORD
Model	FIESTA
Colour	White
Year of manufacture	2011
Gearbox	-

Engine & fuel consumption

Engine capacity	1.242 cc
Fuel type	Petrol
CO2 emission	129 g/km
CO2 label	D





Internet history

Entry 1

Date	2021-01-30
Pictures	1
Listing price	View report



source: [autoonline.co.uk](https://www.autoonline.co.uk)



MOT history

MOT expiry date	2024-04-29
MOT pass rate	67 %
MOT passed	10
Failed MOT tests	5
Total advice items	39
Total items failed	1

MOT #15	2023-04-28 15:09
---------	------------------

MOT test number	715723598517
-----------------	--------------

Result	✓ Passed
--------	----------

Next expiry date	2024-04-29
------------------	------------

Advice	Nearside Rear Child Seat fitted not allowing full inspection of adult belt
Advice	Rear All direction indicators slightly discoloured both (4.4.3 (a))
Advice	Nearside Rear Road wheel slightly distorted (5.2.2 (c) (i))
Advice	Nearside Rear Nail in tyre
Minor	Nearside Rear Rear reflector defective or damaged by up to 50% of the reflecting surface (4.8.1 (a) (i))
Advice	Nearside Front Child Seat fitted not allowing full inspection of adult belt
Advice	Items removed from driver's view prior to test phone holder
Advice	Central Exhaust has a minor leak of exhaust gases (6.1.2 (a))
Advice	Rear Coil spring corroded both (5.3.1 (b) (i))
Advice	Front Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))
Advice	Play in steering rack inner joint(s)
Minor	Offside Rear Rear fog lamp lens defective which has no effect on emitted light (4.5.1 (b) (i))

**MOT #14**

2023-04-28 15:09

MOT test number

543260012506

Result**✗ Failed**

- Advice** Play in steering rack inner joint(s)
- Advice** Nearside Rear Child Seat fitted not allowing full inspection of adult belt
- Advice** Rear All direction indicators slightly discoloured both (4.4.3 (a))
- Advice** Front Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))
- Minor** Nearside Rear Rear reflector defective or damaged by up to 50% of the reflecting surface (4.8.1 (a) (i))
- Advice** Central Exhaust has a minor leak of exhaust gases (6.1.2 (a))
- Advice** Rear Coil spring corroded both (5.3.1 (b) (i))
- Advice** Nearside Rear Nail in tyre
- Advice** Nearside Front Child Seat fitted not allowing full inspection of adult belt
- Advice** Items removed from driver's view prior to test phone holder
- Pass with rectification** Offside Front Headlamp not working on dipped beam (4.1.1 (a) (ii))
- Minor** Offside Rear Rear fog lamp lens defective which has no effect on emitted light (4.5.1 (b) (i))
- Advice** Nearside Rear Road wheel slightly distorted (5.2.2 (c) (i))

MOT #13

2022-04-13 10:54

MOT test number

113343799419

Result**✓ Passed****MOT #12**

2021-04-30 09:00

MOT test number

561318280341

Result**✓ Passed**

**MOT #11** 2021-04-28 11:24**MOT test number** 176861989614**Result** ✗ Failed**MAJOR** Nearside Rear Suspension arm pin or bush excessively worn trailing arm bush (5.3.4 (a) (i))**Advice** Nearside Front Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))**MAJOR** Offside Rear Suspension arm pin or bush excessively worn trailing arm bush (5.3.4 (a) (i))**Advice** Offside Front Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))**MOT #10** 2020-09-14 13:48**MOT test number** 612956709715**Result** ✓ Passed**MOT #9** 2020-09-14 08:39**MOT test number** 727850480892**Result** ✗ Failed**MAJOR** Central Rear Registration plate inscription illegible (0.1 (b))**MOT #8** 2019-10-15 13:54**MOT test number** 544886613766**Result** ✓ Passed**MOT #7** 2019-10-11 13:32**MOT test number** 458600251926**Result** ✗ Failed**MAJOR** Offside Rear Exhaust has a major leak of exhaust gases backbox (6.1.2 (a))

**MOT #6** 2018-09-29 10:32**MOT test number** 432419464168**Result** ✓ Passed**Advice** Front shockers corroded**Advice** Subframe corroded**MOT #5** 2018-09-29 08:21**MOT test number** 764855659722**Result** ✗ Failed**Advice** Front shockers corroded**MAJOR** Offside Front Suspension arm ball joint excessively worn (5.3.4 (a) (i))**Advice** Subframe corroded**MOT #4** 2017-10-07 12:03**MOT test number** 137591993139**Result** ✓ Passed**MOT #3** 2016-10-05 09:28**MOT test number** 167899729921**Result** ✓ Passed**Advice** Offside Front ball joint has a light misting**MOT #2** 2015-10-26 10:59**MOT test number** 529009447576**Result** ✓ Passed**Advice** Front Inner brake disc worn, pitted or scored, but not seriously weakened nearside and offside (3.5.1i)**Advice** Offside Front Suspension arm ball joint dust cover deteriorated, but preventing the ingress of dirt (2.4.G.2)**Advice** Front Brake pad(s) wearing thin nearside and offside (3.5.1g)



MOT #1	2014-12-01 11:03
MOT test number	359755234360
Result	✓ Passed



Tax & MOT check

✓
Taxed
Tax due:
1 September 2024

✓
MOT
Expires:
29 April 2024

Tax status	Valid until 1 September
Days left	125
MOT expiry date	29 April 2024
Full MOT history	See MOT history

Tax calculation

Vehicle class	48
Band	D
Single payment (12 months)	£ 150,00,-
Single six month payment	£ 82,50,-
Total payable by 12 monthly instalments	£ 157,50,-



Damage history

Check the damage history for this FORD. See if, where and when this FORD had damage and the car repair costs. We also check if this FORD was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	

Damage 2

Date	
Category	
Type	



Extra FORD salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this FORD in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,999
Auction value	£ 19,999
Average private trade value	£ 19,999

More info >



Owner history

For how long did the current and previous owner(s) have this FORD? How many owners did this FORD have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since

More info >

Plate changes

See in this check if this FORD had different number plates.

Number of plates	1
Current registration	PO11TXV
Plate since	2019-03-29
Current registration	PO11TXV
Plate since	2019-03-29

More info >



Finance check

Check if this FORD is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this FORD has been settled.

If not, and you buy this FORD then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this FORD is financed.


Finance company	REDACTED	REDACTED
Date of agreement	REDACTED	REDACTED
Agreement type	REDACTED	REDACTED
Agreement term	REDACTED	REDACTED
Agreement number	REDACTED	REDACTED
Contact info	REDACTED	REDACTED

More info >



Mileage check

Odometer	In miles
Mileage registrations	17
First mileage registration	2011-12-09
Last registration	2023-04-28
Complete history	See info



Registration #1	2011-12-09	9 mi
Registration #2	2014-12-01	18.520 mi
Registration #3	2015-10-26	25.126 mi
Registration #4	2016-10-05	30.753 mi
Registration #5	2017-10-07	37.518 mi
Registration #6	2018-09-29	45.091 mi
Registration #7	2018-09-29	45.091 mi
Registration #8	2019-10-11	52.338 mi
Registration #9	2019-10-15	52.339 mi
Registration #10	2019-10-15	52.339 mi
Registration #11	2019-10-15	52.339 mi
Registration #12	2019-10-15	52.339 mi
Registration #13	2019-10-15	52.339 mi
Registration #14	2019-10-15	52.339 mi
Registration #15	2019-10-15	52.339 mi
Registration #16	2019-10-15	52.339 mi
Registration #17	2019-10-15	52.339 mi

More info >



Car features

The FORD factory car options list is only available in the premium report.

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

View the complete FORD factory list for this vehicle [here](#).

More info >

Safety ratings

NCAP rating



Video

[see crash video](#)



Additional information

Number of seats

5

Engine number

BL52429