





report date: 2024-03-29

General information

Make	FORD
Model	FIESTA ZETEC
Colour	Blue
Year of manufacture	2010
Top speed	104 mph
0 - 60 mph	13.3 seconds
Gearbox	5 speed Manual

Engine & fuel consumption

Power	81 BHP
Max. torque	114 Nm
Engine capacity	1.242 cc
Cylinders	4
Fuel type	Petrol
CO2 emission	133 g/km
CO2 label	Е



CarCheck.co.uk page 1/13



report date: 2024-03-29

Internet history

Entry 1

Date 2021-05-25

Pictures 3

Listing price <u>View report</u>







source: autotrader.co.uk

CarCheck.co.uk page 2/13



report date: 2024-03-29

MOT history

MOT expiry date	2024-06-08
MOT pass rate	79 %
MOT passed	11
Failed MOT tests	3
Total advice items	19
Total items failed	8

MOT #14		2023-05-26 15:12
MOT test	number	236440674602
Result		✓ Passed
Next expir	ry date	2024-06-08
Advice	Offside Front Road wheel slightly distorted inner rim bead (5.2.2 (c) (i))	
Advice	Oil leak - oil filter area	
Advice	Oil level on minimum	
Advice	Auxiliary belt cracking	

CarCheck.co.uk page 3/13



report date: 2024-03-29

MOT #13 2023-05-26 14:14

MOT test number 577772916739

Result X Failed

Advice Oil level on minimum

Fail Nearside Rear Stop lamp(s) not working (4.3.1 (a) (ii))

Advice Auxiliary belt cracking

Fail Nearside Front Headlamp aim too low (4.1.2 (a))

Advice Nearside Front Tyre worn close to legal limit/worn on edge 3mm, worn on inner edge and perishing (5.2.3 (e))

Advice Offside Front Road wheel slightly distorted inner rim bead (5.2.2 (c) (i))

Advice Oil leak - oil filter area

Fail Nearside Rear Direction indicator incorrect colour (4.4.3 (a))

Fail Nearside Front Tyre has a cut in excess of the requirements deep enough to reach the ply or cords inner edge (5.2.3 (d) (i))

MOT #12 2022-06-09 12:11

MOT test number 109986802933

Result ✓ Passed

MOT #11 2022-06-02 10:34

MOT test number 861106694209

Result X Failed

Fail Nearside Headlamp insecure (4.1.1 (c))

Fail Nearside Headlamp aim not tested (4.1.2 (b))

MOT #10 2021-06-03 08:50

MOT test number 543807034505

Result \(\sqrt{Passed} \)

CarCheck.co.uk page 4/13



report date: 2024-03-29

MOT test number

Result

Advice Nearside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))

Advice Offside Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))

Advice Offside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))

MOT #8 2020-07-08 13:33 **MOT** test number 306907123751 Result × Failed Offside Front Coil spring fractured or broken (5.3.1 (b) (i)) Fail Advice Offside Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii)) **Advice** Offside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e)) Pass with rectification Offside Headlamp aim too high (4.1.2 (a)) **Advice** Nearside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))

MOT test number

204368352926

Result

Advice Offside Front Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))

Advice Offside Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))

Advice Nearside Front Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))

Advice Nearside Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))

MOT #6

MOT test number

695928134490

Result

✓ Passed

CarCheck.co.uk page 5/13



HV60FKL report date: 2024-03-29

MOT #5	2017-07-04 10:44
MOT test number	811991048322
Result	✓ Passed
MOT #4	2016-07-06 09:43
MOT test number	512119510771
Result	✓ Passed
MOT #3	2015-07-06 11:22
MOT test number	159367885141
Result	✓ Passed
MOT #2	2014-07-15 09:17
MOT test number	238546094144
Result	✓ Passed
MOT #1	2013-07-30 13:13
MOT test number	127671613248
Result	✓ Passed

CarCheck.co.uk page 6/13



report date: 2024-03-29

Tax & MOT check



Tax status	Valid until 1 January
Days left	246
MOT expiry date	8 June 2024
Full MOT history	See MOT history

Tax calculation

Vehicle class	48
Band	Е
Single payment (12 months)	£ 180,00,-
Single six month payment	£ 99,00,-
Total payable by 12 monthly instalments	£ 189,00,-

CarCheck.co.uk page 7/13



HV60FKL report date: 2024-03-29

Damage history

Check the damage history for this FORD. See if, where and when this FORD had damage and the car repair costs. We also check if this FORD was scrapped. Download the premium report <u>here</u> for the results.

Damage 1
Date
Category
Type
Damage 2
Date
Category
Type



Extra FORD salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report <u>here</u> for more information.

More info >

CarCheck.co.uk page 8/13



report date: 2024-03-29

Vehicle valuation

What is this car worth? See the vehicle value of this FORD in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value

Auction value

Average private trade value

More info >

CarCheck.co.uk page 9/13



report date: 2024-03-29

Owner history	
For how long did the current and previous owner(s) have this FORD? How many owners of Check it in the premium report and see all owner registrations. Download the full report is	

HEREETE STATE OF THE STATE OF T	

Plate changes	More info >
See in this check if this FORD had different number plates.	
Number of plates	
Current registration	UK UK
Plate since	
Current registration	NK NA
Plate since	
	More info >

CarCheck.co.uk page 10/13



HV60FKL report date: 2024-03-29

Finance check

Check if this FORD is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this FORD has been settled.

If not, and you buy this FORD then you could lose the money and the car you paid for.

Download the premium report <u>here</u> and check if this FORD is financed.

Finance company	
Date of agreement	
Agreement type	
Agreement term	
Agreement number	
Contact info	

More info >

CarCheck.co.uk page 11/13



report date: 2024-03-29

Mileage check

Odometer	In miles
Mileage registrations	16
First mileage registration	2010-09-02
Last registration	2023-05-26
Complete history	See info



Registration #1	2010-09-02	6 mi
Registration #2	2013-07-30	8.875 mi
Registration #3	2014-07-15	11.409 mi
Registration #4	2015-07-06	13.473 mi
Registration #5	2016-07-06	15.046 mi
Registration #6	2017-07-04	16.591 mi
Registration #7	2018-07-04	18.782 mi
Registration #8	2019-07-03	20.055 mi
Registration #9		11.777 mi
Registration #10		11.777 es
Registration #11		11.777 es
Registration #12		0.00 44
Registration #13		11.777 es
Registration #14		0.00 44
Registration #15		11.777 mi
Registration #16		11.777 es

More info >

CarCheck.co.uk page 12/13



HV60FKL report date: 2024-03-29

Car features

50225	Air conditionin
50295	
50482	
50501	
60566	
60567	
50569	

Safety ratings

NCAP rating	****
Video	see crash video



Dimensions & weight

Width	1722 mm
Height	1433 mm
Length	3950 mm
Wheel base	2489 mm
Kerb weight	1109 kg
Max. allowed weight	1495 kg

Additional information

Fuel tank capacity	42 I
Fuel delivery	Multi-Point Injection
Number of doors	5
Number of seats CarCheck.co.uk	5 page 13/13