






### General information

Make	CITROEN
Model	C1 PURETECH FEEL
Colour	Blue
Year of manufacture	2015
Top speed	106 mph
0 - 60 mph	11.0 seconds
Gearbox	5 speed Manual

## Engine & fuel consumption

Power	82 BHP	
Fower	02 DITI	
Max. torque	116 Nm at 2.750 rpm	
Engine capacity	1.200 cc	
Cylinders	3	
Fuel type	Petrol	
Consumption city	52.3 mpg	
Consumption extra urban	76.3 mpg	
Consumption combined	65.7 mpg	
CO2 emission	99 g/km	
CO2 label	А	







## Internet history

Entry 1	
Date	

2021-01-29

10

Listing price

Pictures

View report



source: autoonline.co.uk



# MOT history

MOT expiry date	2024-05-24
MOT pass rate	75 %
MOT passed	6
Failed MOT tests	2
Total advice items	17
Total items failed	3

MOT #8	2023-05-17 09:38
MOT test number	168201289818
Result	✓ Passed
Next expiry date	2024-05-24
Advice Offside Rear Service brake binding but not excessively (1.2.1 (f))	
<b>Advice</b> Parking brake requirements only just met. It would appear that the brak adjustment or repair	king system requires

MOT #7		2022-05-20 09:37
MOT test	number	332476235122
Result		✓ Passed
Advice adjustmen	Parking brake requirements only just met. It would appear that t t or repair	he braking system requires
MOT #6		2021-05-25 16:30
MOT test	number	686975509054

Result

🗸 Passed



HV65KNR report date: 2024-03-28

MOT #5			2021-05-24 14:04
MOT test	number		923460632542
Result			🗙 Failed
Advice	Front Exhaust has	a minor leak of exhaust gases (6.1.2 (a))	
Advice	Nearside Rear Nail in tyre		
Advice	Advice Offside Front Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))		
Pass wit	h rectification	Nearside Headlamp light intensity severely reduced (4.1	.4 (a))
Fail Fr	ont Exhaust system	n insecure (6.1.2 (a))	
Advice	Nearside Front Bra	ake disc worn, pitted or scored, but not seriously weaken	ned (1.1.14 (a) (ii))

MOT #4	2020-10-08 10:15
MOT test number	335488998939
Result	✓ Passed
Advice Exhaust mounting defective (6.1.2 (a))	

MOT #3		2019-10-14 10:42
MOT test	number	619663558957
Result		✓ Passed
Advice	Offside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))	
Advice	Front tyres wearing inner and outer edges	
Advice	Nearside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))	
Advice	Front exhaust hanger snapped	





MOT #2		2018-09-27 13:34
MOT test	number	757362360788
Result		✓ Passed
Advice Advice	Front Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a Front Brake pad(s) wearing thin (1.1.13 (a) (ii))	) (ii))
MOT #1		2018-09-27 10:08

MOT test	number	744777598637
Result		🗙 Failed
<b>Fail</b> O	ffside Front Tyre tread depth below requirements of 1.6mm (5.2.3 (e))	
Advice	Front Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))	
Advice	Nearside front tyre wearing outer edge	
Advice	Front Brake pad(s) wearing thin (1.1.13 (a) (ii))	



Tax & MOT check

<b>Tax due:</b> 1 May 2025	✓ Taxed	<b>Expires:</b> 24 May 2024	MOT Expires: 24 May 2024	
Tax status			Valid until 1 May	
Days left			367	
MOT expiry date			24 May 2024	
Full MOT history			See MOT history	
Tax calculation				
Vehicle class		48		
Band		Δ		

Band	А
Single payment (12 months)	£ 0,00,-
Single six month payment	Not applicable
Total payable by 12 monthly instalments	Not applicable





### Damage history

Check the damage history for this CITROEN. See if, where and when this CITROEN had damage and the car repair costs. We also check if this CITROEN was scrapped. Download the premium report <u>here</u> for the results.

Damage 1	
Date	
Category	Lamp
Туре	
Damage 2	AMPL
	E Store
Date	1. E
Category	amt
Туре	

#### Extra CITROEN salvage check

If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report <u>here</u> for more information.

More info  $\rightarrow$ 





#### Vehicle valuation

What is this car worth? See the vehicle value of this CITROEN in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	4 10.000
Auction value	4 10.000
Average private trade value	4 10.200

More info  $\rightarrow$ 





### Owner history

For how long did the current and previous owner(s) have this CITROEN? How many owners did this CITROEN have? Check it in the premium report and see all owner registrations. Download the full report <u>here</u>.

And a second sec	
************	
********	
*******	
***********	
********	
	More info >
Plate changes	
See in this check if this CITROEN had different number plates.	
Number of plates	,
Current registration	
Plate since	
Carrent registration	
Plate since	
	More info >





#### Finance check

Check if this CITROEN is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this CITROEN has been settled.

If not, and you buy this CITROEN then you could lose the money and the car you paid for.

Download the premium report <u>here</u> and check if this CITROEN is financed.

Finance company	
Date of agreement	
Agreement type	
Agreement term	
Agreement number	
Contact info	


More info  $\rightarrow$ 





# Mileage check

Odometer	In miles
Mileage registrations	10
First mileage registration	2015-09-30
Last registration	2023-05-17
Complete history	<u>See info</u>



Registration #1	2015-09-30	14 mi
Registration #2	2018-09-27	25.580 mi
Registration #3	2018-09-27	25.580 mi
Registration #4	2019-10-14	36.767 mi
Registration #5	2020-10-08	42.854 mi
Registration #6		11.777 esi
Registration #7		11.777 mi
Registration #7 Registration #8		10.000 est
		00.000 est 0.000 est 00.000 est

More info >





# Safety ratings

NCAP rating	****
Adult	68%
Children	73%
Pedestrian	53%
Safety systems	71%
Overall rating	66%
Video	see crash video



Dimensions & weight	
Width	1884 mm
Height	1460 mm
Length	3466 mm
Wheel base	2340 mm
Kerb weight	865 kg
Max. allowed weight	1240 kg
Additional information	
Additional information Fuel tank capacity	35 l
	35 I Multi-Point Injection
Fuel tank capacity	
Fuel tank capacity Fuel delivery	Multi-Point Injection
Fuel tank capacity Fuel delivery Number of doors	Multi-Point Injection 5