



HYUNDAI




report date: 2024-03-29

General information

Make	HYUNDAI
Model	IX20 ACTIVE
Colour	Grey
Year of manufacture	2013
Top speed	114 mph
0 - 60 mph	12.2 seconds
Gearbox	4 speed automatic

Engine & fuel consumption

Power	123 BHP
Max. torque	156 Nm at 4.200 rpm
Engine capacity	1.591 cc
Cylinders	4
Fuel type	Petrol
Consumption city	34.0 mpg
Consumption extra urban	51.4 mpg
Consumption combined	43.5 mpg
CO2 emission	154 g/km
CO2 label	G






Internet history

Entry 1

Date	2021-07-19
Pictures	31
Listing price	View report



source: cargurus.co.uk



MOT history

MOT expiry date	2024-07-21
MOT pass rate	82 %
MOT passed	9
Failed MOT tests	2
Total advice items	17
Total items failed	4

MOT #11 2023-07-17 16:15

MOT test number 450534719462

Result ✓ Passed

Next expiry date 2024-07-21

Minor Offside Front Anti-roll bar ball joint dust cover severely deteriorated (5.3.4 (b) (i))

Advice Nearside Front Track rod end slightly misaligned (2.1.3 (e))

MOT #10 2022-07-15 07:45

MOT test number 227303191835

Result ✓ Passed

Advice Offside Front Tyre has a cut but not deep enough to reach the ply or cords (5.2.3 (d) (i))

Advice Nearside Front Outer Tyre has a cut but not deep enough to reach the ply or cords (5.2.3 (d) (i))

Advice Offside Front Outer Track rod end ball joint has slight play (2.1.3 (b) (i))

MOT #9 2021-07-22 16:59

MOT test number 843575247449

Result ✓ Passed

**MOT #8** 2021-03-09 08:53**MOT test number** 804464221319**Result** ✓ Passed**Advice** Front Brake pad(s) wearing thin (1.1.13 (a) (ii))**MOT #7** 2020-03-09 16:57**MOT test number** 525298781061**Result** ✓ Passed**MOT #6** 2020-03-09 09:55**MOT test number** 964822503441**Result** ✗ Failed**Fail** Offside Front Position lamp not working (4.2.1 (a) (ii))**MOT #5** 2019-03-11 14:38**MOT test number** 940526483810**Result** ✓ Passed**Advice** Nearside Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))**MOT #4** 2019-03-11 10:34**MOT test number** 760850534149**Result** ✗ Failed**Advice** Nearside Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))**Pass with rectification** Nearside Windscreen washer not working (3.5 (a))**Fail** Nearside Rear Stop lamp(s) not working (4.3.1 (a) (ii))**Pass with rectification** Offside Windscreen washer not working (3.5 (a))

**MOT #3** 2018-02-28 12:18**MOT test number** 765684924685**Result** ✓ Passed**Advice** Central Front Items removed from driver's view prior to test**MOT #2** 2017-02-24 11:54**MOT test number** 562192398739**Result** ✓ Passed**Advice** Offside Rear Shock absorber has a light misting of oil (2.7.3)**Advice** Items removed from driver's view prior to test**MOT #1** 2016-02-05 10:09**MOT test number** 995364619226**Result** ✓ Passed**Advice** Nearside Front Brake pad(s) wearing thin (3.5.1g)**Advice** Nearside Rear Brake pad(s) wearing thin (3.5.1g)**Advice** Brake discs lipped and pitted all round.**Advice** Offside Front Brake pad(s) wearing thin (3.5.1g)**Advice** Offside Rear Brake pad(s) wearing thin (3.5.1g)**Advice** Both front wipers smearing.



Tax & MOT check

✓
Taxed
Tax due:
1 August 2024

✓
MOT
Expires:
21 July 2024

Tax status	Valid until 1 August
Days left	94
MOT expiry date	21 July 2024
Full MOT history	See MOT history

Tax calculation

Vehicle class	48
Band	G
Single payment (12 months)	£ 240,00,-
Single six month payment	£ 132,00,-
Total payable by 12 monthly instalments	£ 252,00,-



Damage history

Check the damage history for this HYUNDAI. See if, where and when this HYUNDAI had damage and the car repair costs. We also check if this HYUNDAI was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	

Damage 2

Date	
Category	
Type	



Extra HYUNDAI salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this HYUNDAI in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,999
Auction value	£ 19,999
Average private trade value	£ 19,999

More info >



Owner history

For how long did the current and previous owner(s) have this HYUNDAI? How many owners did this HYUNDAI have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration

More info >

Plate changes

See in this check if this HYUNDAI had different number plates.

Number of plates	1
Current registration	
Plate since	2024-03-29
Current registration	
Plate since	2024-03-29

More info >



Finance check

Check if this HYUNDAI is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this HYUNDAI has been settled.

If not, and you buy this HYUNDAI then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this HYUNDAI is financed.

Finance company	XXXXXXXX	XXXX
Date of agreement	XXXXXXXX	XXXX
Agreement type	XXXXXXXX	XXXX
Agreement term	XXXXXXXX	XXXX
Agreement number	XXXXXXXX	XXXX
Contact info	XXXXXXXX	XXXX

More info >



Mileage check

Odometer	In miles
Mileage registrations	13
First mileage registration	2013-03-01
Last registration	2023-07-17
Complete history	See info



Registration #1	2013-03-01	28 mi
Registration #2	2016-02-05	15.890 mi
Registration #3	2017-02-24	20.434 mi
Registration #4	2018-02-28	24.886 mi
Registration #5	2019-03-11	32.070 mi
Registration #6	2019-03-11	32.070 mi
Registration #7	2020-03-09	39.055 mi
Registration #8	2020-03-09	39.055 mi
Registration #9	2020-03-09	39.055 mi
Registration #10	2020-03-09	39.055 mi
Registration #11	2020-03-09	39.055 mi
Registration #12	2020-03-09	39.055 mi
Registration #13	2020-03-09	39.055 mi

More info >



Car features

The HYUNDAI factory car options list is only available in the premium report.

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

View the complete HYUNDAI factory list for this vehicle [here](#).

More info >

Safety ratings

NCAP rating	★★★★★
Adult	89%
Children	85%
Pedestrian	64%
Safety systems	71%
Overall rating	81%
Video	see crash video



Dimensions & weight

Width	1765 mm
Height	1600 mm
Length	4100 mm
Wheel base	2615 mm
Kerb weight	1294 kg
Max. allowed weight	1730 kg

Additional information

Fuel tank capacity	48 l
Fuel delivery	Multi-Point Injection
Number of doors	5
Number of seats	5

Number of axles	2
Engine number	G4FCDZ716757