



Mercedes-Benz



report date: 2024-03-28

General information

Make	MERCEDES
Model	C C180K SE
Colour	Silver
Year of manufacture	2008
Top speed	137 mph
0 - 60 mph	9.9 seconds
Gearbox	6 speed automatic

Engine & fuel consumption

Power	141 BHP
Max. torque	220 Nm at 2.500 rpm
Engine capacity	1.796 cc
Cylinders	4
Fuel type	Petrol
Consumption city	23.7 mpg
Consumption extra urban	45.6 mpg
Consumption combined	33.6 mpg
CO2 emission	200 g/km
CO2 label	J





MOT history

MOT expiry date	2025-01-30
MOT pass rate	78 %
MOT passed	14
Failed MOT tests	4
Total advice items	43
Total items failed	4

MOT #18	2024-01-31 12:45
MOT test number	156971588169
Result	✓ Passed
Next expiry date	2025-01-30
Advice	Nearside Front Suspension arm ball joint has slight play (5.3.4 (a) (i))

MOT #17	2023-03-15 12:06
MOT test number	767411620561
Result	✓ Passed
Advice	Rear Anti-roll bar corroded but not seriously weakened (5.3.3 (b) (i))
Advice	Front Brake disc worn, but not excessively (1.1.14 (a) (i))
Advice	Nearside Front Track rod end ball joint has slight play (2.1.3 (b) (i))
Advice	Offside Rear subframe bush slightly perished

MOT #16	2022-03-09 13:26
MOT test number	334754324188
Result	✓ Passed
Advice	Both rear tires getting low

**MOT #15** 2021-03-26 12:08**MOT test number** 929362025486**Result** ✓ Passed**Advice** Nearside Rear Shock absorbers has a reduced damping effect (5.3.2 (d))**Advice** Rear Brake pad(s) wearing thin (1.1.13 (a) (ii))**Advice** Rear antiroll bar corroded**Advice** Offside Front Wheel bearing has slight play (5.1.3 (a) (i))**MOT #14** 2020-03-05 10:04**MOT test number** 806523123747**Result** ✓ Passed**MOT #13** 2019-02-25 11:21**MOT test number** 625207880697**Result** ✓ Passed**Advice** Offside Front Wheel bearing has slight play (5.1.3 (a) (i))**Advice** Both front strut top bearings slightly tight**Advice** Nearside Front Wheel bearing has slight play (5.1.3 (a) (i))**Advice** Undertrays fitted**Advice** Nearside Rear Nail in tyre 245/40/17

**MOT #12**

2019-02-25 11:21

MOT test number

516474763043

Result**✗ Failed****Pass with rectification** Offside Front Position lamp not working (4.2.1 (a))**Advice** Offside Front Wheel bearing has slight play (5.1.3 (a) (i))**Advice** Both front strut top bearings slightly tight**Advice** Nearside Rear Nail in tyre 245/40/17**Advice** Nearside Front Wheel bearing has slight play (5.1.3 (a) (i))**Advice** Undertrays fitted**MOT #11**

2018-02-09 13:44

MOT test number

831990902856

Result**✓ Passed****Advice** Front Brake pad(s) wearing thin (3.5.1g)**Advice** Offside Front Front wheel bearing has slight play (2.5.A.3c)**Advice** Nearside Front Tyre has damage to outer wall. 225/45/17**Advice** Nearside Rear Tyre worn close to the legal limit 3mm. 245/40/17 (4.1.E.1)**Advice** Front brake disc worn, pitted or scored, but not seriously weakened (3.5.1i)**Advice** Nearside Front Front wheel bearing has slight play (2.5.A.3c)**Advice** Steering system slightly tight Both strut top bearings (2.2.D.1)**Advice** Offside Rear Tyre worn close to the legal limit 3mm (4.1.E.1)

**MOT #10** 2017-02-23 11:18**MOT test number** 481660509360**Result** ✓ Passed**Advice** Nearside Front Front wheel bearing has slight play (2.5.A.3c)**Advice** Front Steering system slightly tight Both strut top bearings (2.2.D.1)**Advice** Offside Front Front wheel bearing has slight play (2.5.A.3c)**MOT #9** 2017-02-23 09:38**MOT test number** 147542447462**Result** ✗ Failed**Advice** Front Steering system slightly tight Both strut top bearings (2.2.D.1)**Advice** Offside Front Front wheel bearing has slight play (2.5.A.3c)**Fail** Offside Front Tyre has ply or cords exposed 225/45/17 (4.1.D.1b)**Advice** Nearside Front Front wheel bearing has slight play (2.5.A.3c)**MOT #8** 2016-02-29 13:03**MOT test number** 538910819181**Result** ✓ Passed**MOT #7** 2015-02-27 13:33**MOT test number** 488418155093**Result** ✓ Passed**MOT #6** 2015-02-27 11:40**MOT test number** 609078555076**Result** ✗ Failed**Fail** Nearside Front Front suspension has excessive play in a lower suspension ball joint (2.5.B.1a)

**MOT #5** 2014-02-19 11:07**MOT test number** 315340354044**Result** ✓ Passed**MOT #4** 2013-02-20 16:31**MOT test number** 728421053064**Result** ✓ Passed**Advice** Nearside Front Lower Suspension arm has slight play in a pin/bush (2.4.G.2)**Notice** O/S/F and O/S/R tyres have small cuts in outer sidewalls but cord not exposed.**MOT #3** 2013-02-20 16:06**MOT test number** 757311853000**Result** ✗ Failed**Advice** Nearside Front Lower Suspension arm has slight play in a pin/bush (2.4.G.2)**Fail** Offside Front Lower Suspension arm has excessive play in a pin/bush (2.4.G.2)**Notice** O/S/F and O/S/R tyres have small cuts in outer sidewalls but cord not exposed.**MOT #2** 2012-02-13 15:08**MOT test number** 646954042035**Result** ✓ Passed**Advice** Nearside Rear Tyre worn close to the legal limit (4.1.E.1)**Advice** Offside Front Suspension arm has slight play in a ball joint (2.4.G.2)**Advice** Offside Rear Tyre worn close to the legal limit (4.1.E.1)



MOT #12011-02-18 11:29

MOT test number159329041408

Result

✓ Passed

NoticeO/s/r tead 3mm

NoticeN/s/r tyre tread 3mm



Tax & MOT check

✓
Taxed
Tax due:
1 September 2024

✓
MOT
Expires:
30 January 2025

Tax status	Valid until 1 September
Days left	125
MOT expiry date	30 January 2025
Full MOT history	See MOT history

Tax calculation

Vehicle class	48
Band	J
Single payment (12 months)	£ 365,00,-
Single six month payment	£ 200,75,-
Total payable by 12 monthly instalments	£ 383,25,-




Damage history

Check the damage history for this MERCEDES. See if, where and when this MERCEDES had damage and the car repair costs. We also check if this MERCEDES was scrapped. Download the premium report [here](#) for the results.


Damage 1

Date	
Category	
Type	



Damage 2

Date	
Category	
Type	



Extra MERCEDES salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this MERCEDES in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,999
Auction value	£ 19,999
Average private trade value	£ 19,999

More info >



Owner history

For how long did the current and previous owner(s) have this MERCEDES? How many owners did this MERCEDES have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

*****	*****
*****	*****
*****	*****
*****	*****
*****	*****
*****	*****

More info >

Plate changes

See in this check if this MERCEDES had different number plates.

Number of plates	7
Current registration	*****
Plate since	2019-06-29
Current registration	*****
Plate since	2019-06-29

More info >



Finance check

Check if this MERCEDES is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this MERCEDES has been settled.

If not, and you buy this MERCEDES then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this MERCEDES is financed.

Finance company	REDACTED	REDACTED
Date of agreement	REDACTED	REDACTED
Agreement type	REDACTED	REDACTED
Agreement term	REDACTED	REDACTED
Agreement number	REDACTED	REDACTED
Contact info	REDACTED	REDACTED

More info >



Mileage check

Odometer	In miles
Mileage registrations	19
First mileage registration	2008-03-01
Last registration	2024-01-31
Complete history	See info



Registration #1	2008-03-01	16 mi
Registration #2	2011-02-18	9.450 mi
Registration #3	2012-02-13	12.111 mi
Registration #4	2013-02-20	14.626 mi
Registration #5	2013-02-20	14.626 mi
Registration #6	2014-02-19	16.921 mi
Registration #7	2015-02-27	19.524 mi
Registration #8	2015-02-27	19.524 mi
Registration #9	2016-02-29	21.699 mi
Registration #10	2017-02-23	29.695 mi
Registration #11	2018-03-01	35.377 mi
Registration #12	2018-03-01	35.377 mi
Registration #13	2018-03-01	35.377 mi
Registration #14	2018-03-01	35.377 mi
Registration #15	2018-03-01	35.377 mi
Registration #16	2018-03-01	35.377 mi
Registration #17	2018-03-01	35.377 mi
Registration #18	2018-03-01	35.377 mi
Registration #19	2018-03-01	35.377 mi

More info >



Dimensions & weight

Width	1957 mm
Height	1406 mm
Length	4343 mm
Wheel base	2715 mm
Kerb weight	1465 kg

Additional information

Fuel tank capacity	62 l
Fuel delivery	Multi-Point Injection
Number of doors	3
Number of seats	4
Number of axles	2
Engine number	27194630965683