



RE60FXG

report date: 2024-03-28

General information

Make	VOLKSWAGEN
Model	CADDY C20 TDI
Colour	White
Year of manufacture	2010
Top speed	104 mph
0 - 60 mph	12.2 seconds
Gearbox	5 speed Manual

Engine & fuel consumption

Power	101 BHP
Max. torque	250 Nm at 1.500 rpm
Engine capacity	1.598 cc
Cylinders	4
Fuel type	Diesel
Consumption city	42.2 mpg
Consumption extra urban	53.3 mpg
Consumption combined	48.7 mpg





Internet history

Entry 1

Date	2021-02-06
Pictures	1
Listing price	<a href="#">View report</a>



source: [autoonline.co.uk](https://www.autoonline.co.uk)



MOT history

MOT expiry date	2024-05-23
MOT pass rate	83 %
MOT passed	10
Failed MOT tests	2
Total advice items	29
Total items failed	8

MOT #12	2023-05-24 15:08
MOT test number	184872262332
Result	✓ Passed
Next expiry date	2024-05-23
Minor	Nearside Front Lower Suspension arm ball joint dust cover severely deteriorated (5.3.4 (b) (i))
Minor	Offside Front Lower Suspension arm ball joint dust cover severely deteriorated (5.3.4 (b) (i))
Advice	Rear exhaust deteriorating

**MOT #11**

2023-05-17 12:15

**MOT test number**

669412685065

**Result**

✗ Failed

- Fail** Nearside Rear Tyre has ply or cords exposed (5.2.3 (d) (ii))
- Minor** Nearside Front Lower Suspension arm ball joint dust cover severely deteriorated (5.3.4 (b) (i))
- Fail** Offside Front Position lamp not working (4.2.1 (a) (ii))
- Advice** Rear exhaust deteriorating
- Fail** Offside Rear Stop lamp(s) not working (4.3.1 (a) (ii))
- Fail** Windscreen washer provides insufficient washer liquid (3.5 (a))
- Advice** Offside Front Lower Suspension arm pin or bush worn but not resulting in excessive movement (5.3.4 (a) (i))
- Advice** Nearside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))
- Minor** Offside Front Lower Suspension arm ball joint dust cover severely deteriorated (5.3.4 (b) (i))
- Fail** Registration plate lamp inoperative in the case of a single lamp or all lamps (4.7.1 (b) (ii))
- Fail** Offside Rear Rear fog lamp not working (4.5.1 (a) (ii))
- Fail** Nearside Front Lower Suspension arm pin or bush excessively worn (5.3.4 (a) (i))

**MOT #10**

2022-05-17 12:14

**MOT test number**

359003231909

**Result**

✓ Passed

**MOT #9** 2020-10-28 08:16**MOT test number** 583493369358**Result** ✓ Passed

- Advice** Both lower arm ball joint gaiters perished
- Advice** Nearside Stone chip in windscreen
- Advice** O/S front brake pads worn lower than N/S front brake pads
- Advice** Offside Front Wheel has a slight bind on rotation

**MOT #8** 2019-10-08 07:52**MOT test number** 799329108589**Result** ✓ Passed

- Advice** Offside Rear Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))
- Advice** Nearside Stone chip in screen
- Advice** Nearside Rear Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))

**MOT #7** 2018-10-10 13:36**MOT test number** 675458610697**Result** ✓ Passed**MOT #6** 2017-10-05 16:47**MOT test number** 717312705582**Result** ✓ Passed**MOT #5** 2016-10-13 08:53**MOT test number** 959774292587**Result** ✓ Passed

- Advice** Centre Windscreen has damage to an area less than a 40mm circle outside zone 'A' (8.3.1d)



<b>MOT #4</b>	2015-11-24 16:39
<b>MOT test number</b>	957428277391
<b>Result</b>	✓ Passed
<b>Advice</b>	Damage to front bumper/grill, however latch still works correctly

<b>MOT #3</b>	2015-11-20 15:43
<b>MOT test number</b>	350909805689
<b>Result</b>	✗ Failed
<b>Advice</b>	Osr lamp damaged but not showing white light
<b>Fail</b>	Nearside Rear Tyre has a cut in excess of the requirements deep enough to reach the ply or cords cut to cord (4.1.D.1a)
<b>Advice</b>	Front brake pads close to wear limit
<b>Advice</b>	Damage to front bumper/grill, however latch still works correctly
<b>Advice</b>	Both front shock absorbers leaking
<b>Advice</b>	Offside Rear Tyre worn close to the legal limit tyre close to wear limit measuring 2mm in several areas (4.1.E.1)
<b>Advice</b>	Rear brake pads close to wear limit

<b>MOT #2</b>	2014-11-14 09:34
<b>MOT test number</b>	697228314390
<b>Result</b>	✓ Passed
<b>Advice</b>	Offside Front Shock absorber has a light misting of oil (2.7.3)
<b>Advice</b>	Nearside Front Shock absorber has a light misting of oil (2.7.3)
<b>Advice</b>	Offside Headlamp damaged but light output not reduced (1.7.5a)



MOT #1	2013-11-11 09:11
MOT test number	129955513307
Result	✓ Passed
Advice	Front Brake pad(s) wearing thin (3.5.1g)
Advice	Offside Stop lamp has a product on the light source but not adversely affecting light output (1.2.1d)
Advice	Front brake disc worn, pitted or scored, but not seriously weakened (3.5.1i)



Tax & MOT check

✓  
**Taxed**  
**Tax due:**  
1 August 2024

✓  
**MOT**  
**Expires:**  
23 May 2024

<b>Tax status</b>	Valid until 1 August
-------------------	----------------------

<b>Days left</b>	95
------------------	----

<b>MOT expiry date</b>	23 May 2024
------------------------	-------------

<b>Full MOT history</b>	<a href="#">See MOT history</a>
-------------------------	---------------------------------





Damage history


Check the damage history for this VOLKSWAGEN. See if, where and when this VOLKSWAGEN had damage and the car repair costs. We also check if this VOLKSWAGEN was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	

Damage 2

Date	
Category	
Type	



Extra VOLKSWAGEN salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this VOLKSWAGEN in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,999
Auction value	£ 19,999
Average private trade value	£ 19,999

More info >



Owner history

For how long did the current and previous owner(s) have this VOLKSWAGEN? How many owners did this VOLKSWAGEN have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration

More info >

Plate changes

See in this check if this VOLKSWAGEN had different number plates.

Number of plates	1
Current registration	 <b>RE60FXG</b>
Plate since	2024-03-28
Current registration	 <b>RE60FXG</b>
Plate since	2024-03-28

More info >



Finance check

Check if this VOLKSWAGEN is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this VOLKSWAGEN has been settled.

If not, and you buy this VOLKSWAGEN then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this VOLKSWAGEN is financed.


Finance company	REDACTED	REDACTED
Date of agreement	REDACTED	REDACTED
Agreement type	REDACTED	REDACTED
Agreement term	REDACTED	REDACTED
Agreement number	REDACTED	REDACTED
Contact info	REDACTED	REDACTED

More info >



Mileage check

Odometer	In miles
Mileage registrations	14
First mileage registration	2010-12-01
Last registration	2023-05-24
Complete history	<a href="#">See info</a>



Registration #1	2010-12-01	16 mi
Registration #2	2013-11-11	58.129 mi
Registration #3	2014-11-14	83.972 mi
Registration #4	2015-11-20	107.765 mi
Registration #5	2015-11-24	107.765 mi
Registration #6	2016-10-13	117.853 mi
Registration #7	2017-10-05	123.643 mi
Registration #8	2018-05-29	123.643 mi
Registration #9	2018-05-29	123.643 mi
Registration #10	2018-05-29	123.643 mi
Registration #11	2018-05-29	123.643 mi
Registration #12	2018-05-29	123.643 mi
Registration #13	2018-05-29	123.643 mi
Registration #14	2018-05-29	123.643 mi

More info >



Car features

The VOLKSWAGEN factory car options list is only available in the premium report.

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

View the complete VOLKSWAGEN factory list for this vehicle [here](#).

More info >

Safety ratings

NCAP rating

Video [see crash video](#)



Dimensions & weight

Width	2062 mm
Height	1836 mm
Length	4876 mm
Kerb weight	1478 kg

Additional information

Fuel tank capacity	60 l
Fuel delivery	Direct Injection
Number of doors	4
Number of seats	2
Engine number	CAY 480292