



TOYOTA



report date: 2024-03-29

General information

Make	TOYOTA
Model	LANDCRUISER D-4D LC4 8 SEATS
Colour	Black
Year of manufacture	2005
Top speed	112 mph
0 - 60 mph	11.2 seconds
Gearbox	5 speed automatic

Engine & fuel consumption

Power	164 BHP
Max. torque	410 Nm at 2.000 rpm
Engine capacity	2.982 cc
Cylinders	4
Fuel type	Diesel
Consumption city	24.4 mpg
Consumption extra urban	37.7 mpg
Consumption combined	31.4 mpg
CO2 emission	243 g/km
CO2 label	L







Internet history

Entry 1

Date	2022-03-23
Pictures	38
Listing price	<a href="#">View report</a>



source: cargurus.co.uk



MOT history

MOT expiry date	2025-02-21
MOT pass rate	90 %
MOT passed	18
Failed MOT tests	2
Total advice items	45
Total items failed	7

MOT #20	2024-02-22 16:26
MOT test number	566248190153
Result	✓ Passed
Next expiry date	2025-02-21
Advice	Nearside Rear Brake pad(s) wearing thin (1.1.13 (a) (ii))
Minor	Nearside Front Headlamp lens slightly defective (4.1.1 (b) (i))
Advice	Offside Front Suspension arm pin or bush worn but not resulting in excessive movement (5.3.4 (a) (i))
Advice	Offside Rear Brake pad(s) wearing thin (1.1.13 (a) (ii))
Minor	Offside Front Headlamp lens slightly defective (4.1.1 (b) (i))

MOT #19	2024-01-23 12:48
MOT test number	398821672626
Result	✓ Passed
Advice	Offside Front Suspension arm pin or bush worn but not resulting in excessive movement (5.3.4 (a) (i))
Advice	Nearside Rear Brake pad(s) wearing thin (1.1.13 (a) (ii))
Minor	Nearside Front Headlamp lens slightly defective (4.1.1 (b) (i))
Advice	Offside Rear Brake pad(s) wearing thin (1.1.13 (a) (ii))
Minor	Offside Front Headlamp lens slightly defective (4.1.1 (b) (i))

**MOT #18**

2023-02-08 10:42

**MOT test number**

336660789691

**Result**

✓ Passed

- Advice** Nearside Rear Brake pad(s) wearing thin (1.1.13 (a) (ii))
- Minor** Nearside Rear Anti-roll bar linkage ball joint dust cover severely deteriorated (5.3.4 (b) (i))
- Minor** Nearside Front Headlamp lens slightly defective (4.1.1 (b) (i))
- Minor** Offside Rear Anti-roll bar linkage ball joint dust cover severely deteriorated (5.3.4 (b) (i))
- Advice** Offside Rear Brake pad(s) wearing thin (1.1.13 (a) (ii))
- Minor** Offside Front Headlamp lens slightly defective (4.1.1 (b) (i))

**MOT #17**

2022-02-15 14:00

**MOT test number**

791831790553

**Result**

✓ Passed

**MOT #16**

2021-10-05 14:24

**MOT test number**

937531373456

**Result**

✓ Passed

- Minor** Offside Front Lower Suspension arm ball joint dust cover severely deteriorated (5.3.4 (b) (i))
- Advice** Offside Front Shock absorbers has light misting of oil (5.3.2 (b))
- Advice** Offside Front Coil spring corroded (5.3.1 (b) (i))

**MOT #15**

2020-10-23 15:00

**MOT test number**

410201879598

**Result**

✓ Passed

- Advice** Offside Front Anti-roll bar pin or bush worn but not resulting in excessive movement Strong advise (5.3.4 (a) (i))
- Minor** Nearside Rear Anti-roll bar ball joint dust cover severely deteriorated (5.3.4 (b) (i))

**MOT #14**

2019-04-11 08:24

**MOT test number**

726573137049

**Result**

✓ Passed

**Minor**

Nearside Front Lower Anti-roll bar ball joint dust cover severely deteriorated (5.3.4 (b) (i))

**Minor**

Offside Front Lower Suspension arm ball joint dust cover severely deteriorated (5.3.4 (b) (i))

**Advice**

Front Inner Tyre worn close to legal limit/worn on edge inner and outer edges are slightly worn (5.2.3 (e))

**Minor**

Offside Front Lower Anti-roll bar ball joint dust cover severely deteriorated (5.3.4 (b) (i))

**MOT #13**

2018-04-12 15:19

**MOT test number**

932510365547

**Result**

✓ Passed

**Advice**

Offside Rear tyre outer wall deteriorated

**Advice**

Nearside Rear tyre outer wall deteriorated

**MOT #12**

2017-04-03 11:17

**MOT test number**

687003146128

**Result**

✓ Passed

**Advice**

ENGINE COVER &amp; UNDER TRAY FITTED

**Advice**

Nearside Rear TYRE IS OLD &amp; HAS CRACKS ON SIDE WALL AROUND NEAR THE WHEEL

**Advice**

Rear Brake pad(s) wearing thin SEEMS LOW , ADVISE BRAKE INSPECTION (3.5.1g)

**MOT #11**

2016-04-11 14:38

**MOT test number**

242818778861

**Result**

✓ Passed

**Advice**

ENGINE COVER &amp; UNDER TRAY FITTED

**Advice**

Headlamp has a product on the lens but not seriously reducing light output BOTH GETTING FOGGY (1.7.5a)

**MOT #10** 2016-04-11 08:35**MOT test number** 604046535418**Result** ✗ Failed**Advice** Rear Brake pad(s) wearing thin STRONG ADVICE (3.5.1g)**Advice** ENGINE COVER & UNDER TRAY FITTED**Fail** Offside Registration plate lamp not working (1.1.C.1d)**Advice** Headlamp has a product on the lens but not seriously reducing light output BOTH GETTING FOGGY (1.7.5a)**Advice** AIR FRESHENER BLOCKING VIEW REMOVED**MOT #9** 2015-04-28 11:26**MOT test number** 486058815128**Result** ✓ Passed**Notice** Sealant on nearside front outer CV boot.**MOT #8** 2014-04-30 12:53**MOT test number** 169900624135**Result** ✓ Passed

**MOT #7** 2014-04-22 12:51**MOT test number** 698592214196**Result** ✗ Failed

- Fail** Nearside Rear Registration plate lamp not working (1.1.C.1d)
- Fail** Nearside Front Steering rack insecure (2.2.B.1a)
- Fail** Supplementary Restraint System warning lamp indicates a fault (5.4.2)
- Fail** Nearside Rear Tyre tread depth below requirements of 1.6mm (4.1.E.1)
- Fail** Front Brake pad(s) less than 1.5 mm thick (3.5.1g)
- Advice** Offside Rear Tyre worn close to the legal limit (4.1.E.1)
- Fail** Offside Front Tyre tread depth below requirements of 1.6mm (4.1.E.1)

**MOT #6** 2013-10-30 14:00**MOT test number** 157283303321**Result** ✓ Passed**MOT #5** 2012-10-10 11:37**MOT test number** 598524782262**Result** ✓ Passed**MOT #4** 2011-10-06 11:02**MOT test number** 176109071277**Result** ✓ Passed

- Advice** Nearside Rear Tyre worn close to the legal limit (4.1.E.1)
- Advice** Offside Front Tyre worn close to the legal limit (4.1.E.1)
- Advice** Nearside Front Tyre worn close to the legal limit (4.1.E.1)

**MOT #3** 2010-10-06 14:38**MOT test number** 944139970257**Result** ✓ Passed**MOT #2** 2009-11-18 10:14**MOT test number** 344192729353**Result** ✓ Passed**Advice** Nearside Front Tyre worn close to the legal limit (4.1.E.1)**Notice** Air con lower pipe leaking fluid osf under car**Advice** Offside Front Tyre worn close to the legal limit (4.1.E.1)**MOT #1** 2008-11-05 12:52**MOT test number** 332150918367**Result** ✓ Passed**Advice** Nearside Front Brake pad(s) wearing thin (3.5.1g)





Tax & MOT check

✓  
**Taxed**  
**Tax due:**  
1 July 2024

✓  
**MOT**  
**Expires:**  
21 February 2025

<b>Tax status</b>	Valid until 1 July
<b>Days left</b>	63
<b>MOT expiry date</b>	21 February 2025
<b>Full MOT history</b>	<a href="#">See MOT history</a>

Tax calculation

<b>Vehicle class</b>	49
<b>Band</b>	K
<b>Single payment (12 months)</b>	£ 395,00,-
<b>Single six month payment</b>	£ 217,25,-
<b>Total payable by 12 monthly instalments</b>	£ 414,75,-



Damage history

Check the damage history for this TOYOTA. See if, where and when this TOYOTA had damage and the car repair costs. We also check if this TOYOTA was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	



Damage 2

Date	
Category	
Type	

Extra TOYOTA salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this TOYOTA in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,999
Auction value	£ 19,999
Average private trade value	£ 19,999

More info >



Owner history

For how long did the current and previous owner(s) have this TOYOTA? How many owners did this TOYOTA have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration

More info >

Plate changes

See in this check if this TOYOTA had different number plates.

Number of plates	1
Current registration	<b>GV55UHU</b>
Plate since	2019-03-29
Current registration	<b>GV55UHU</b>
Plate since	2019-03-29

More info >



Finance check

Check if this TOYOTA is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this TOYOTA has been settled. If not, and you buy this TOYOTA then you could lose the money and the car you paid for. Download the premium report [here](#) and check if this TOYOTA is financed.

Finance company	XXXXXXXXXX	XXXX
Date of agreement	XXXXXXXXXX	XXXX
Agreement type	XXXXXXXXXX	XXXX
Agreement term	XXXXXXXXXX	XXXX
Agreement number	XXXXXXXXXX	XXXX
Contact info	XXXXXXXXXX	XXXX

More info >



Mileage check

Odometer	In miles
Mileage registrations	22
First mileage registration	2005-09-30
Last registration	2024-02-22
Complete history	<a href="#">See info</a>



Registration #1	2005-09-30	21 mi
Registration #2	2008-11-05	22.433 mi
Registration #3	2009-11-18	31.618 mi
Registration #4	2010-10-06	37.390 mi
Registration #5	2011-10-06	44.142 mi
Registration #6	2012-10-10	49.615 mi
Registration #7	2013-10-30	53.494 mi
Registration #8	2014-04-22	54.183 mi
Registration #9	2014-04-30	54.183 mi
Registration #10	2015-04-28	61.688 mi
Registration #11	2016-04-11	68.318 mi
Registration #12	2016-05-20	75.000 mi
Registration #13	2016-06-20	81.682 mi
Registration #14	2016-07-20	88.364 mi
Registration #15	2016-08-20	95.046 mi
Registration #16	2016-09-20	101.728 mi
Registration #17	2016-10-20	108.410 mi
Registration #18	2016-11-20	115.092 mi
Registration #19	2016-12-20	121.774 mi
Registration #20	2017-01-20	128.456 mi
Registration #21	2017-02-20	135.138 mi
Registration #22	2017-03-20	141.820 mi

More info >



Car features

The TOYOTA factory car options list is only available in the premium report.

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

View the complete TOYOTA factory list for this vehicle [here](#).

More info >

Dimensions & weight

Width	1875 mm
Height	1905 mm
Length	4850 mm
Wheel base	2790 mm
Kerb weight	2190 kg
Max. allowed weight	2850 kg

Additional information

Fuel tank capacity	87 l
Fuel delivery	Direct Injection
Number of doors	5
Number of seats	8
Number of axles	2
Engine number	1KD1334867