



**FV65XWC**

report date: 2024-03-29

General information

Make	FORD
Model	TRANSIT
Colour	White
Year of manufacture	2016
Gearbox	-

Engine & fuel consumption

Engine capacity	2.198 cc
Fuel type	Diesel
CO2 emission	212 g/km
CO2 label	K





Internet history

Entry 1

Date	2022-01-15
Pictures	12
Listing price	<a href="#">View report</a>



source: [autotrader.co.uk](#)



## MOT history

MOT expiry date	2024-03-15
MOT pass rate	63 %
MOT passed	5
Failed MOT tests	3
Total advice items	24
Total items failed	10

MOT #8	2023-03-16 18:36
MOT test number	943492347656
Result	✓ Passed
Next expiry date	2024-03-15
Advice	Brake pipe corroded, covered in grease or other material various brake pipes greased (1.1.11 (c))

MOT #7	2023-02-27 16:22
MOT test number	997991005719
Result	✗ Failed
Fail	Offside Rear Tyre has a cut in excess of the requirements deep enough to reach the ply or cords (5.2.3 (d) (i))
Advice	Front Brake disc worn, pitted or scored, but not seriously weakened both very poor condition (1.1.14 (a) (ii))
Fail	Offside Rear Tyre has ply or cords exposed small cut exposing cords (5.2.3 (d) (ii))
Advice	Front Brake pipe corroded, covered in grease or other material both sides sections to front flexi hoses corroded (1.1.11 (c))
Fail	Front Service brake excessively fluctuating both sides (1.2.1 (e))
Fail	Nearside Rear Tyre has ply or cords exposed various cuts in tread exposing cords (5.2.3 (d) (ii))
Fail	Engine MIL inoperative or indicates a malfunction On (8.2.2.2 (g))
Advice	Front Lower Suspension arm pin or bush worn but not resulting in excessive movement both sides lower arms inner rear bushes at limit of acceptable wear/deterioration - recommend replacing (5.3.4 (a) (i))

**MOT #6**

2022-02-02 16:47

**MOT test number**

749670782989

**Result**

✓ Passed

**Advice** Front Suspension arm pin or bush worn but not resulting in excessive movement front lower arm rear bushes both sides (5.3.4 (a) (i))

**Advice** Front Brake pipe corroded, covered in grease or other material both sides inner wheel arch (1.1.11 (c))

**Advice** Front Brake disc worn, pitted or scored, but not seriously weakened both sides worn (1.1.14 (a) (ii))

**MOT #5**

2022-01-20 15:46

**MOT test number**

436327807554

**Result**

✗ Failed

**Advice** Front Brake disc worn, pitted or scored, but not seriously weakened both sides worn (1.1.14 (a) (ii))

**Advice** Front Suspension arm pin or bush worn but not resulting in excessive movement front lower arm rear bushes both sides (5.3.4 (a) (i))

**Fail** Nearside Rear Body panel likely to become detached number plate panel loose (6.2.1 (a) (ii))

**Advice** Front Brake pipe corroded, covered in grease or other material both sides inner wheel arch (1.1.11 (c))

**Minor** Rear Registration plate lamp inoperative in the case of multiple lamps or light sources (4.7.1 (b) (i))

**Fail** Offside Front Windscreen damaged and affecting the driver's view of the road (3.2 (a) (ii))

**MOT #4**

2021-01-20 17:26

**MOT test number**

764751740276

**Result**

✓ Passed

**Advice** Offside Front Suspension arm pin or bush worn but not resulting in excessive movement (5.3.4 (a) (i))

**Advice** Offside Front Brake pipe corroded, covered in grease or other material (1.1.11 (c))

**Advice** Drivers seat cushion is showing signs of wear

**Advice** Nearside Front Brake pipe corroded, covered in grease or other material (1.1.11 (c))

**Advice** Nearside Front Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))



**MOT #3**

2021-01-19 18:33

**MOT test number**

493197527551

**Result****✗ Failed**

**Advice** Offside Front Suspension arm pin or bush worn but not resulting in excessive movement (5.3.4 (a) (i))

**Advice** Nearside Front Brake pipe corroded, covered in grease or other material (1.1.11 (c))

**Advice** Rear offside door handle is missing ,but door can be secured shut

**Advice** Nearside Front Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))

**Fail** Brake pad(s) worn down to wear indicator (1.1.13 (a) (i))

**Fail** Offside Rear Brake pipe excessively corroded (1.1.11 (c))

**Advice** Offside Front Brake pipe corroded, covered in grease or other material (1.1.11 (c))

**Fail** Offside Front Tyre has ply or cords exposed (5.2.3 (d) (ii))

**Advice** Drivers seat cushion is showing signs of wear

**MOT #2**

2020-01-09 15:37

**MOT test number**

764684114449

**Result****✓ Passed**

**Minor** Offside Rear reflector defective or damaged by up to 50% of the reflecting surface (4.8.1 (a) (i))

**MOT #1**

2018-12-05 16:29

**MOT test number**

412599212418

**Result****✓ Passed**

**Advice** Front Brake disc worn, but not excessively (1.1.14 (a) (i))



Damage history

Check the damage history for this FORD. See if, where and when this FORD had damage and the car repair costs. We also check if this FORD was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	

Damage 2

Date	
Category	
Type	



Extra FORD salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this FORD in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,299
Auction value	£ 19,299
Average private trade value	£ 19,299

More info >





Owner history

For how long did the current and previous owner(s) have this FORD? How many owners did this FORD have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since

More info >

Plate changes

See in this check if this FORD had different number plates.

Number of plates	1
Current registration	<b>XXXXXX</b>
Plate since	2024-03-29
Current registration	<b>XXXXXX</b>
Plate since	2024-03-29

More info >



Finance check

Check if this FORD is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this FORD has been settled.

If not, and you buy this FORD then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this FORD is financed.

Finance company	XXXXXXXXXX	XXXX
Date of agreement	XXXXXXXXXX	XXXX
Agreement type	XXXXXXXXXX	XXXX
Agreement term	XXXXXXXXXX	XXXX
Agreement number	XXXXXXXXXX	XXXX
Contact info	XXXXXXXXXX	XXXX

More info >



Mileage check

Odometer	In miles
Mileage registrations	9
First mileage registration	2016-01-15
Last registration	2023-03-16
Complete history	<a href="#">See info</a>



Registration #1	2016-01-15	24 mi
Registration #2	2018-12-05	105.384 mi
Registration #3	2020-01-09	143.758 mi
Registration #4	2021-01-19	165.812 mi
Registration #5	2021-01-20	165.831 mi
Registration #6	2023-03-16	165.831 mi
Registration #7	2023-03-16	165.831 mi
Registration #8	2023-03-16	165.831 mi
Registration #9	2023-03-16	165.831 mi

More info >



Car features

The FORD factory car options list is only available in the premium report.

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

View the complete FORD factory list for this vehicle [here](#).

More info >

Safety ratings

NCAP rating	★★★★★
Adult	84%
Children	90%
Pedestrian	48%
Safety systems	71%
Overall rating	76%
Video	<a href="#">see crash video</a>



Additional information

Number of seats	3
Engine number	FM16468