



Mercedes-Benz



report date: 2024-03-28

General information

Make	MERCEDES
Model	CLK CLK280 SPORT
Colour	Blue
Year of manufacture	2008
Top speed	150 mph
0 - 60 mph	7.8 seconds
Gearbox	7 speed automatic

Engine & fuel consumption

Power	228 BHP
Max. torque	300 Nm at 3.000 rpm
Engine capacity	2.996 cc
Cylinders	6
Fuel type	Petrol
Consumption city	20.8 mpg
Consumption extra urban	38.7 mpg
Consumption combined	29.4 mpg
CO2 emission	229 g/km
CO2 label	L



Internet history

Entry 1

Date	2021-05-24
Pictures	8
Listing price	View report





REPRESENTATIVE EXAMPLE			
CASH PRICE	£1,249.00	FIXED INTEREST RATE	5.17% PA
DEPOSIT	£1,100.00	REPRESENTATIVE APR	6.95% APR
TOTAL AMOUNT OF CREDIT	£1,100.00	DURATION OF AGREEMENT	36 MONTHS
TOTAL AMOUNT PAYABLE	£1,100.00	INITIAL PAYMENT	£0.00
ADMINISTRATION FEE	£0.00	12 MONTHLY PAYMENTS	£29.00
OPTION TO PURCHASE FEE	£0.00	FINAL PAYMENT	£29.00





source: autotrader.co.uk



MOT history

MOT expiry date	2025-02-22
MOT pass rate	82 %
MOT passed	14
Failed MOT tests	3
Total advice items	29
Total items failed	5

MOT #17 2024-02-21 08:49

MOT test number 708246316760

Result ✓ Passed

Next expiry date 2025-02-22

- Advice** Nearside Front Wheel bearing has slight play (5.1.3 (a) (i))
- Advice** Nearside Front Inner Brake disc worn, pitted or scored, but not seriously weakened pitted and scored (1.1.14 (a) (ii))
- Advice** Nearside Rear Brake disc worn, pitted or scored, but not seriously weakened pitted (1.1.14 (a) (ii))
- Advice** Offside Front Wheel bearing has slight play (5.1.3 (a) (i))
- Advice** Offside Front Inner Brake disc worn, pitted or scored, but not seriously weakened pitted and scored (1.1.14 (a) (ii))
- Advice** Offside Rear Brake disc worn, pitted or scored, but not seriously weakened pitted (1.1.14 (a) (ii))

MOT #16 2023-02-23 08:40

MOT test number 810091835470

Result ✓ Passed

- Advice** Offside Front Wheel bearing has slight play (5.1.3 (a) (i))

MOT #15 2022-02-03 15:08

MOT test number 374377676914

Result ✓ Passed

**MOT #14** 2022-01-31 09:29**MOT test number** 523304340035**Result** ✗ Failed

- Minor** Offside Indicator tell-tale inoperative (4.9.1 (a) (i))
- Fail** Anti-lock braking system warning lamp does not illuminate (1.6 (a))
- Fail** Main beam tell-tale not working (4.9.1 (a) (ii))
- Minor** Nearside Indicator tell-tale missing (4.9.1 (a) (i))
- Fail** Speedometer clearly inoperative (7.8 (b) (ii))
- Advice** Supplementary restraint system warning lamp does not illuminate (7.1.6 (a))

MOT #13 2021-02-03 11:01**MOT test number** 504566328447**Result** ✓ Passed**MOT #12** 2020-01-14 10:39**MOT test number** 124717440314**Result** ✓ Passed

- Advice** Nearside Front Inner Tyre has a cut but not deep enough to reach the ply or cords sidewall (5.2.3 (d) (i))

MOT #11 2019-01-15 11:30**MOT test number** 544729360778**Result** ✓ Passed

- Advice** Offside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))
- Advice** Offside Front Tyre has a cut but not deep enough to reach the ply or cords side wall (5.2.3 (d) (i))
- Advice** Nearside Front Tyre has a cut but not deep enough to reach the ply or cords side wall (5.2.3 (d) (i))

**MOT #10** 2018-01-22 11:01**MOT test number** 116837197142**Result** ✓ Passed**Advice** Cuts in both front tyre walls**MOT #9** 2017-01-23 10:47**MOT test number** 535908257246**Result** ✓ Passed**Advice** Both nearside tyre walls damaged**MOT #8** 2016-01-26 15:35**MOT test number** 508677916025**Result** ✓ Passed**Advice** Under trays fitted restricting view of underside components**Advice** Engine cover fitted restricting view of components under bonnet**Advice** Front Brake pad(s) wearing thin (3.5.1g)**MOT #7** 2016-01-26 10:37**MOT test number** 370703674940**Result** ✗ Failed**Advice** Front Brake pad(s) wearing thin (3.5.1g)**Advice** Engine cover fitted restricting view of components under bonnet**Fail** Offside Rear Tyre tread depth below requirements of 1.6mm (4.1.E.1)**Advice** Under trays fitted restricting view of underside components

**MOT #6** 2015-01-19 10:33**MOT test number** 258529115031**Result** ✓ Passed**Advice** Offside Rear Tyre worn close to the legal limit (4.1.E.1)**MOT #5** 2014-01-22 12:17**MOT test number** 125822124436**Result** ✓ Passed**Advice** Nearside Rear Tyre worn close to the legal limit (4.1.E.1)**Notice** Front pads getting low**MOT #4** 2013-01-31 11:44**MOT test number** 148641733498**Result** ✓ Passed**MOT #3** 2013-01-29 12:04**MOT test number** 468979723047**Result** ✗ Failed**Fail** Nearside Rear Tyre tread depth below requirements of 1.6mm (4.1.E.1)**MOT #2** 2012-01-25 12:11**MOT test number** 235935522095**Result** ✓ Passed**Advice** Offside Rear Tyre worn close to the legal limit (4.1.E.1)**Advice** Nearside Rear Tyre worn close to the legal limit (4.1.E.1)



MOT #1	2011-02-02 16:14
MOT test number	856273731046
Result	✓ Passed
Notice	Front tyres wearing on both out side and inside edges
Advice	Nearside Rear Seat belt stitching slightly frayed (5.2.2b)



Tax & MOT check

✓
Taxed
Tax due:
1 February 2025

✓
MOT
Expires:
22 February 2025

Tax status	Valid until 1 February
Days left	279
MOT expiry date	22 February 2025
Full MOT history	See MOT history

Tax calculation

Vehicle class	48
Band	L
Single payment (12 months)	£ 675,00,-
Single six month payment	£ 371,25,-
Total payable by 12 monthly instalments	£ 708,75,-



Damage history


Check the damage history for this MERCEDES. See if, where and when this MERCEDES had damage and the car repair costs. We also check if this MERCEDES was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	

Damage 2

Date	
Category	
Type	



Extra MERCEDES salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this MERCEDES in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,999
Auction value	£ 19,999
Average private trade value	£ 19,999

More info >



Owner history

For how long did the current and previous owner(s) have this MERCEDES? How many owners did this MERCEDES have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since

More info >

Plate changes

See in this check if this MERCEDES had different number plates.

Number of plates	1
Current registration	 RF57VDM
Plate since	2019-06-29
Current registration	 RF57VDM
Plate since	2019-06-29

More info >



Finance check

Check if this MERCEDES is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this MERCEDES has been settled.

If not, and you buy this MERCEDES then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this MERCEDES is financed.

Finance company	REDACTED	REDACTED
Date of agreement	REDACTED	REDACTED
Agreement type	REDACTED	REDACTED
Agreement term	REDACTED	REDACTED
Agreement number	REDACTED	REDACTED
Contact info	REDACTED	REDACTED

More info >



Mileage check

Odometer	In miles
Mileage registrations	18
First mileage registration	2008-01-30
Last registration	2024-02-21
Complete history	See info



Registration #1	2008-01-30	8 mi
Registration #2	2011-02-02	33.116 mi
Registration #3	2012-01-25	37.899 mi
Registration #4	2013-01-29	42.961 mi
Registration #5	2013-01-31	42.982 mi
Registration #6	2014-01-22	47.115 mi
Registration #7	2015-01-19	50.780 mi
Registration #8	2016-01-26	55.195 mi
Registration #9	2016-01-26	55.195 mi
Registration #10	2016-01-26	55.195 mi
Registration #11	2016-01-26	55.195 mi
Registration #12	2016-01-26	55.195 mi
Registration #13	2016-01-26	55.195 mi
Registration #14	2016-01-26	55.195 mi
Registration #15	2016-01-26	55.195 mi
Registration #16	2016-01-26	55.195 mi
Registration #17	2016-01-26	55.195 mi
Registration #18	2016-01-26	55.195 mi

More info >



Dimensions & weight

Width	1991 mm
Height	1415 mm
Length	4652 mm
Wheel base	2690 mm
Kerb weight	1705 kg

Additional information

Fuel tank capacity	62 l
Fuel delivery	Multi-Point Injection
Number of doors	2
Number of seats	4
Number of axles	2
Engine number	27294030954540