





report date: 2024-03-29

## General information

Make	PEUGEOT
Model	206 ALLURE COUPE CABRIOLET
Colour	Blue
Year of manufacture	2006
Top speed	120 mph
0 - 60 mph	11.3 seconds
Gearbox	5 speed Manual

## Engine & fuel consumption

Power	107 BHP
Max. torque	147 Nm at 4.000 rpm
Engine capacity	1.587 cc
Cylinders	4
Fuel type	Petrol
Consumption city	29.7 mpg
Consumption extra urban	49.6 mpg
Consumption combined	40.4 mpg
CO2 emission	166 g/km
CO2 label	Н



CarCheck.co.uk page 1/13



MOT history

MOT expiry date	2021-07-15
MOT pass rate	67 %
MOT passed	12
Failed MOT tests	6
Total advice items	24
Total items failed	12

MOT #18	2020-07-16 12:10
MOT test number	657033545484
Result	✓ Passed
Next expiry date	2021-07-15

MOT #17		2020-07-16 12:10
MOT test number		322469292548
Result		<b>×</b> Failed
Pass with rectification	Nearside Headlamp not working on dipped beam (4.1.1 (a) (ii))	

MOT #16	2019-04-01 15:08
MOT test number	839083820078
Result	✓ Passed

CarCheck.co.uk page 2/13



**MOT #15** 2018-04-30 14:27

MOT test number 268039755742

Advice Nearside rear tyre has age cracking in tread

Advice Offside Rear Nail in tyre

Advice Nearside front tyre has damage to outer sidewall but not exposing ply or cords

Advice Both rear tyres worn beyond legal limits on inner edge/shoulders

Advice Offside front tyre worn beyond legal limits on edges/shoulders

**Advice** Nearside Front Road wheel with a slightly distorted bead rim (4.2.A.1a)

**Advice** Offside door check strap broken and no longer functioning

**Advice** Offside front tyre has cracking in inner and outer sidewalls

**MOT #14** 2018-04-30 08:47

MOT test number 110019759096

Result × Failed

Fail Nearside Front Anti-roll bar linkage has excessive play in a pin/bush (2.4.G.2)

Advice Nearside front tyre has damage to outer sidewall but not exposing ply or cords

**Advice** Both rear tyres worn beyond legal limits on inner edge/shoulders

**Advice** Offside front tyre worn beyond legal limits on edges/shoulders

Advice Nearside Front Road wheel with a slightly distorted bead rim (4.2.A.1a)

Advice Offside door check strap broken and no longer functioning

Fail Offside Front Anti-roll bar linkage has excessive play in a pin/bush (2.4.G.2)

**Advice** Offside front tyre has cracking in inner and outer sidewalls

**Advice** Nearside rear tyre has age cracking in tread

**Advice** Offside Rear Nail in tyre

CarCheck.co.uk page 3/13



KV06HGY

report date: 2024-03-29

**MOT #13** 2017-05-08 08:55

**MOT test number** 609183643718

MOT #12 2016-04-16 11:50

MOT test number 260685023381

Result 

Passed

**MOT #11** 2016-04-12 08:48

MOT test number 271442991252

**Result** X Failed

**Fail** Offside Front Anti-roll bar linkage ball joint dust cover excessively damaged so that it no longer prevents the ingress of dirt (2.4.G.2)

Fail Nearside Windscreen wiper does not clear the windscreen effectively (8.2.2)

Fail Rear Exhaust has a major leak of exhaust gases (7.1.2)

**MOT #10** 2015-04-30 16:29

**MOT test number** 568970825138

MOT #9 2014-05-07 14:17

**MOT test number** 275037924148

**Advice** Offside Rear Tyre worn close to the legal limit (4.1.E.1)

**Advice** Nearside Front Tyre worn close to the legal limit (4.1.E.1)

**Notice** Rear brake pads low

CarCheck.co.uk page 4/13



MOT #8 2013-04-16 16:13

**MOT test number** 336336103170

**Notice** O/s/r tyre getting low

MOT #7 2013-04-16 16:13

**MOT test number** 779826803161

Result × Failed

**Notice** O/s/r tyre getting low

**Pass with rectification** Nearside Headlamp not working on dipped beam (1.7.5a)

MOT #6 2012-04-17 15:41

**MOT test number** 696328702195

**Result** ✓ Passed

**MOT #5** 2012-04-16 15:38

**MOT test number** 467437802144

**Result** X Failed

**Notice** N/s/r tyre puntured in 3 places

**Fail** Nearside Front brake disc in such a condition that it is seriously weakened (3.5.1i)

MOT #4 2011-04-08 13:35

**MOT test number** 155698591065

CarCheck.co.uk page 5/13



MOT #3 2011-04-08 13:13

**MOT test number** 707828691019

**Result** X Failed

Fail Offside Front Wheel bolt(s) missing (4.2.A.1e)

**Fail** Offside Rear Wheel bolt(s) missing (4.2.A.1e)

Fail Nearside Front Wheel bolt(s) missing (4.2.A.1e)

Fail Nearside Rear Wheel bolt(s) missing (4.2.A.1e)

MOT #2 2010-03-09 15:35

**MOT test number** 452968660062

Result \rightarrow Passed

**Advice** Nearside Front brake disc slightly pitted (3.5.1h)

**Advice** Offside Front brake disc slightly pitted (3.5.1h)

MOT #1 2009-03-26 09:27

**MOT test number** 111715389060

**Result** ✓ Passed

CarCheck.co.uk page 6/13



## Tax & MOT check



Expired: 15 July 2021

X **MOT** 

Tax expired: 3 February 2021

Expired at 3 February 2021

**Days left** 1182 days too late

**MOT** expiry date 15 July 2021

**Full MOT history** See MOT history

## Tax calculation

**Tax status** 

Vehicle class	48
Band	Н
Single payment (12 months)	£ 290,00,-
Single six month payment	£ 159,50,-
Total payable by 12 monthly instalments	£ 304,50,-

CarCheck.co.uk page 7/13



Damage history

Check the damage history for this PEUGEOT. See if, where and when this PEUGEOT had damage and the car repair costs. We also check if this PEUGEOT was scrapped. Download the premium report <u>here</u> for the results.

Damage 1
Date
Category
Type
Damage 2
Date
Category
Type



### Extra PEUGEOT salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report <u>here</u> for more information.

More info >

CarCheck.co.uk page 8/13



## Vehicle valuation

What is this car worth? See the vehicle value of this PEUGEOT in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

**Trade retail value** 

**Auction value** 

Average private trade value

More info >

CarCheck.co.uk page 9/13



Owner history

factor scincore

KV06HGY

report date: 2024-03-29

# For how long did the current and previous owner(s) have this PEUGEOT? How many owners did this PEUGEOT have? Check it in the premium report and see all owner registrations. Download the full report <a href="https://example.com/here.">here.</a> More info > Plate changes

See in this check if this PEUGEOT had different number plates.

More info >

CarCheck.co.uk page 10/13



## Finance check

Check if this PEUGEOT is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this PEUGEOT has been settled.

If not, and you buy this PEUGEOT then you could lose the money and the car you paid for.

Download the premium report <u>here</u> and check if this PEUGEOT is financed.

Finance company	
Date of agreement	
Agreement type	
Agreement term	
Agreement number	

**Contact info** 


More info >

CarCheck.co.uk page 11/13



Mileage check

Odometer	In miles
Mileage registrations	18
First mileage registration	2006-03-30
Last registration	2020-07-16
Complete history	See info



Registration #1	2006-03-30	17 mi
Registration #2	2009-03-26	5.570 mi
Registration #3	2010-03-09	6.918 mi
Registration #4	2011-04-08	20.920 mi
Registration #5	2011-04-08	20.920 mi
Registration #6	2012-04-16	34.287 mi
Registration #7	2012-04-17	34.287 mi
Registration #8	2013-04-16	44.891 mi
Registration #9	2014-05-07	56.270 mi
Registration #10		71.777 es
Registration #11		11.777 es
Registration #12		71.777 es
Registration #13		11.777 es
Registration #14		71.777 es
Registration #15		11.777 es
Registration #16		71.777 es
Registration #17		11.777 es
Registration #18		11.777 au

More info >

CarCheck.co.uk page 12/13



# Car features

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

# Safety ratings

NCAP rating	***
Video	see crash video



# Dimensions & weight

Width	1673 mm
Height	1373 mm
Length	3835 mm
Wheel base	2442 mm
Kerb weight	1215 kg
Max. allowed weight	1535 kg

# Additional information

Fuel tank capacity	47
Fuel delivery	Multi-Point Injection
Number of doors	2
Number of seats CarCheck.co.uk	4 page 13/1:

Number of axles 2

**Engine number** FX6N2895274