





report date: 2024-03-28

General information

| Make | HYUNDAI |
|---------------------|-------------------------|
| Model | TUCSON GDI S BLUE DRIVE |
| Colour | Black |
| Year of manufacture | 2017 |
| Top speed | 113 mph |
| 0 - 60 mph | 11.5 seconds |
| Gearbox | 6 speed Manual |

Engine & fuel consumption

| Power | 130 BHP |
|-------------------------|---------------------|
| Max. torque | 161 Nm at 4.850 rpm |
| Engine capacity | 1.591 cc |
| Cylinders | 4 |
| Fuel type | Petrol |
| Consumption city | 35.8 mpg |
| Consumption extra urban | 52.3 mpg |
| Consumption combined | 44.8 mpg |
| CO2 emission | 147 g/km |
| CO2 label | F |



CarCheck.co.uk page 1/11



report date: 2024-03-28

Internet history

Entry 2

Date 2021-11-28

Pictures 11

Listing price <u>View report</u>









source: cargurus.co.uk

Entry 1

| Date | 2021-06-06 |
|------|------------|
| | |

Pictures 3

Listing price <u>View report</u>







source: yesauto.com

CarCheck.co.uk page 2/11



report date: 2024-03-28

MOT history

| MOT expiry date | 2025-01-04 |
|--------------------|------------|
| MOT pass rate | 71 % |
| MOT passed | 5 |
| Failed MOT tests | 2 |
| Total advice items | 8 |
| Total items failed | 4 |

| MOT #7 | | 2023-12-11 14:57 |
|---|---|------------------|
| MOT test | number | 482502860957 |
| Result | | ✓ Passed |
| Next expiry date 2025-01 | | 2025-01-04 |
| Advice Offside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e)) | | |
| Advice | Nearside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e)) | |

| MOT #6 | 2023-12-11 09:05 |
|--|------------------|
| MOT test number | 801410453516 |
| Result | × Failed |
| Advice Offside Front Brake pad(s) wearing thin (1.1.13 (a) (ii)) | |
| Advice Nearside Front Brake disc worn, but not excessively (1.1.14 (a) (i)) | |
| Fail Offside Front Tyre tread depth below requirements of 1.6mm (5.2.3 (e)) | |
| Advice Offside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e)) | |
| Advice Nearside Front Brake pad(s) wearing thin (1.1.13 (a) (ii)) | |
| Fail Nearside Front Tyre tread depth below requirements of 1.6mm (5.2.3 (e)) | |
| Advice Offside Front Brake disc worn, but not excessively (1.1.14 (a) (i)) | |
| Advice Nearside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e)) | |

CarCheck.co.uk page 3/11



report date: 2024-03-28

| MOT #5 | 2022-12-19 09:38 |
|-----------------|------------------|
| MOT test number | 914533709135 |
| Result | ✓ Passed |
| | |
| MOT #4 | 2022-01-05 12:22 |
| MOT test number | 389853021342 |
| Result | ✓ Passed |
| | |
| MOT #3 | 2021-06-10 16:01 |
| MOT test number | 328800432567 |
| Result | ✓ Passed |
| | |
| MOT #2 | 2020-12-07 06:49 |
| MOT test number | 659343643333 |
| Result | ✓ Passed |
| | |
| MOT #1 | 2020-12-03 11:02 |

| MOT #1 | 2020-12-03 11:02 |
|--|------------------|
| MOT test number | 811002599845 |
| Result | × Failed |
| Fail Front Windscreen wiper does not clear the windscreen effectively (3.4 (b) (ii)) | |
| Fail Engine MIL inoperative or indicates a malfunction (8.2.1.2 (h)) | |

CarCheck.co.uk page 4/11



EK67WKV
report date: 2024-03-28

Tax & MOT check



| Tax status | Valid until 1 January |
|------------------|-----------------------|
| Days left | 247 |
| MOT expiry date | 4 January 2025 |
| Full MOT history | See MOT history |

Tax calculation

| Vehicle class | 48 |
|-------------------------------|------------|
| Band | Н |
| First licence fee (12 months) | £ 255,00,- |
| Standard rate (12 months) | £ 180,00,- |
| Standard rate (6 months) | £ 99,00,- |
| Premium rate (12 months) | £ 570,00,- |
| Premium rate (6 months) | £ 313,50,- |

CarCheck.co.uk page 5/11



report date: 2024-03-28

Damage history

Check the damage history for this HYUNDAI. See if, where and when this HYUNDAI had damage and the car repair costs. We also check if this HYUNDAI was scrapped. Download the premium report here for the results.

Damage 1
Date
Category
Type
Damage 2
Date
Category
Type



Extra HYUNDAI salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report <u>here</u> for more information.

More info >

CarCheck.co.uk page 6/11



report date: 2024-03-28

Vehicle valuation

What is this car worth? See the vehicle value of this HYUNDAI in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value

Auction value

Average private trade value

More info >

CarCheck.co.uk page 7/11



faste since

EK67WKV

report date: 2024-03-28

For how long did the current and previous owner(s) have this HYUNDAI? How many owners did this HYUNDAI have? Check it in the premium report and see all owner registrations. Download the full report here. More info > Plate changes See in this check if this HYUNDAI had different number plates.

More info >

CarCheck.co.uk page 8/11



report date: 2024-03-28

Finance check

Check if this HYUNDAI is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this HYUNDAI has been settled.

If not, and you buy this HYUNDAI then you could lose the money and the car you paid for.

Download the premium report <u>here</u> and check if this HYUNDAI is financed.

| Finance company | |
|-------------------|--|
| Date of agreement | |
| Agreement type | |
| Agreement term | |
| Agreement number | |
| | |

Contact info

More info >

CarCheck.co.uk page 9/11



report date: 2024-03-28

Mileage check

| Odometer | In miles |
|----------------------------|------------|
| Mileage registrations | 10 |
| First mileage registration | 2017-11-29 |
| Last registration | 2023-12-11 |
| Complete history | See info |



| Registration #1 | 2017-11-29 | 9 mi |
|---------------------------------|------------|----------------------------------|
| Registration #2 | 2020-12-03 | 14.042 mi |
| Registration #3 | 2020-12-07 | 14.042 mi |
| Registration #4 | | 11.777 es |
| Registration #5 | 2021-06-10 | 14.048 mi |
| | | |
| Registration #6 | | 11.777 es |
| Registration #6 Registration #7 | | 11,177 ea 11,177 ea |
| | | 11.77 m |
| Registration #7 | | 11.77 es 11.77 es 11.77 es |

More info >

CarCheck.co.uk page 10/11



report date: 2024-03-28

Car features

| 50225 | Air conditioning |
|-------|------------------|
| S0295 | |
| 50482 | |
| 50501 | |
| 50566 | |
| 50567 | |
| 50569 | |

Safety ratings

| NCAP rating | **** |
|----------------|-----------------|
| Adult | 86% |
| Children | 85% |
| Pedestrian | 71% |
| Safety systems | 71% |
| Overall rating | 80% |
| Video | see crash video |



Dimensions & weight

| Width | 1850 mm |
|---------------------|---------|
| Height | 1645 mm |
| Length | 4475 mm |
| Wheel base | 2670 mm |
| Kerb weight | 1464 kg |
| Max. allowed weight | 1895 kg |

Additional information

| Fuel tank capacity | 62 I |
|-----------------------------------|-----------------------|
| Fuel delivery | Multi-Point Injection |
| Number of doors | 5 |
| Number of seats CarCheck.co.uk | 5 page 11/11 |

Number of axles 2

Engine number G4FDHZ947577