



BN09BXB

report date: 2024-03-29

General information

Make	FORD
Model	TRANSIT 350 H/R P/V
Colour	Blue
Year of manufacture	2009
Gearbox	6 speed Manual

Engine & fuel consumption

Power	113 BHP
Engine capacity	2.402 cc
Cylinders	4
Fuel type	Diesel



LABEL UNKNOWN



MOT history

MOT expiry date	2023-03-09
MOT pass rate	58 %
MOT passed	11
Failed MOT tests	8
Total advice items	70
Total items failed	6

MOT #19 2022-03-10 17:56

MOT test number 912548763285

Result ✓ Passed

Next expiry date 2023-03-09

Advice Nearside Rear Suspension component mounting prescribed area damaged but not considered excessive (5.3.6 (a) (i))

Advice Offside Rear Suspension component mounting prescribed area damaged but not considered excessive (5.3.6 (a) (i))

MOT #18 2022-03-09 19:27

MOT test number 903941864185

Result ✗ Failed

MAJOR Nearside Front Windscreen wiper does not clear the windscreen effectively (3.4 (b) (ii))

MAJOR Nearside Rear Stop lamp(s) not working (4.3.1 (a) (ii))

MAJOR Offside Front Windscreen wiper does not clear the windscreen effectively (3.4 (b) (ii))

Advice Nearside Rear Suspension component mounting prescribed area damaged but not considered excessive (5.3.6 (a) (i))

MAJOR Nearside Rear Shock absorbers has a serious fluid leak (5.3.2 (b))

MAJOR Nearside Front Windscreen wiper does not clear the windscreen effectively (3.4 (b) (ii))

Advice Offside Rear Suspension component mounting prescribed area damaged but not considered excessive (5.3.6 (a) (i))

**MOT #17** 2021-03-06 13:23**MOT test number** 492095145337**Result** ✓ Passed**MOT #16** 2021-03-05 18:15**MOT test number** 874129309405**Result** ✗ Failed**MAJOR** Nearside Front Headlamp not working on main beam (4.1.1 (a) (ii))**MAJOR** Nearside Rear Lower Shock absorbers has an excessively worn bush (5.3.2 (c))**MAJOR** Rear Exhaust system insecure (6.1.2 (a))**MOT #15** 2020-02-27 12:30**MOT test number** 926411757361**Result** ✓ Passed**Advice** Rear Brake pad(s) wearing thin (1.1.13 (a) (ii))**MOT #14** 2020-02-27 12:30**MOT test number** 173585095603**Result** ✗ Failed**Pass with rectification** Nearside Front Front passenger door catch insecure striker plate welded (6.2.3 (c) (ii))**Advice** Rear Brake pad(s) wearing thin (1.1.13 (a) (ii))

**MOT #13**

2020-02-27 09:28

MOT test number

153645969192

Result**✗ Failed**

- MAJOR** Offside Headlamp aim not tested (4.1.2 (b))
- Advice** Rear Brake pad(s) wearing thin (1.1.13 (a) (ii))
- MAJOR** Engine MIL inoperative or indicates a malfunction on (8.2.2.2 (g))
- MAJOR** Offside Headlamp not working on dipped beam (4.1.1 (a) (ii))
- MAJOR** Offside Stop lamp(s) not working (4.3.1 (a) (ii))
- MAJOR** Offside Obligatory mirror seriously damaged, affecting the rear view (3.3 (b) (ii))
- Minor** Offside Registration plate lamp inoperative in the case of multiple lamps or light sources (4.7.1 (b) (i))
- MAJOR** Nearside Front Upper Outline marker lamp not working (4.2.1 (a) (ii))

MOT #12

2019-02-21 14:17

MOT test number

234630329383

Result**✓ Passed**

- Advice** Nearside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))
- Advice** Offside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))

**MOT #11**

2019-02-19 14:14

MOT test number

308113818582

Result**✗ Failed**

- Advice** Nearside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))
- MAJOR** Nearside Rear Stop lamp(s) not working (4.3.1 (a) (ii))
- MAJOR** Parking brake efficiency below requirements (1.4.2 (a) (i))
- DANGEROUS** Rear Brake disc in such a condition that it is seriously weakened breaking away on face (1.1.14 (a) (ii))
- MAJOR** Offside Obligatory mirror seriously damaged, affecting the rear view (3.3 (b) (ii))
- Advice** Offside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))
- MAJOR** Rear Brake pad(s) worn down to wear indicator (1.1.13 (a) (i))
- MAJOR** Engine MIL inoperative or indicates a malfunction (8.2.2.2 (g))

MOT #10

2018-02-20 16:57

MOT test number

756954182999

Result**✓ Passed**

- Advice** Rear Anti-roll bar linkage has slight play in a ball joint both sides (2.4.G.2)
- Advice** Offside Front Lower Front suspension has slight movement at a wishbone pin or bush rear bush (2.5.A.1c)
- Advice** Nearside Front Lower Front suspension has slight movement at a wishbone pin or bush rear bush (2.5.A.1c)
- Advice** Rear brake disc worn, pitted or scored, but not seriously weakened (3.5.1i)
- Advice** Chasis crossmember corroded

**MOT #9** 2017-02-15 13:58**MOT test number** 607883269256**Result** ✓ Passed**Advice** Nearside Rear Anti-roll bar linkage has slight play in a pin/bush (2.4.G.2)**Advice** Offside Front Lower Anti-roll bar linkage has slight play in a ball joint (2.4.G.2)**Advice** Offside Rear Anti-roll bar linkage has slight play in a pin/bush (2.4.G.2)**MOT #8** 2017-01-25 17:26**MOT test number** 547771473315**Result** ✗ Failed**Advice** Offside Front Lower Anti-roll bar linkage has slight play in a ball joint (2.4.G.2)**Advice** Nearside Rear Lower Anti-roll bar linkage has slight play in a pin/bush (2.4.G.2)**Fail** Fuel cap/sealing device does not fasten securely by positive means (7.2.4b)**Fail** Offside Rear Lower Shock absorber has an excessively worn bush (2.7.4)**Advice** Offside Rear Lower Anti-roll bar linkage has slight play in a pin/bush (2.4.G.2)**MOT #7** 2016-02-26 10:10**MOT test number** 223899640087**Result** ✓ Passed**Advice** Offside Front Suspension arm rubber bush deteriorated but not resulting in excessive movement
Wishbone rear bush (2.4.G.2)**Advice** Brake hose has slight corrosion to ferrules All (3.6.B.4e)**Advice** Engine management light on**Advice** Nearside front upper side light inoperative**Advice** Nearside Front Suspension arm rubber bush deteriorated but not resulting in excessive movement
Wishbone rear bush (2.4.G.2)**Advice** Brake pipe slightly corroded All (3.6.B.2c)**Advice** Nearside rear and nearside rear body marker lights inoperative

**MOT #6**

2016-02-26 10:10

MOT test number

233941481067

Result

✗ Failed

Pass with rectification Nearside Rear Stop lamp not working (1.2.1b)**Advice** Nearside rear and nearside rear body marker lights inoperative**Advice** Nearside Front Suspension arm rubber bush deteriorated but not resulting in excessive movement
Wishbone rear bush (2.4.G.2)**Advice** Brake pipe slightly corroded All (3.6.B.2c)**Advice** Engine management light on**Pass with rectification** Nearside Rear Registration plate lamp not working (1.1.C.1d)**Advice** Nearside front upper side light inoperative**Advice** Offside Front Suspension arm rubber bush deteriorated but not resulting in excessive movement
Wishbone rear bush (2.4.G.2)**Advice** Brake hose has slight corrosion to ferrules All (3.6.B.4e)**MOT #5**

2015-02-18 09:45

MOT test number

868199745069

Result

✓ Passed

MOT #4

2014-02-12 11:12

MOT test number

645543944095

Result

✓ Passed

Advice Nearside Front Brake pipe slightly corroded (3.6.B.2c)**Advice** Offside Rear Shock absorber has a slightly worn bush (2.7.4)**Notice** Nail in nearside front tyre**Advice** Offside Front Brake pipe slightly corroded (3.6.B.2c)**Notice** Items removed from driver's view prior to test

**MOT #3** 2013-02-28 13:01**MOT test number** 808909253024**Result** ✓ Passed**Advice** Offside Inner Rear Tyre worn close to the legal limit (4.1.E.1)**Advice** Nearside Inner Rear Tyre worn close to the legal limit (4.1.E.1)**Advice** Offside Front Brake pipe slightly corroded (3.6.B.2c)**Advice** Offside Outer Rear Tyre worn close to the legal limit (4.1.E.1)**MOT #2** 2013-02-28 13:01**MOT test number** 705879353009**Result** ✗ Failed**Pass with rectification** Offside Rear Stop lamp not working (1.2.1b)**Advice** Offside Inner Rear Tyre worn close to the legal limit (4.1.E.1)**Advice** Nearside Inner Rear Tyre worn close to the legal limit (4.1.E.1)**Advice** Offside Front Brake pipe slightly corroded (3.6.B.2c)**Advice** Offside Outer Rear Tyre worn close to the legal limit (4.1.E.1)**MOT #1** 2012-03-13 13:31**MOT test number** 629993372017**Result** ✓ Passed



Tax & MOT check

✕
Untaxed

Tax expired:
30 April 2023

✕
MOT

Expired:
9 March 2023

Tax status	Expired at 30 April 2023
Days left	366 days too late
MOT expiry date	9 March 2023
Full MOT history	See MOT history



Damage history

Check the damage history for this FORD. See if, where and when this FORD had damage and the car repair costs. We also check if this FORD was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	

Damage 2

Date	
Category	
Type	



Extra FORD salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this FORD in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,999
Auction value	£ 19,999
Average private trade value	£ 19,999

More info >



Owner history

For how long did the current and previous owner(s) have this FORD? How many owners did this FORD have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	Start date
Owner	Start date
Owner	Start date
Owner	Start date
Owner	Start date
Owner	Start date
Owner	Start date

More info >

Plate changes

See in this check if this FORD had different number plates.

Number of plates	1
Current registration	BN09BXB
Plate since	2024-03-29
Current registration	BN09BXB
Plate since	2024-03-29

More info >



Finance check

Check if this FORD is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this FORD has been settled.

If not, and you buy this FORD then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this FORD is financed.

Finance company	XXXXXXXX	XXXX
Date of agreement	XXXXXXXX	XXXX
Agreement type	XXXXXXXX	XXXX
Agreement term	XXXXXXXX	XXXX
Agreement number	XXXXXXXX	XXXX
Contact info	XXXXXXXX	XXXX

More info >



Mileage check

Odometer	In miles
Mileage registrations	19
First mileage registration	2009-03-20
Last registration	2022-03-10
Complete history	See info



Registration #1	2009-03-20	11 mi
Registration #2	2012-03-13	73.891 mi
Registration #3	2013-02-28	98.406 mi
Registration #4	2014-02-12	114.578 mi
Registration #5	2015-02-18	131.248 mi
Registration #6	2016-02-26	134.538 mi
Registration #7	2016-02-26	134.538 mi
Registration #8	2017-01-25	138.796 mi
Registration #9	2017-02-15	138.940 mi
Registration #10	2018-02-20	144.675 mi
Registration #11	2019-03-20	151.248 mi
Registration #12	2019-03-20	151.248 mi
Registration #13	2019-03-20	151.248 mi
Registration #14	2019-03-20	151.248 mi
Registration #15	2019-03-20	151.248 mi
Registration #16	2019-03-20	151.248 mi
Registration #17	2019-03-20	151.248 mi
Registration #18	2019-03-20	151.248 mi
Registration #19	2019-03-20	151.248 mi

More info >



Car features

The FORD factory car options list is only available in the premium report.

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

View the complete FORD factory list for this vehicle [here](#).

More info >

Dimensions & weight

Width	2374 mm
Height	2543 mm
Length	5680 mm
Kerb weight	2062 kg
Max. allowed weight	3500 kg

Additional information

Fuel tank capacity	80 l
Fuel delivery	Direct Injection
Number of doors	3
Number of seats	3
Engine number	8K44781