



report date: 2024-03-28

General information

Make	VAUXHALL
Model	AGILA 12V EXPRESSION TWINPORT
Colour	Red
Year of manufacture	-
Top speed	88 mph
0 - 60 mph	16.7 seconds
Gearbox	5 speed Manual

Engine & fuel consumption

Power	58 BHP
Max. torque	85 Nm at 3.800 rpm
Cylinders	3
Fuel type	Petrol
Consumption city	36.7 mpg
Consumption extra urban	50.4 mpg
Consumption combined	44.1 mpg




LABEL UNKNOWN



Internet history

Entry 1

Date	2021-06-20
Pictures	19
Listing price	View report



source: [autotrader.co.uk](#)



MOT history

MOT #21	2021-09-21 15:01
MOT test number	656955647865
Result	✓ Passed
Next expiry date	2022-09-21
Advice	Nearside Front Upper Macpherson strut pin or bush worn but not resulting in excessive movement (5.3.4 (a) (i))
Advice	Exhaust system corroded.

MOT #20	2021-09-20 12:52
MOT test number	606550812948
Result	✗ Failed
Advice	Nearside Front Upper Macpherson strut pin or bush worn but not resulting in excessive movement (5.3.4 (a) (i))
Fail	Offside Rear Brake pipe excessively corroded (1.1.11 (c))
Advice	Exhaust system corroded.
Fail	Nearside Rear Brake pipe excessively corroded (1.1.11 (c))

MOT #19	2020-09-22 15:40
MOT test number	727216847127
Result	✓ Passed
Advice	Front Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))

MOT #18	2019-08-02 11:05
MOT test number	701473665726
Result	✓ Passed

Advice Offside Front Tyre worn close to legal limit/worn on edge 2mm & badly worn to edge 155/65/14 (5.2.3 (e))

Advice Nearside Front Road wheel slightly distorted inner rim (5.2.2 (c) (i))

Advice Nearside Front Tyre worn close to legal limit/worn on edge 2mm & badly worn to edge 155/65/14 (5.2.3 (e))

Advice Offside Rear Tyre worn close to legal limit/worn on edge 3mm & cracking 155/65/14 (5.2.3 (e))

Advice Nearside Rear Road wheel slightly distorted inner rim (5.2.2 (c) (i))

**MOT #17**

2018-08-01 13:53

MOT test number

939193243836

Result

✓ Passed

- Advice** Offside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))
- Advice** Nearside Rear Road wheel slightly distorted inner bead rim (5.2.2 (c) (i))
- Advice** Nearside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))
- Advice** Nearside Front Road wheel slightly distorted inner bead rim (5.2.2 (c) (i))

MOT #16

2018-08-01 08:26

MOT test number

435125195197

Result

✗ Failed

- Advice** Nearside Rear Road wheel slightly distorted inner bead rim (5.2.2 (c) (i))
- Advice** Nearside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))
- Fail** Front Windscreen wiper not working both sides (3.4 (a))
- Advice** Nearside Front Road wheel slightly distorted inner bead rim (5.2.2 (c) (i))
- Fail** Nearside Front Position lamp not working (4.2.1 (a))
- Advice** Offside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))

MOT #15

2017-08-04 09:48

MOT test number

554081283952

Result

✓ Passed

- Advice** Nearside Front Shock absorber has a light misting of oil (2.7.3)
- Advice** Rear exhaust section corroded but not holed or blowing at time of test.
- Advice** Offside Front Shock absorber has a light misting of oil (2.7.3)

**MOT #14** 2016-07-20 09:01**MOT test number** 326427040929**Result** ✓ Passed**MOT #13** 2016-07-20 09:01**MOT test number** 632167896079**Result** ✗ Failed**Pass with rectification** Offside Front Headlamp aim too low (1.8)**MOT #12** 2015-07-18 10:13**MOT test number** 566339195120**Result** ✓ Passed**Advice** Rear registration plate deteriorated but not likely to be misread (6.3.1d)**Advice** Offside Front Track rod end ball joint dust cover deteriorated, but preventing the ingress of dirt (2.2.C.1c)**Notice** Coolant level low**Advice** Centre Exhaust has a minor leak of exhaust gases (7.1.2)**Advice** Front registration plate deteriorated but not likely to be misread (6.3.1d)

**MOT #11** 2015-07-18 10:13**MOT test number** 298259995183**Result** ✗ Failed**Pass with rectification** Offside Headlamp aim too high and too far to the left. (1.8)**Advice** Centre Exhaust has a minor leak of exhaust gases (7.1.2)**Advice** Front registration plate deteriorated but not likely to be misread (6.3.1d)**Notice** Coolant level low**Pass with rectification** Nearside Headlamp aim beam image obviously incorrect (1.8.A.1b)**Advice** Rear registration plate deteriorated but not likely to be misread (6.3.1d)**Advice** Offside Front Track rod end ball joint dust cover deteriorated, but preventing the ingress of dirt (2.2.C.1c)**MOT #10** 2014-07-23 12:27**MOT test number** 726284904204**Result** ✓ Passed**MOT #9** 2014-07-23 08:31**MOT test number** 328514004205**Result** ✗ Failed**Fail** Centre Rear Registration plate lamp not working (1.1.C.1d)**MOT #8** 2013-07-19 12:38**MOT test number** 427180703237**Result** ✓ Passed**Notice** Nail in nearside rear tyre**MOT #7** 2012-08-01 16:34**MOT test number** 537314112292**Result** ✓ Passed

**MOT #6** 2012-08-01 10:34**MOT test number** 729314012272**Result** ✗ Failed**Fail** Rear Registration plate lamp not working (1.1.C.1d)**Notice** Items removed from driver's view prior to test**Fail** Nearside Headlamp aim beam image obviously incorrect (1.8.A.1b)**MOT #5** 2011-07-29 16:29**MOT test number** 546240511202**Result** ✓ Passed**MOT #4** 2011-07-28 12:10**MOT test number** 509129901262**Result** ✗ Failed**Fail** Front Exhaust has a major leak of exhaust gases (7.1.2)**Fail** Registration plate lamp not working (1.1.C.1d)**Fail** Exhaust emissions Lambda reading after 2nd fast idle outside specified limits (7.3.D.3)**Advice** Parking brake: parking brake efficiency only just met. It would appear that the braking system requires adjustment or repair. (3.7.B.7)**MOT #3** 2010-07-29 13:04**MOT test number** 274030710275**Result** ✓ Passed**MOT #2** 2009-07-31 14:18**MOT test number** 640152519254**Result** ✓ Passed



MOT #1	2009-07-31 14:18
MOT test number	540752719253
Result	✗ Failed
Pass with rectification	Nearside Front Headlamp aim too high (1.8)



Damage history

Check the damage history for this VAUXHALL. See if, where and when this VAUXHALL had damage and the car repair costs. We also check if this VAUXHALL was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	



Damage 2

Date	
Category	
Type	



Extra VAUXHALL salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this VAUXHALL in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,299
Auction value	£ 19,299
Average private trade value	£ 19,299

More info >



Owner history

For how long did the current and previous owner(s) have this VAUXHALL? How many owners did this VAUXHALL have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration

More info >

Plate changes

See in this check if this VAUXHALL had different number plates.

Number of plates	1
Current registration	SK56YMO
Plate since	2019-06-29
Current registration	SK56YMO
Plate since	2019-06-29

More info >



Finance check

Check if this VAUXHALL is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this VAUXHALL has been settled.

If not, and you buy this VAUXHALL then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this VAUXHALL is financed.


Finance company	XXXXXXXX	XXXX
Date of agreement	XXXXXXXX	XXXX
Agreement type	XXXXXXXX	XXXX
Agreement term	XXXXXXXX	XXXX
Agreement number	XXXXXXXX	XXXX
Contact info	XXXXXXXX	XXXX

More info >



Mileage check

Odometer	In miles
Mileage registrations	21
First mileage registration	2006-09-01
Last registration	2021-09-21
Complete history	See info



Registration #1	2006-09-01	23 mi
Registration #2	2009-07-31	13.723 mi
Registration #3	2010-07-29	19.087 mi
Registration #4	2011-07-28	25.540 mi
Registration #5	2011-07-29	25.550 mi
Registration #6	2012-08-01	34.160 mi
Registration #7	2012-08-01	34.160 mi
Registration #8	2013-07-19	40.428 mi
Registration #9	2014-07-23	46.924 mi
Registration #10	2014-07-23	46.923 mi
Registration #11	2015-07-18	54.105 mi
Registration #12	2016-07-18	61.287 mi
Registration #13	2017-07-18	68.469 mi
Registration #14	2018-07-18	75.651 mi
Registration #15	2019-07-18	82.833 mi
Registration #16	2020-07-18	90.015 mi
Registration #17	2021-07-18	97.197 mi
Registration #18	2022-07-18	104.379 mi
Registration #19	2023-07-18	111.561 mi
Registration #20	2024-07-18	118.743 mi
Registration #21	2025-07-18	125.925 mi

More info >



Safety ratings

NCAP rating	★★★★★
Video	see crash video



Dimensions & weight

Width	1940 mm
Height	1660 mm
Length	3500 mm
Wheel base	2360 mm
Kerb weight	965 kg
Max. allowed weight	1435 kg

Additional information

Fuel tank capacity	41 l
Fuel delivery	Multi-Point Injection
Number of doors	5
Number of seats	5
Number of axles	2
Engine number	19GY7464