



General information

Make	VOLKSWAGEN
Model	CADDY LIFE TDI
Colour	Blue
Year of manufacture	2010
Top speed	103 mph
Gearbox	5 speed Semi Auto

Engine & fuel consumption

Power	104 BHP
Max. torque	250 Nm at 1.900 rpm
Engine capacity	1.896 cc
Cylinders	4
Fuel type	Diesel
Consumption city	34.5 mpg
Consumption extra urban	49.6 mpg
Consumption combined	42.8 mpg
CO2 emission	177 g/km
CO2 label	I









Internet history

Entry 1

Date	2021-02-06
Pictures	10
Listing price	View report



source: [autoonline.co.uk](https://www.autoonline.co.uk)

**MOT history**

MOT expiry date	2024-10-04
MOT pass rate	86 %
MOT passed	12
Failed MOT tests	2
Total advice items	13
Total items failed	3

MOT #14	2023-10-05 09:49
MOT test number	227413035588
Result	✓ Passed
Next expiry date	2024-10-04
Advice	Parking brake efficiency only just met. Appears braking system requires adjustment or repair

MOT #13	2022-11-14 12:47
MOT test number	569562094811
Result	✓ Passed

MOT #12	2021-11-12 11:25
MOT test number	323446714394
Result	✓ Passed
Advice	Both front tyres badly perished & in poor condition

MOT #11	2020-10-29 17:00
MOT test number	502034550813
Result	✓ Passed

**MOT #10** 2019-10-28 09:11**MOT test number** 860962519723**Result** ✓ Passed**Advice** Slight play in steering column**MOT #9** 2018-11-20 08:29**MOT test number** 328331241133**Result** ✓ Passed**Advice** Steering wheel wheel loose on removable mount**MOT #8** 2018-11-16 13:17**MOT test number** 680069524413**Result** ✗ Failed**Fail** Nearside Windscreen wiper does not clear the windscreen effectively (3.4 (b) (ii))**Advice** Nearside Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))**Advice** Rear Brake pad(s) wearing thin (1.1.13 (a) (ii))**Advice** Steering wheel wheel loose on removable mount**Fail** Offside Windscreen wiper does not clear the windscreen effectively (3.4 (b) (ii))**Advice** Offside Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))**MOT #7** 2018-07-24 07:57**MOT test number** 932512297789**Result** ✓ Passed**Advice** Nearside Rear Tyre slightly damaged/valve stem damaged (5.2.3 (d) (i))**Advice** Slight play in quick release steering wheel**Advice** Offside Rear Tyre slightly damaged/valve stem damaged (5.2.3 (d) (i))

**MOT #6** 2017-05-09 12:21**MOT test number** 570700236710**Result** ✓ Passed**MOT #5** 2016-04-29 08:49**MOT test number** 693000310466**Result** ✓ Passed**MOT #4** 2016-04-28 15:39**MOT test number** 838834108700**Result** ✗ Failed**Fail** Nearside Rear Fuel tank leaking fuel leak from top of fuel tank pipe connection (7.2.3)**MOT #3** 2015-05-14 16:45**MOT test number** 895524435160**Result** ✓ Passed**MOT #2** 2014-04-25 15:57**MOT test number** 775355114181**Result** ✓ Passed**Notice** Vehicle adapted for wheelchair user**MOT #1** 2013-04-24 13:39**MOT test number** 416744513184**Result** ✓ Passed**Notice** Vehicle heavily modified to accomodate disabled driver. Drivers seat, air bag and factory steering wheel removed. Offside sliding door locked in closed position.All hand controls disconnected at time of test allowing factory fit controls to be used.



Tax & MOT check

✓
Taxed
Tax due:
1 October 2024

✓
MOT
Expires:
4 October 2024

Tax status	Valid until 1 October
Days left	155
MOT expiry date	4 October 2024
Full MOT history	See MOT history

Tax calculation

Vehicle class	49
Band	I
Single payment (12 months)	£ 320,00,-
Single six month payment	£ 176,00,-
Total payable by 12 monthly instalments	£ 336,00,-



Damage history

Check the damage history for this VOLKSWAGEN. See if, where and when this VOLKSWAGEN had damage and the car repair costs. We also check if this VOLKSWAGEN was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	

Damage 2

Date	
Category	
Type	



Extra VOLKSWAGEN salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this VOLKSWAGEN in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,999
Auction value	£ 19,999
Average private trade value	£ 19,999

More info >



Owner history

For how long did the current and previous owner(s) have this VOLKSWAGEN? How many owners did this VOLKSWAGEN have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

*****	*****
*****	*****
*****	*****
*****	*****
*****	*****
*****	*****

More info >

Plate changes

See in this check if this VOLKSWAGEN had different number plates.

Number of plates	7
Current registration	 *****
Plate since	2019-06-29
Current registration	 *****
Plate since	2019-06-29

More info >



Finance check

Check if this VOLKSWAGEN is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this VOLKSWAGEN has been settled.

If not, and you buy this VOLKSWAGEN then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this VOLKSWAGEN is financed.

Finance company	REDACTED	REDACTED
Date of agreement	REDACTED	REDACTED
Agreement type	REDACTED	REDACTED
Agreement term	REDACTED	REDACTED
Agreement number	REDACTED	REDACTED
Contact info	REDACTED	REDACTED

More info >



Mileage check

Odometer	In miles
Mileage registrations	16
First mileage registration	2010-06-08
Last registration	2023-10-05
Complete history	See info



Registration #1	2010-06-08	21 mi
Registration #2	2013-04-24	17.895 mi
Registration #3	2014-04-25	26.020 mi
Registration #4	2015-05-14	33.838 mi
Registration #5	2016-04-28	39.921 mi
Registration #6	2016-04-29	39.921 mi
Registration #7	2017-05-09	46.838 mi
Registration #8	2018-07-24	50.025 mi
Registration #9	2019-05-29	55.277 mi
Registration #10	2019-05-29	55.277 mi
Registration #11	2019-05-29	55.277 mi
Registration #12	2019-05-29	55.277 mi
Registration #13	2019-05-29	55.277 mi
Registration #14	2019-05-29	55.277 mi
Registration #15	2019-05-29	55.277 mi
Registration #16	2019-05-29	55.277 mi

More info >



Car features

The VOLKSWAGEN factory car options list is only available in the premium report.

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

View the complete VOLKSWAGEN factory list for this vehicle [here](#).

More info >

Safety ratings

NCAP rating

Video [see crash video](#)



Dimensions & weight

Width	2062 mm
Height	1833 mm
Length	4405 mm
Max. allowed weight	2280 kg

Additional information

Number of seats	5
Number of axles	2
Engine number	BLS C09239