



report date: 2024-03-28

General information

Make	VOLKSWAGEN
Model	CADDY C20 SWB VAN 104TDI
Colour	White
Year of manufacture	-
Top speed	103 mph
0 - 60 mph	13.3 seconds
Gearbox	5 speed Manual

Engine & fuel consumption

Power	103 BHP
Max. torque	250 Nm at 1.900 rpm
Cylinders	4
Fuel type	Diesel



LABEL UNKNOWN

**MOT history**

MOT #14	2021-11-06 11:27
MOT test number	620540111592
Result	✓ Passed
Next expiry date	2022-11-05
Advice	Offside Front Track rod end ball joint has slight play (2.1.3 (b) (i))
Advice	Nearside Front Suspension arm pin or bush worn but not resulting in excessive movement rear bush (5.3.4 (a) (i))
Advice	Nearside Non obligatory mirror damaged
Advice	Rear Anti-roll bar pin or bush worn but not resulting in excessive movement both D bushes (5.3.4 (a) (i))
Advice	Offside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))
Advice	Crack in windscreen
Advice	Offside Steering linkage ball joint has slight play rack end (2.1.3 (b) (i))
Advice	Offside Front Suspension arm pin or bush worn but not resulting in excessive movement rear bush (5.3.4 (a) (i))
Advice	Nearside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))
Advice	Offside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))

MOT #13	2020-10-15 10:52
MOT test number	856265811053
Result	✓ Passed
Minor	Battery insecure but not likely to fall from carrier (4.13 (a) (i))
Advice	Offside Front Inner Track rod end ball joint has slight play (2.1.3 (b) (i))
Minor	Windscreen damaged but not adversely affecting driver's view (3.2 (a) (i))

MOT #12	2019-10-28 11:34
MOT test number	461381527199
Result	✓ Passed

**MOT #11** 2018-10-11 14:58**MOT test number** 214605974194**Result** ✓ Passed**MOT #10** 2017-02-17 08:49**MOT test number** 673895496494**Result** ✓ Passed**Advice** O/s/f door pins have slight play**Advice** Slight front brake imbalance/fluctuation 15%**Advice** O/s/f inner rack has slight play**MOT #9** 2016-01-27 15:26**MOT test number** 147649224081**Result** ✓ Passed**Advice** O/s/f tyre slightly bold on edges**MOT #8** 2015-02-05 13:32**MOT test number** 439666935067**Result** ✓ Passed**MOT #7** 2015-02-04 11:25**MOT test number** 117045635000**Result** ✗ Failed**Fail** Offside Front Headlamp not working on dipped beam (1.7.5a)**Fail** Front registration plate delaminated (6.3.1d)**Fail** Nearside Front Headlamp aim too high (1.8)**Fail** Exhaust has a major leak of exhaust gases (7.1.2)

**MOT #6**

2014-02-28 14:09

MOT test number

447949654099

Result

✓ Passed

Notice Osr tyre perished on tread**Notice** Nsr tyre perished on side wall**MOT #5**

2014-02-04 16:56

MOT test number

289295734076

Result

✗ Failed

Fail Offside Rear Direction indicator incorrect colour (1.4.A.2f)**Fail** Offside Front Windscreen wiper does not clear the windscreen effectively (8.2.2)**Notice** Osr tyre perished on tread**Fail** Nearside Rear Anti-roll bar rubber bush deteriorated resulting in excessive movement (2.4.G.2)**Fail** Nearside Front Headlamp aim too high (1.8)**Fail** Nearside Rear Front suspension has excessive movement at a wishbone pin or bush (2.5.A.1c)**Fail** Nearside Rear Direction indicator incorrect colour (1.4.A.2f)**Fail** Nearside Front Windscreen wiper does not clear the windscreen effectively (8.2.2)**Notice** Nsr tyre perished on side wall**Fail** Nearside Front Front constant velocity joint gaiter damaged to the extent that it no longer prevents the ingress of dirt etc (2.5.C.1a)**Fail** Offside Rear Anti-roll bar rubber bush deteriorated resulting in excessive movement (2.4.G.2)**Fail** Offside Front Headlamp aim too high (1.8)**Fail** Offside Rear Front suspension has excessive movement at a wishbone pin or bush (2.5.A.1c)

**MOT #4** 2012-11-26 13:51**MOT test number** 719151332307**Result** ✓ Passed

- Advice** Offside Front Tyre worn close to the legal limit (4.1.E.1)
- Advice** Nearside Front Tyre worn close to the legal limit (4.1.E.1)
- Advice** Windscreen has damage to an area less than a 40mm circle outside zone 'A' (8.3.1d)
- Notice** Front brake disc s corroded

MOT #3 2011-12-19 09:20**MOT test number** 389243251362**Result** ✓ Passed**MOT #2** 2010-11-23 09:40**MOT test number** 232337820376**Result** ✓ Passed

- Notice** Egr cooler blowing slightly

MOT #1 2010-01-05 09:47**MOT test number** 813335900026**Result** ✓ Passed



Damage history

Check the damage history for this VOLKSWAGEN. See if, where and when this VOLKSWAGEN had damage and the car repair costs. We also check if this VOLKSWAGEN was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	

Damage 2

Date	
Category	
Type	



Extra VOLKSWAGEN salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this VOLKSWAGEN in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,999
Auction value	£ 19,999
Average private trade value	£ 19,999

More info >



Owner history

For how long did the current and previous owner(s) have this VOLKSWAGEN? How many owners did this VOLKSWAGEN have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration

More info >

Plate changes

See in this check if this VOLKSWAGEN had different number plates.

Number of plates	1
Current registration	 BT56XEW
Plate since	2019-06-29
Current registration	 BT56XEW
Plate since	2019-06-29

More info >



Finance check

Check if this VOLKSWAGEN is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this VOLKSWAGEN has been settled.

If not, and you buy this VOLKSWAGEN then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this VOLKSWAGEN is financed.

Finance company	REDACTED	REDACTED
Date of agreement	REDACTED	REDACTED
Agreement type	REDACTED	REDACTED
Agreement term	REDACTED	REDACTED
Agreement number	REDACTED	REDACTED
Contact info	REDACTED	REDACTED

More info >



Mileage check

Odometer	In miles
Mileage registrations	15
First mileage registration	2007-01-16
Last registration	2021-11-06
Complete history	See info



Registration #1	2007-01-16	6 mi
Registration #2	2010-01-05	58.007 mi
Registration #3	2010-11-23	76.391 mi
Registration #4	2011-12-19	102.098 mi
Registration #5	2012-11-26	123.984 mi
Registration #6	2014-02-04	138.555 mi
Registration #7	2014-02-28	138.568 mi
Registration #8	2015-02-04	155.452 mi
Registration #9	2015-05-20	155.557 mi
Registration #10	2015-05-20	155.557 mi
Registration #11	2015-05-20	155.557 mi
Registration #12	2015-05-20	155.557 mi
Registration #13	2015-05-20	155.557 mi
Registration #14	2015-05-20	155.557 mi
Registration #15	2015-05-20	155.557 mi

More info >



Car features

The VOLKSWAGEN factory car options list is only available in the premium report.

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

View the complete VOLKSWAGEN factory list for this vehicle [here](#).

More info >

Safety ratings

NCAP rating

Video [see crash video](#)



Dimensions & weight

Width	2062 mm
Length	4405 mm

Additional information

Fuel tank capacity	55 l
Fuel delivery	Direct Injection
Number of doors	3
Number of seats	3
Engine number	BLS 258417