





General information

Make	FIAT
Model	PUNTO EASY
Colour	Grey
Year of manufacture	2013
Top speed	103 mph
0 - 60 mph	13.2 seconds
Gearbox	5 speed Manual

Engine & fuel consumption

Power	77 BHP
Max. torque	115 Nm at 3.250 rpm
Engine capacity	1.368 cc
Cylinders	4
Fuel type	Petrol
Consumption city	42.2 mpg
Consumption extra urban	61.4 mpg
Consumption combined	52.3 mpg
CO2 emission	132 g/km
CO2 label	E





Internet history	
Entry 1	
Date	2021-09-03
Pictures	0
Listing price	View report

source: autotrader.co.uk



MOT history

MOT expiry date	2024-09-24
MOT pass rate	77 %
MOT passed	10
Failed MOT tests	3
Total advice items	27
Total items failed	0

MOT #13	2023-09-25 13:22
MOT test number	938930322267
Result	✓ Passed
Next expiry date	2024-09-24
Advice Nearside Front Shock absorbers has light misting of oil (5.3.2 (b))	
Advice Front Oil leak, but not excessive (8.4.1 (a) (i))	

MOT #12	2023-09-25 11:38
MOT test number	771282424676
Result	🗙 Failed
DANGEROUS Offside Front Tyre tread depth below requirements of 1.6mm (5.2.3 (e))	
MAJOR Nearside Rear Position lamp not working (4.2.1 (a) (ii))	
Advice Nearside Front Shock absorbers has light misting of oil (5.3.2 (b))	
DANGEROUS Nearside Front Tyre tread depth below requirements of 1.6mm (5.2.3 (e))	
Advice Front Oil leak, but not excessive (8.4.1 (a) (i))	

MOT #11	2022-09-14 13:18
MOT test number	403395222330
Result	✓ Passed
Advice Nearside Front Shock absorbers has light misting of oil (5.3.2 (b))	





MOT #10		2021-09-20 08:22
MOT test	number	360540451745
Result		✓ Passed
Advice	Nearside Front Shock absorbers has light misting of oil (5.3.2 (b))	
MOT #9		2020-09-10 12:55
MOT test	number	465234770086
Result		✓ Passed
Advice	Offside Front Nail in tyre	
Advice	Nearside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))	
Advice Nearside Front Shock absorbers light misting of oil or has limited damping effect (5.3.2 (b))		
Advice	N/s/r and o/s/r shock absorbers corroded	
Advice	Offside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))	
MOT #8		2019-09-18 07:22

MOT #8	2019-09-18 07:22
MOT test number	664499105282
Result	✓ Passed

MOT #7	2019-09-06 09:14
MOT test number	476244014844
Result	✓ Passed



SK13PBV	,
report date: 2024-03-29	9

MOT #6		2019-09-04 14:39
MOT test	number	897177432422
Result		🗙 Failed
Advice	Oil leak, but not excessive (8.4.1 (a) (i))	
Advice	Exhaust has part of system slightly deteriorated	
Advice	Front Brake pad(s) wearing thin (1.1.13 (a) (ii))	
MAJOR	Nearside Rear Position lamp not working (4.2.1 (a) (ii))	

MOT #5	2019-03-29 09:26
MOT test number	826026547862
Result	✓ Passed
Advice Sump pan corroded	
Advice Nearside Front Brake pad(s) wearing thin (1.1.13 (a) (ii))	

MOT #4		2019-03-26 09:50
MOT test	number	528650078423
Result		🗙 Failed
MAJOR	Offside Front Coil spring fractured or broken (5.3.1 (b) (i))	
MAJOR	Nearside Front Coil spring fractured or broken (5.3.1 (b) (i))	
Advice	Sump pan corroded	
Advice	Nearside Front Brake pad(s) wearing thin (1.1.13 (a) (ii))	
MAJOR	Offside Front Windscreen wiper does not clear the windscreen effectively (3.4 (b)	(ii))





MOT #3		2018-03-09 14:46
MOT test	number	835495392839
Result		✓ Passed
Advice Advice	Offside wiper blade slightly smearing Nearside Front Tyre worn close to the legal limit (4.1.E.1)	
MOT #2		2017-03-27 15:09
MOT test	number	161391440546
Result		✓ Passed

MOT #1	2016-03-05 09:56
MOT test number	556996319135
Result	✓ Passed



Tax & MOT check

✓ Taxed	✓ мот
Tax due: 1 March 2025	Expires: 24 September 2024
Tax status	Valid until 1 March
Days left	306
MOT expiry date	24 September 2024
Full MOT history	See MOT history

Tax calculation

Vehicle class	48
Band	E
Single payment (12 months)	£ 180,00,-
Single six month payment	£ 99,00,-
Total payable by 12 monthly instalments	£ 189,00,-





Damage history

Check the damage history for this FIAT. See if, where and when this FIAT had damage and the car repair costs. We also check if this FIAT was scrapped. Download the premium report <u>here</u> for the results.

Damage 1	
Date	
Category	Lamp
Туре	
Damage 2	AMPLE
Dumage 2	E E E E
Date	J.
Category	amer
Туре	

Extra FIAT salvage check

If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report <u>here</u> for more information.





Vehicle valuation

What is this car worth? See the vehicle value of this FIAT in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	4 10.000
Auction value	4 10.000
Average private trade value	4





Owner history

For how long did the current and previous owner(s) have this FIAT? How many owners did this FIAT have? Check it in the premium report and see all owner registrations. Download the full report <u>here</u>.

xxxxxxxx	

	More info >
Plate changes	
See in this check if this FIAT had different number plates.	
Number of plates	,
Current registration	
Plate since	
Carrent registration	
Plate since	
	More info >





Finance check

Check if this FIAT is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this FIAT has been settled.

If not, and you buy this FIAT then you could lose the money and the car you paid for.

Download the premium report <u>here</u> and check if this FIAT is financed.


Finance company	
Date of agreement	
Agreement type	
Agreement term	
Agreement number	
Contact info	





Mileage check

Odometer	In miles
Mileage registrations	15
First mileage registration	2013-03-29
Last registration	2023-09-25
Complete history	See info



Registration #1	2013-03-29	9 mi
Registration #2	2016-03-05	16.503 mi
Registration #3	2017-03-27	22.821 mi
Registration #4	2018-03-09	27.447 mi
Registration #5	2019-03-26	33.302 mi
Registration #6	2019-03-29	33.330 mi
Registration #7	2019-09-04	34.970 mi
Registration #8	2019-09-06	34.970 mi
Registration #9		11.777 mi
Registration #10		11.777 mi
Registration #11		11.777 mi
Registration #12		11.777 esi
Registration #13		11.777 mi
Registration #14		11.777 esi
Registration #15		11.777 mi





Car features

S0225	Air conditioning
S0295	
S0482	
\$0501	
\$0566	
S0567	
S0569	

Safety ratings

NCAP rating

Video

**** see crash video



Dimensions & weight	
Width	1687 mm
Height	1490 mm
Length	4065 mm
Wheel base	2510 mm
Kerb weight	1025 kg
Max. allowed weight	1585 kg
Additional information	
Fuel tank capacity	45 I
Fuel delivery	Multi-Point Injection
Number of doors	3
Number of seats CarCheck.co.uk	5 page 13/13

Number of axles	2
Engine number	0272619