





report date: 2024-03-29

#### General information

Make	FIAT
Model	PANDA DYNAMIC
Colour	Black
Year of manufacture	2008
Top speed	96 mph
0 - 60 mph	14.0 seconds
Gearbox	5 speed Manual

### Engine & fuel consumption

Power	60 BHP
Max. torque	102 Nm at 2.500 rpm
Engine capacity	1.242 cc
Cylinders	4
Fuel type	Petrol
Consumption city	39.8 mpg
Consumption extra urban	58.9 mpg
Consumption combined	50.4 mpg
CO2 emission	133 g/km
CO2 label	E



CarCheck.co.uk page 1/13



report date: 2024-03-29

## Internet history

#### Entry 1

Date 2021-01-29

Pictures 3

Listing price <u>View report</u>







source: autoonline.co.uk

CarCheck.co.uk page 2/13



report date: 2024-03-29

B 4	$\sim$ $-$		
10.71	$^{\prime}$	hic	torv.
101	C I	1115	IUI V
	•		tory

MOT expiry date	2024-07-12
MOT pass rate	87 %
MOT passed	13
Failed MOT tests	2
Total advice items	23
Total items failed	3

MOT #15	2023-07-13 14:38
MOT test number	469397428857
Result	<b>✓</b> Passed
Next expiry date	2024-07-12

MOT #14	2023-07-05 10:05
MOT test number	996581424574
Result	<b>X</b> Failed
Advice Rear Direction indicator slightly discoloured (4.4.3 (a))	
Advice Rear Service brake binding but not excessively (1.2.1 (f))	
Advice Front Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))	
Advice Hand brake travel	
Fail Offside Front Position lamp not working (4.2.1 (a) (ii))	
Fail Nearside Headlamp aim too low (4.1.2 (a))	

CarCheck.co.uk page 3/13



report date: 2024-03-29

MOT #13

MOT test number

Sesult

Advice Nearside Rear Service brake binding but not excessively (1.2.1 (f))

Advice Rear Axle corroding

Advice Rear Direction indicator slightly discoloured BOTH SIDES (4.4.3 (a))

Advice Front Tyre slightly damaged/cracking or perishing BOTH SIDES, cracking (5.2.3 (d) (ii))

MOT #12

MOT test number

923001657771

Result

Advice Front Tyre slightly damaged/cracking or perishing BOTH SIDES , starting to crack (5.2.3 (d) (ii))

MOT test number

Result

Advice

Nearside Rear Brake slightly binding when rotated by hand

Advice

Front Tyre slightly damaged/cracking or perishing BOTH SIDES , cracking (5.2.3 (d) (ii))

Advice

Nearside Front Shock absorber has slight movement at the upper attachment

MOT #10	2020-01-13 15:04
MOT test number	357005309785
Result	✓ Passed

CarCheck.co.uk page 4/13



report date: 2024-03-29

MOT test number

Result

Advice Nearside Front Drive shaft seal slight seepage of oil.

Advice Nearside Headlight adjusted to maximum but aim is on lowest height limit.

Advice Coil spring corroded Both rear. (5.3.1 (b) (i))

MOT #8

MOT test number

Result

Advice Tyre worn close to the legal limit Both rear. (4.1.E.1)

Advice Coil spring corroded Both rear. (2.4.C.1b)

MOT #7

MOT test number

Fesult

Advice Nearside Rear Tyre worn close to the legal limit (4.1.E.1)

MOT #6

MOT test number

Result

Advice Rear tyres wearing on the inner edges

2016-01-05 12:53

351993468477

✓ Passed

MOT #5

MOT test number

786514544374

Result

Notice Nearside rear brake slight bind

CarCheck.co.uk page 5/13



report date: 2024-03-29

MOT #4

MOT test number

Result

MOT #3

MOT test number

2013-12-23 10:49

Passed

MOT #3

2013-01-07 12:20

MOT test number

997637903085

Result

Notice

Under-trays fitted obscuring some underside components

MOT #2

MOT test number

507904002072

Result

✓ Passed

MOT test number

Result

Notice Offside rear lamp cracked

Advice Front registration plate deteriorated but not likely to be misread (6.3.1d)

Fail Offside Rear Tyre tread depth below requirements of 1.6mm (4.1.E.1)

CarCheck.co.uk page 6/13



report date: 2024-03-29

#### Tax & MOT check



Tax status	Valid until 1 December
Days left	215
MOT expiry date	12 July 2024
Full MOT history	See MOT history

#### Tax calculation

Vehicle class	48
Band	E
Single payment (12 months)	£ 180,00,-
Single six month payment	£ 99,00,-
Total payable by 12 monthly instalments	£ 189,00,-

CarCheck.co.uk page 7/13



report date: 2024-03-29

#### Damage history

Check the damage history for this FIAT. See if, where and when this FIAT had damage and the car repair costs. We also check if this FIAT was scrapped. Download the premium report <u>here</u> for the results.

Damage 1
Date
Category
Type
Damage 2
Date
Category
Type



#### Extra FIAT salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report <u>here</u> for more information.

More info >

CarCheck.co.uk page 8/13



report date: 2024-03-29

#### Vehicle valuation

What is this car worth? See the vehicle value of this FIAT in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

**Trade retail value** 

**Auction value** 

Average private trade value

More info >

CarCheck.co.uk page 9/13



report date: 2024-03-29

### Owner history

For how long did the current and previous owner(s) have this FIAT? How many owners die Check it in the premium report and see all owner registrations. Download the full report is	
***************************************	
2000000	
***************************************	
	More info >
Plate changes	
See in this check if this FIAT had different number plates.	
Number of plates	
Executive and American	NE
Cornect region acon	OK ON THE STATE OF
Plate since	
Current registration	IIK SIE
Plate since	
	More info >
	More into >

CarCheck.co.uk page 10/13



report date: 2024-03-29

#### Finance check

Check if this FIAT is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this FIAT has been settled.

If not, and you buy this FIAT then you could lose the money and the car you paid for.

Download the premium report <u>here</u> and check if this FIAT is financed.

Finance company	
Date of agreement	
Agreement type	
Agreement term	
Agreement number	
Contact info	

Contact info

More info >


CarCheck.co.uk page 11/13



report date: 2024-03-29

## Mileage check

Odometer	In miles
Mileage registrations	17
First mileage registration	2008-10-02
Last registration	2023-07-13
Complete history	See info



Registration #1	2008-10-02	10 mi
Registration #2	2011-09-19	51.933 mi
Registration #3	2012-01-04	52.835 mi
Registration #4	2013-01-07	54.188 mi
Registration #5	2013-12-23	55.354 mi
Registration #6	2014-12-10	56.433 mi
Registration #7	2016-01-05	57.629 mi
Registration #8	2017-01-04	58.619 mi
Registration #9	2018-01-03	59.310 mi
Registration #10		11.777 es
Registration #11		11.777 es
Registration #12		11.777 es
Registration #13		11.777 es
Registration #14		11.777 es
Registration #15		91.777 es
Registration #16		11.777 es
Registration #17		11.777 es

More info >

CarCheck.co.uk page 12/13



report date: 2024-03-29

Car features

S0225	Air conditioning
S0295	
50482	
50501	
S0566	
50567	
S0569	

## Safety ratings

NCAP rating	***
Video	see crash video



## Dimensions & weight

Width	1578 mm
Height	1540 mm
Length	3538 mm
Wheel base	2299 mm
Kerb weight	860 kg
Max. allowed weight	1305 kg

## Additional information

Fuel tank capacity	35 I
Fuel delivery	Multi-Point Injection
Number of doors	5
Number of seats CarCheck.co.uk	4 page 13/13