



RENAULT

HV68SXF

report date: 2024-03-28

General information

| | |
|---------------------|-----------------|
| Make | RENAULT |
| Model | CAPTUR PLAY TCE |
| Colour | Grey |
| Year of manufacture | 2018 |
| Top speed | 106 mph |
| 0 - 100 km/h | 13.0 seconds |
| 0 - 60 mph | 13.1 seconds |
| Gearbox | 5 speed Manual |

Engine & fuel consumption

| | |
|-------------------------|------------------------|
| Power | 66 kW / 90 HP / 89 BHP |
| Max. torque | 140 Nm at 2.250 rpm |
| Engine capacity | 898 cc |
| Cylinders | 3 |
| Fuel type | Petrol |
| Consumption city | 44.8 mpg |
| Consumption extra urban | 58.8 mpg |
| Consumption combined | 2.8 mpg |
| CO2 emission | 123 g/km |
| CO2 label | D |






Internet history

Entry 1

| | |
|---------------|-----------------------------|
| Date | 2022-03-11 |
| Pictures | 46 |
| Listing price | View report |



source: cargurus.co.uk



MOT history

| | |
|--------------------|------------|
| MOT expiry date | 2024-10-19 |
| MOT pass rate | 75 % |
| MOT passed | 3 |
| Failed MOT tests | 1 |
| Total advice items | 6 |
| Total items failed | 0 |

| | |
|------------------|---|
| MOT #4 | 2023-10-10 14:54 |
| MOT test number | 614661440046 |
| Result | ✓ Passed |
| Next expiry date | 2024-10-19 |
| Advice | Tyre slightly damaged/cracking or perishing nearside and offside rear tyres perished on sidewall (5.2.3 (d) (ii)) |

| | |
|-----------------|--|
| MOT #3 | 2022-10-20 13:36 |
| MOT test number | 452973831837 |
| Result | ✓ Passed |
| Advice | Nearside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e)) |
| Advice | Offside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e)) |

| | |
|-----------------|------------------|
| MOT #2 | 2021-10-13 08:15 |
| MOT test number | 721302360044 |
| Result | ✓ Passed |



| | |
|-----------------|---|
| MOT #1 | 2021-10-07 10:50 |
| MOT test number | 225966396961 |
| Result | ✗ Failed |
| Minor | Nearside Windscreen wiper blade defective (3.4 (b) (i)) |
| MAJOR | Reversing lamp inoperative (4.6.1 (a)) |
| Minor | Offside Windscreen wiper blade defective (3.4 (b) (i)) |



Tax & MOT check

✓
Taxed
Tax due:
1 March 2025

✓
MOT
Expires:
19 October 2024

| | |
|-------------------------|---------------------------------|
| Tax status | Valid until 1 March |
| Days left | 306 |
| MOT expiry date | 19 October 2024 |
| Full MOT history | See MOT history |

Tax calculation

| | |
|--------------------------------------|------------|
| Vehicle class | 48 |
| Band | G |
| First licence fee (12 months) | £ 210,00,- |
| Standard rate (12 months) | £ 180,00,- |
| Standard rate (6 months) | £ 99,00,- |
| Premium rate (12 months) | £ 570,00,- |
| Premium rate (6 months) | £ 313,50,- |



Damage history

Check the damage history for this RENAULT. See if, where and when this RENAULT had damage and the car repair costs. We also check if this RENAULT was scrapped. Download the premium report [here](#) for the results.

Damage 1

| | |
|----------|--|
| Date | |
| Category | |
| Type | |

Damage 2

| | |
|----------|--|
| Date | |
| Category | |
| Type | |



Extra RENAULT salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this RENAULT in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

| | |
|-----------------------------|----------|
| Trade retail value | £ 19,299 |
| Auction value | £ 19,299 |
| Average private trade value | £ 19,299 |

More info >



Owner history

For how long did the current and previous owner(s) have this RENAULT? How many owners did this RENAULT have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

| | |
|-------|-------|
| Owner | Since |
| Owner | Since |
| Owner | Since |
| Owner | Since |
| Owner | Since |
| Owner | Since |
| Owner | Since |

More info >

Plate changes

See in this check if this RENAULT had different number plates.

| | |
|----------------------|-----------------|
| Number of plates | 1 |
| Current registration | REDACTED |
| Plate since | 2024-03-28 |
| Current registration | REDACTED |
| Plate since | 2024-03-28 |

More info >



Finance check

Check if this RENAULT is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this RENAULT has been settled.

If not, and you buy this RENAULT then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this RENAULT is financed.

| | | |
|-------------------|----------|----------|
| Finance company | REDACTED | REDACTED |
| Date of agreement | REDACTED | REDACTED |
| Agreement type | REDACTED | REDACTED |
| Agreement term | REDACTED | REDACTED |
| Agreement number | REDACTED | REDACTED |
| Contact info | REDACTED | REDACTED |

More info >



Mileage check

| | |
|----------------------------|--------------------------|
| Odometer | In miles |
| Mileage registrations | 6 |
| First mileage registration | 2018-10-20 |
| Last registration | 2023-10-10 |
| Complete history | See info |



| | | |
|-----------------|------------|-----------|
| Registration #1 | 2018-10-20 | 23 mi |
| Registration #2 | 2021-10-07 | 28.118 mi |
| Registration #3 | 2021-10-13 | 28.215 mi |
| Registration #4 | 2023-10-10 | 28.215 mi |
| Registration #5 | 2023-10-10 | 28.215 mi |
| Registration #6 | 2023-10-10 | 28.215 mi |

More info >



Car features

The RENAULT factory car options list is only available in the premium report.

| | |
|-------|------------------|
| S0225 | Air conditioning |
| S0295 | |
| S0482 | |
| S0501 | |
| S0566 | |
| S0567 | |
| S0569 | |

View the complete RENAULT factory list for this vehicle [here](#).

More info >

Safety ratings

| | |
|----------------|---------------------------------|
| NCAP rating | ★★★★★ |
| Adult | 88% |
| Children | 79% |
| Pedestrian | 61% |
| Safety systems | 81% |
| Overall rating | 80% |
| Video | see crash video |



Dimensions & weight

| | |
|---------------------|---------|
| Width | 1778 mm |
| Height | 1566 mm |
| Length | 4122 mm |
| Wheel base | 2606 mm |
| Kerb weight | 1173 kg |
| Max. allowed weight | 1659 kg |

Additional information

| | |
|--------------------|-----------------------|
| Fuel tank capacity | 45 l |
| Fuel delivery | Multi-Point Injection |
| Number of doors | 5 |
| Number of seats | 5 |

| | |
|------------------------|---------|
| Number of axles | 2 |
| Engine number | D577109 |