



AJ58ERZ

report date: 2024-03-29

General information

Make	VOLVO
Model	C30
Colour	Silver
Year of manufacture	2008
Gearbox	-

Engine & fuel consumption

Engine capacity	1.798 cc
Fuel type	Petrol
CO2 emission	174 g/km
CO2 label	H





Internet history

Entry 1

Date	2021-09-22
Pictures	13
Listing price	View report



source: [autotrader.co.uk](https://www.autotrader.co.uk)



MOT history

MOT expiry date	2024-06-22
MOT pass rate	63 %
MOT passed	12
Failed MOT tests	7
Total advice items	12
Total items failed	13

MOT #19	2023-06-23 11:03
MOT test number	436207200772
Result	✓ Passed
Next expiry date	2024-06-22
Advice	Offside Rear Direction indicator slightly discoloured (4.4.3 (a))
Advice	Nearside Rear Direction indicator slightly discoloured (4.4.3 (a))

MOT #18	2022-09-03 10:37
MOT test number	571140988678
Result	✗ Failed
Minor	Windscreen damaged but not adversely affecting driver's view (3.2 (a) (i))
Advice	Offside Rear Direction indicator slightly discoloured (4.4.3 (a))
Fail	Offside Front Tyre tread depth below requirements of 1.6mm (5.2.3 (e))
Fail	Offside Front Lower Suspension arm pin or bush excessively worn (5.3.4 (a) (i))
Advice	Nearside Rear Direction indicator slightly discoloured (4.4.3 (a))
Fail	Nearside Front Tyre tread depth below requirements of 1.6mm (5.2.3 (e))
Fail	Nearside Front Lower Suspension arm pin or bush excessively worn (5.3.4 (a) (i))

**MOT #17** 2021-07-23 13:07**MOT test number** 246057539991**Result** ✓ Passed**MOT #16** 2021-07-23 09:31**MOT test number** 469170049723**Result** ✗ Failed**Advice** Exhaust emits blue smoke during acceleration (8.2.1.2 (g))**Fail** Exhaust carbon monoxide content after 2nd fast idle exceeds manufacturer's specified limits (8.2.1.2 (a))**MOT #15** 2020-08-04 15:00**MOT test number** 309507683539**Result** ✓ Passed**MOT #14** 2020-08-04 15:00**MOT test number** 137372079784**Result** ✗ Failed**Pass with rectification** Nearside Front Brake disc significantly and obviously worn (1.1.14 (a) (i))**Pass with rectification** Offside Front Brake disc significantly and obviously worn (1.1.14 (a) (i))**MOT #13** 2019-08-02 10:25**MOT test number** 726613425675**Result** ✓ Passed**Minor** Registration plate lamp inoperative in the case of multiple lamps or light sources (4.7.1 (b) (i))

**MOT #12** 2019-08-02 10:25**MOT test number** 155193938613**Result** ✗ Failed**Pass with rectification** Nearside Headlamp aim projected beam image is obviously incorrect (4.1.2 (c))**Minor** Registration plate lamp inoperative in the case of multiple lamps or light sources (4.7.1 (b) (i))**MOT #11** 2018-07-20 13:20**MOT test number** 751223638098**Result** ✓ Passed**MOT #10** 2017-07-21 10:47**MOT test number** 900251073959**Result** ✓ Passed**MOT #9** 2017-07-21 10:46**MOT test number** 848619863124**Result** ✗ Failed**Pass with rectification** Nearside Front position lamp(s) not working (1.1.A.3b)**MOT #8** 2016-07-30 08:29**MOT test number** 366223494467**Result** ✓ Passed**MOT #7** 2015-08-19 14:17**MOT test number** 638874271356**Result** ✓ Passed

**MOT #6** 2015-08-18 00:00**MOT test number** 931053904138**Result** ✗ Failed**Fail** Offside Headlamp aim beam image obviously incorrect (1.8.A.1b)**Fail** Nearside Headlamp aim too high (1.8)**MOT #5** 2014-08-15 10:28**MOT test number** 836237824285**Result** ✓ Passed**MOT #4** 2013-09-19 12:40**MOT test number** 266792563293**Result** ✓ Passed**Advice** Offside Front Tyre worn close to the legal limit (4.1.E.1)**Advice** Nearside Front Tyre worn close to the legal limit (4.1.E.1)**MOT #3** 2013-09-19 09:30**MOT test number** 977232663232**Result** ✗ Failed**Fail** Offside Rear Tyre not fitted in accordance with side wall instructions (4.1.D.1f)**Advice** Offside Front Tyre worn close to the legal limit (4.1.E.1)**Fail** Nearside Rear Tyre tread depth below requirements of 1.6mm (4.1.E.1)**Advice** Nearside Front Tyre worn close to the legal limit (4.1.E.1)**MOT #2** 2012-10-01 11:04**MOT test number** 309925372464**Result** ✓ Passed



MOT #1	2011-09-30 09:51
MOT test number	629883671224
Result	✓ Passed



Tax & MOT check

✓
Taxed

Tax due:
1 July 2024

✓
MOT

Expires:
22 June 2024

Tax status	Valid until 1 July
Days left	63
MOT expiry date	22 June 2024
Full MOT history	See MOT history

Tax calculation

Vehicle class	48
Band	H
Single payment (12 months)	£ 290,00,-
Single six month payment	£ 159,50,-
Total payable by 12 monthly instalments	£ 304,50,-



Damage history

Check the damage history for this VOLVO. See if, where and when this VOLVO had damage and the car repair costs. We also check if this VOLVO was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	

Damage 2

Date	
Category	
Type	



Extra VOLVO salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this VOLVO in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,999
Auction value	£ 19,999
Average private trade value	£ 19,999

More info >



Owner history

For how long did the current and previous owner(s) have this VOLVO? How many owners did this VOLVO have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

*****	*****
*****	*****
*****	*****
*****	*****
*****	*****
*****	*****
*****	*****

More info >

Plate changes

See in this check if this VOLVO had different number plates.

Number of plates	1
Current registration	*****
Plate since	2019-09-29
Current registration	*****
Plate since	2019-09-29

More info >



Finance check

Check if this VOLVO is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this VOLVO has been settled.

If not, and you buy this VOLVO then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this VOLVO is financed.

Finance company	XXXXXXXXXX	XXXX
Date of agreement	XXXXXXXXXX	XXXX
Agreement type	XXXXXXXXXX	XXXX
Agreement term	XXXXXXXXXX	XXXX
Agreement number	XXXXXXXXXX	XXXX
Contact info	XXXXXXXXXX	XXXX

More info >



Mileage check

Odometer	In miles
Mileage registrations	21
First mileage registration	2008-09-30
Last registration	2023-06-23
Complete history	See info



Registration #1	2008-09-30	8 mi
Registration #2	2011-09-30	23.677 mi
Registration #3	2012-10-01	32.704 mi
Registration #4	2013-09-19	45.542 mi
Registration #5	2013-09-19	45.542 mi
Registration #6	2014-08-15	56.731 mi
Registration #7	2015-08-18	63.848 mi
Registration #8	2015-08-19	63.848 mi
Registration #9	2016-07-30	71.824 mi
Registration #10	2017-07-21	80.323 mi
Registration #11	2017-07-21	80.323 mi
Registration #12	2018-06-20	80.323 mi
Registration #13	2018-06-20	80.323 mi
Registration #14	2018-06-20	80.323 mi
Registration #15	2018-06-20	80.323 mi
Registration #16	2018-06-20	80.323 mi
Registration #17	2018-06-20	80.323 mi
Registration #18	2018-06-20	80.323 mi
Registration #19	2018-06-20	80.323 mi
Registration #20	2018-06-20	80.323 mi
Registration #21	2018-06-20	80.323 mi

More info >



Car features

The VOLVO factory car options list is only available in the premium report.

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

View the complete VOLVO factory list for this vehicle [here](#).

More info >

Safety ratings

NCAP rating



Video

[see crash video](#)



Additional information

Number of seats

4

Engine number

143891