



HONDA



W448RRU

report date: 2024-03-28

General information

Make	HONDA
Model	INTEGRA 16V
Colour	Red
Year of manufacture	2000
Top speed	145 mph
0 - 60 mph	6.7 seconds
Gearbox	5 speed Manual

Engine & fuel consumption

Power	188 BHP
Max. torque	178 Nm at 7.300 rpm
Engine capacity	1.797 cc
Cylinders	4
Fuel type	Petrol
Consumption city	23.3 mpg
Consumption extra urban	40.9 mpg
Consumption combined	32.1 mpg



LABEL UNKNOWN



Internet history

Entry 2

Date	2021-06-29
Pictures	40
Listing price	View report



source: cargurus.co.uk

Entry 1

Date	2021-06-28
Pictures	1
Listing price	View report



source: autotrader.co.uk



MOT history

MOT expiry date	2022-07-14
MOT pass rate	84 %
MOT passed	16
Failed MOT tests	3
Total advice items	21
Total items failed	3

MOT #19	2021-07-15 16:34
MOT test number	618459163285
Result	✓ Passed
Next expiry date	2022-07-14

MOT #18	2020-08-24 15:02
MOT test number	182319581754
Result	✓ Passed

**MOT #17**

2020-08-05 11:42

MOT test number

299632863460

Result

✗ Failed

Advice Offside Front Shock absorbers has a slightly worn bush bottom strut bush (5.3.2 (c))**Advice** Exhaust has a minor leak of exhaust gases front pipe to centre section flange (6.1.2 (a))**MAJOR** Exhaust Lambda reading after 2nd fast idle outside specified limits (8.2.1.2 (c))**Minor** Battery insecure but not likely to fall from carrier (4.13 (a) (i))**Advice** Nearside Front Shock absorbers has a slightly worn bush bottom strut bush (5.3.2 (c))**Advice** Exhaust noisy (8.1.1 (a))**Advice** Nearside Rear Brake pad(s) wearing thin (1.1.13 (a) (ii))**MAJOR** Exhaust catalytic converter missing where one was fitted as standard (8.2.1.1 (a))**MAJOR** Exhaust Lambda reading after 2nd fast idle outside specified limits (8.2.1.2 (c))**MOT #16**

2019-08-07 13:00

MOT test number

427967217052

Result

✓ Passed

MOT #15

2018-05-23 09:26

MOT test number

604511128181

Result

✓ Passed

Advice Rear Brakes imbalanced requirements only just met. It would appear that the braking system requires adjustment or repair. (1.2.1 (b) (i))**Advice** Nearside Rear Suspension arm pin or bush worn but not resulting in excessive movement Trailing arm bush (5.3.4 (a) (i))**Advice** Offside Rear Anti-roll bar linkage pin or bush worn but not resulting in excessive movement (5.3.4 (a) (i))**Advice** Offside Rear Suspension arm pin or bush worn but not resulting in excessive movement Trailing arm bush (5.3.4 (a) (i))



MOT #14	2017-03-09 14:46
----------------	------------------

MOT test number	464953147014
------------------------	--------------

Result	✓ Passed
---------------	----------

MOT #13	2016-02-26 16:41
----------------	------------------

MOT test number	935926698650
------------------------	--------------

Result	✓ Passed
---------------	----------

MOT #12	2014-11-09 15:09
----------------	------------------

MOT test number	598223414396
------------------------	--------------

Result	✓ Passed
---------------	----------

Notice	Rust in places
---------------	----------------

Advice	Rear Exhaust has a minor leak of exhaust gases (7.1.2)
---------------	--

Advice	Brake pipe slightly corroded (3.6.B.2c)
---------------	---

MOT #11	2013-11-20 11:09
----------------	------------------

MOT test number	326974323331
------------------------	--------------

Result	✓ Passed
---------------	----------

MOT #10	2012-11-13 11:47
----------------	------------------

MOT test number	936468212399
------------------------	--------------

Result	✓ Passed
---------------	----------

MOT #9	2011-11-30 09:29
---------------	------------------

MOT test number	848514231358
------------------------	--------------

Result	✓ Passed
---------------	----------

MOT #8	2010-11-15 12:13
---------------	------------------

MOT test number	370069510395
------------------------	--------------

Result	✓ Passed
---------------	----------

**MOT #7** 2009-11-19 13:06**MOT test number** 861863729323**Result** ✓ Passed**MOT #6** 2009-11-16 13:37**MOT test number** 220970129323**Result** ✗ Failed**Fail** Offside Front Tyre tread depth below requirements of 1.6mm (4.1.E.1)**Fail** Nearside Front Tyre tread depth below requirements of 1.6mm (4.1.E.1)**MOT #5** 2008-12-18 09:52**MOT test number** 651833158336**Result** ✓ Passed**Advice** Nearside Rear Upper Anti-roll bar linkage has slight play in a pin/bush (2.4.G.2)**Advice** Front brake disc slightly pitted (3.5.1h)**Advice** Offside Front Tyre worn close to the legal limit (4.1.E.1)**Advice** Nearside Front Tyre worn close to the legal limit (4.1.E.1)**MOT #4** 2007-12-28 09:57**MOT test number** 484782867374**Result** ✓ Passed**MOT #3** 2007-12-27 14:48**MOT test number** 493501367479**Result** ✗ Failed**Advice** Offside Front Tyre worn close to the legal limit (4.1.E.1)**Fail** Nearside Front Tyre tread depth below requirements of 1.6mm (4.1.E.1)



MOT #2	2007-02-24 12:29
MOT test number	362165557082
Result	✓ Passed
MOT #1	2006-02-25 09:52
MOT test number	710096256068
Result	✓ Passed



Damage history

Check the damage history for this HONDA. See if, where and when this HONDA had damage and the car repair costs. We also check if this HONDA was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	

Damage 2

Date	
Category	
Type	



Extra HONDA salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this HONDA in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,999
Auction value	£ 19,999
Average private trade value	£ 19,999

More info >



Owner history

For how long did the current and previous owner(s) have this HONDA? How many owners did this HONDA have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since

More info >

Plate changes

See in this check if this HONDA had different number plates.

Number of plates	1
Current registration	W448RRU
Plate since	2019-03-28
Current registration	W448RRU
Plate since	2019-03-28

More info >



Finance check

Check if this HONDA is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this HONDA has been settled.

If not, and you buy this HONDA then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this HONDA is financed.

Finance company	XXXXXXXXXX	XXXX
Date of agreement	XXXXXXXXXX	XXXX
Agreement type	XXXXXXXXXX	XXXX
Agreement term	XXXXXXXXXX	XXXX
Agreement number	XXXXXXXXXX	XXXX
Contact info	XXXXXXXXXX	XXXX

More info >



Mileage check

Odometer	In miles
Mileage registrations	22
First mileage registration	2000-03-24
Last registration	2021-07-15
Complete history	See info



Registration #1	2000-03-24	24 mi
Registration #2	2006-02-25	39.217 mi
Registration #3	2007-02-24	45.556 mi
Registration #4	2007-12-27	50.223 mi
Registration #5	2007-12-28	50.223 mi
Registration #6	2008-12-18	59.624 mi
Registration #7	2009-11-16	66.418 mi
Registration #8	2009-11-19	66.421 mi
Registration #9	2010-11-15	69.747 mi
Registration #10	2011-11-30	73.277 mi
Registration #11	2012-11-13	74.562 mi
Registration #12	2013-05-20	75.277 mi
Registration #13	2013-05-20	75.277 mi
Registration #14	2013-05-20	75.277 mi
Registration #15	2013-05-20	75.277 mi
Registration #16	2013-05-20	75.277 mi
Registration #17	2013-05-20	75.277 mi
Registration #18	2013-05-20	75.277 mi
Registration #19	2013-05-20	75.277 mi
Registration #20	2013-05-20	75.277 mi
Registration #21	2013-05-20	75.277 mi
Registration #22	2013-05-20	75.277 mi

More info >



Safety ratings

NCAP rating	★★★★☆
Video	see crash video



Dimensions & weight

Width	1705 mm
Height	1335 mm
Length	4400 mm
Kerb weight	1165 kg

Additional information

Fuel tank capacity	50 l
Fuel delivery	Multi-Point Injection
Number of doors	2
Engine number	B18C61200385