





report date: 2024-03-29

General information

Make	FIAT	
Model	500L MULTIJET LOUNGE DUALOGIC	
Colour	White	
Year of manufacture	2013	
Top speed	102 mph	
0 - 60 mph	15.1 seconds	
Gearbox	5 speed automatic	

Engine & fuel consumption

Power	85 BHP
Max. torque	200 Nm at 1.500 rpm
Engine capacity	1.248 cc
Cylinders	4
Fuel type	Diesel
Consumption city	62.8 mpg
Consumption extra urban	76.4 mpg
Consumption combined	70.6 mpg
CO2 emission	105 g/km
CO2 label	В



CarCheck.co.uk page 1/12



report date: 2024-03-29

Internet history

Entry 3

 Date
 2023-06-28

 Pictures
 0

Listing price <u>View report</u>

source: carcraft.co.uk

Entry 2

 Date
 2023-06-23

 Pictures
 4

Listing price <u>View report</u>









source: cargurus.co.uk

Entry 1

Date 2021-10-15

Pictures 18

Listing price <u>View report</u>









source: cargurus.co.uk

CarCheck.co.uk page 2/12



MOT history

AU63LWF

report date: 2024-03-29

,	
MOT expiry date	2024-06-25
MOT pass rate	75 %
MOT passed	9
Failed MOT tests	3
Total advice items	10
Total items failed	5
MOT #12	2023-06-26 12:38
MOT test number	808384469662
Result	✓ Passed
Next expiry date	2024-06-25
MOT #11	2022-10-31 13:23
MOT test number	809406200683
Result	✓ Passed

MOT #10	2021-11-03 16:24
MOT test number	605162221012
Result	✓ Passed

MOT #9		2021-02-02 14:43
MOT test r	number	263781823231
Result		√ Passed
Advice	Oil leak, but not excessive (8.4.1 (a) (i))	

CarCheck.co.uk page 3/12



AU63LWF
report date: 2024-03-29

MOT #8 2021-02-02 09:13

MOT test number 945534546775

Result X Failed

Advice Oil leak, but not excessive (8.4.1 (a) (i))

Fail Front Brakes imbalanced across an axle Axle 1 (1.2.1 (b) (i))

Advice Brake disc worn, pitted or scored, but not seriously weakened both front (1.1.14 (a) (ii))

Fail Service brake efficiency below requirements (1.2.2 (a) (i))

Advice Exhaust emits excessive smoke or vapour but not likely to obscure the vision of other road users (8.2.2.2 (c))

MOT #7 2020-02-01 15:31

MOT test number 121075075903

Result ✓ Passed

MOT #6 2019-02-06 13:19

MOT test number 836965473906

Result Passed

Advice Nearside Rear reversing lamp outer lens is broken

Advice O/sf & n/sf tyres are both worn on outer treads

MOT #5 2019-02-06 13:19

MOT test number 620956641179

Result X Failed

Advice O/sf & n/sf tyres are both worn on outer treads

Pass with rectification Nearside Reversing lamp inoperative (4.6.1 (a))

Advice Nearside Rear reversing lamp outer lens is broken

CarCheck.co.uk page 4/12



report date: 2024-03-29

MOT #4 2018-02-05 16:51

MOT test number 102727508736

MOT #3 2018-02-05 14:44

MOT test number 130914356316

Result × Failed

Fail Nearside Windscreen wiper does not clear the windscreen effectively (8.2.2)

Fail Offside Windscreen wiper does not clear the windscreen effectively (8.2.2)

MOT #2 2017-02-07 09:40

MOT test number 587444665559

Result \rightarrow Passed

MOT #1 2016-04-20 13:19

MOT test number 482081300677

Advice Nearside Front Tyre worn close to the legal limit (4.1.E.1)

Advice Offside Front Tyre worn close to the legal limit (4.1.E.1)

CarCheck.co.uk page 5/12



report date: 2024-03-29

Tax & MOT check



Tax status	Valid until 1 June
Days left	32
MOT expiry date	25 June 2024
Full MOT history	See MOT history

Tax calculation

Vehicle class	49
Band	В
Single payment (12 months)	£ 20,00,-
Single six month payment	Not applicable
Total payable by 12 monthly instalments	£ 21,00,-

CarCheck.co.uk page 6/12



report date: 2024-03-29

Damage history

Check the damage history for this FIAT. See if, where and when this FIAT had damage and the car repair costs. We also check if this FIAT was scrapped. Download the premium report <u>here</u> for the results.

Damage 1
Date
Category
Type
Damage 2
Date
Category
Type



Extra FIAT salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report <u>here</u> for more information.

More info >

CarCheck.co.uk page 7/12



report date: 2024-03-29

Vehicle valuation

What is this car worth? See the vehicle value of this FIAT in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value

Auction value

Average private trade value

More info >

CarCheck.co.uk page 8/12



report date: 2024-03-29

\sim	
Owner	nictory
CVVIICI	IIISLUIV
~	,

For how long did the current and previous owner(s) have this FIAT? How many owners did	d this FIAT have?
Check it in the premium report and see all owner registrations. Download the full report	
manage of the same	

	M 1. 6
	More info >
Plate changes	
See in this check if this FIAT had different number plates.	
Number of plates	
	NIE.
Cornect registration	NK MK
Plate since	
Current registration	NE SIE
Flate since	
	More info >
	More IIII0 >

CarCheck.co.uk page 9/12



report date: 2024-03-29

Finance check

Check if this FIAT is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this FIAT has been settled.

If not, and you buy this FIAT then you could lose the money and the car you paid for.

Download the premium report <u>here</u> and check if this FIAT is financed.

Finance company	
Date of agreement	
Agreement type	
Agreement term	
Agreement number	
Control info	

Contact info

More info >

CarCheck.co.uk page 10/12



report date: 2024-03-29

Mileage check

Registration #16

Odometer	In miles
Mileage registrations	16
First mileage registration	2013-11-13
Last registration	2023-06-26
Complete history	See info



Registration #1	2013-11-13	29 mi
Registration #2	2016-04-20	27.930 mi
Registration #3	2017-02-07	33.163 mi
Registration #4	2018-02-05	40.219 mi
Registration #5	2018-02-05	40.219 mi
Registration #6	2019-02-06	48.089 mi
Registration #7	2019-02-06	48.089 mi
Registration #8	2020-02-01	55.638 mi
Registration #9		11.777 es
Registration #10		11.777 es
Registration #11		11.777 es
Registration #12		11.777 es
Registration #13		11.777 es
Registration #14		D.777 es
Registration #15		11.777 es

7070.70.70

More info >

77.777 86

CarCheck.co.uk page 11/12



report date: 2024-03-29

Car features

50225	Air conditioning
50295	
60482	
0501	
0566	
60567	
60569	

Safety ratings

NCAP rating	****
Adult	94%
Children	78%
Pedestrian	65%
Safety systems	71%
Overall rating	83%
Video	see crash video



Dimensions & weight

Width	2018 mm
Height	1667 mm
Length	4147 mm
Wheel base	2612 mm
Kerb weight	1320 kg
Max. allowed weight	1880 kg

Additional information

Fuel tank capacity	50 I	
Fuel delivery	Direct Injection	
Number of doors	5	
Number of seats CarCheck.co.uk	5 pa	ge 12/12

Number of axles 2

Engine number 4939266